Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103 May 27, 2004
<u>District I</u> 1625 N French Dr., Hobbs, NM 88240 District II			WELL API NO.
<u>District II</u> 1301 W Grand Ave , Artesia, NM 88210 District III			30-025-38001 5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM 87505			6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		7. Lease Name or Unit Agreement Name VACUUM GRAYBURG SANANDRES UNIT	
1. Type of Well: Oil Well Gas Well Other Taip		8. Well Number 250	
2. Name of Operator		9. OGRID Number 4323	
CHEVRON U.S.A. INC. 3. Address of Operator			10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, T	EXAS 79705		VACUUM GRAYBURG SAN ANDRES
4. Well Location			
Unit Letter H: 1443 feet from the NORTH line and 1286 feet from the EAST lineSection 1Township 18-SRange34-ENMPMCounty LEA			
3ection 1 rownship 10-3 Raige 34-E NiviFM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3986' GL			
Pit or Below-grade Tank Application 🗋 or Closure			
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:SUBPERFORM REMEDIAL WORKPLUG AND ABANDONREMEDIAL WORTEMPORARILY ABANDONCHANGE PLANSCOMMENCE DRPULL OR ALTER CASINGMULTIPLE COMPLCASING/CEMEN			
OTHER INTENT TO ADD PERFS		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
CHEVRON U.S.A. INC. INTENDS TO ADD PERFS & ACIDIZE.			
THE INTENDED PROCEDURE IS ATTACHED FOR YOUR APPROVAL.			
			HOBBS OCD
WFX-823			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines \Box , a general permit \Box or an (attached) alternative OCD-approved plan \Box .			
SIGNATURE Alemie Penker ton TITLE Regulatory Specialist DATE 04-07-2008			
Type or print name Denise Pinkerton E-mail address: <u>leakejd@chevron.com</u> Telephone No. 432-687-7375 For State Use Only			
ALL A A CONSTRUCT SUPERVISOR/GENERAL MANAGER			
APPROVED BY: Mus, Conditions of Approval (if any):	Atlean TITLE		DATE PR 2 9 2008

,

VGSAU 250

Vacuum (Grayburg San Andres) Field, Lea County NM API No. 30-025-38001

Procedure to: C/O Perforate and Stim T-Z

Production depart should be sure well has been flowed to battery for 2 weeks prior to rig up.

- 1 Kill well as necessary. MU RU PU & RU. Pressure test backside to 500#.
- 2 Pump 25 bbls 10# BW dn tbg take SI pressure and calculate kill weight fluid. Kill well as nec. ND WH. NU BOP. Unset pkr & POOH w/ tbg & pkr.
- 3 TIH w 6 1/8" MT bit, 6 3 1/2" DC on 2 7/8" WS. RU Rvs Unit and C/O fill to PBTD of 5079'. Circ clean with 10# BW. POOH w/ WS, DCs & bit.
- 4 Rig up wireline truck. Get on depth with Baker Atlas' Radial Bond Log dated 3/12/2007. Note: It does not appear that a short joint was ran. Also the CCL log on the bond log is very noisy. For casing collar depth correlation also refer to the Baker Atlas Temperature log dated 3/13/07. Perforate w/ 3-1/8" slick guns w/ 2 JSPF @ 120 degree phasing as follows: 4705-4711', 4715-4721, 4725-4746', 4752-4761', 4767-4780', 4791-4800', 4805-4813', 4817-4837', 4841-4869'.
- 5 TIH w/ 7" treating packer on 2-7/8" workstring and set at ~4650'.
- 6 MI RU Halliburton to acidize the Lower San Andres and TZ interval 4677' 4869' interval with 8,000 gallons 15% HCL in 4 equal stages Drop 1500# rock salt between stages mixed in GBW. Rate 5-6 BPM Max press 5000 psi. Flush to bottom perf w/ 10 BW. Flowback to tank to recover load.
- 7 Kill well as nec. Rise Pkr & POOH with WS and PKR.
- 8 TIH w/ notched collar and circ out rock salt to PBD of 5079'. TOH w/ WS and Notched collar. If any trouble was encountereed while C/O in step 4 above RIH w/ bit to C/O.
- 9 TIH w/ Injection tbg & pkr w/ On-Off tool. Set Pkr @ ~ 4280 w/ 10 pt compression. Space out. Rise from On-Off tool circ hole with 10 ppg pkr fluid. Latch back onto On-Off tool. ND BOP. NU WH. Run MIT test for OCD.
- 10 Hookup injection lines. Clean location. RDMO PU & RU.
- 11 Turn well over to operations. Maximum premitted water injection pressure is 1730 psi.
- 12 Run injection profile when rate stabilizes.

LGB 3/27/08 PTB (revised)_3/31/08

VGSAU #250 Wellbore Diagram



TD: 5200'

