

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water"

23-May-08

OXY USA WTP LIMITED PARTNERSHIP

PO Box 4294

Houston TX 77210-4294

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

MYERS LANGLIE MATTIX UNIT No.158

30-025-10981-00-00

Active Oil (Producing)

L-2-24S-37E

Test Date:

5/15/2008

Permitted Injection PSI:

Actual PSI:

8/18/2008

Test Reason:

Annual IMIT

Test Result:

Repair Due:

Test Type:

Bradenhead Test

FAIL TYPE: Tubing

Comments on MIT:

FAIL CAUSE:

BHT FOR WATERFLOW CHECK: HOLE IN TUBING WELL IS SHUT IN;

MYERS LANGLIE MATTIX UNIT No.149

30-025-11000-00-00

Approved TA Oil (Producing)

H-4-24S-37E

Test Date: Test Reason: 5/15/2008

Permitted Injection PSI: Test Result:

Actual PSI: Repair Due:

8/18/2008

Test Type:

Annual IMIT Bradenhead Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT:

BHT FOR WATERFLOW CHECK: NEED TO BLEED OFF CASING; CIBP IN HOLE PER BUDDY

OKAY TUBING & CASING;*** 690 # ON CASING AND TUBING***

MYERS LANGLIE MATTIX UNIT No.128

30-025-26910-00-00

Expired TA Injection - (All Types)

C-4-24S-37E

Test Date: 5/19/2008 Permitted Injection PSI:

Actual PSI:

Test Reason:

incerely

Annual IMIT

Test Result:

Repair Due: 8/22/2008

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: WOULD NOT HOLD PRESSURE;

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas