State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

CONDITIONS OF APPROVAL AF ANY:

THE INTRIBUTE ON SERVATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 AY 1 220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-07521
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia North Artesia Nor	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 32 8. Well No. 231
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 231
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4 Well Location	
Unit Letter K : 2310 Feet From The South 2310 Fe	et From The West Line
Section 32 Township 18-S Range 38-	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3632' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	ateriai
12. Check Appropriate Box to Indicate Nature of Notice, Report, or	Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	SEQUENT NEFONT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING
	X ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	X ALTERING CASING PNS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	X ALTERING CASING PNS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well.	X ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. packer.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. Packer. RDPU 04/11/08
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. Packer. RDPU 04/11/08
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. packer. RDPU 04/11/08 that any pit or below-grade tank has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 Thereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. Packer. RDPU 04/11/08 That any pit or below-grade tank has been/will be the OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 1 hereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan. SIGNATURE	ALTERING CASING PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. Packer. RDPU 04/11/08 that any pit or below-grade tank has been/will be the OCD-approved Associate DATE 05/08/2008
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 1 hereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A. Johnson F-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. PART JOB starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Hot oil tubing & casing. 2. NU BOP/ND wellhead. 3. POOH w/rods & tubing. 4. RIH w/bit. Tag @3947'. Clean out. 5. Pickle tubing using 5 bbl of aicd @ 19 bbl of 2% KCL. POOH w/bit. 6. RIH w/packer set @3796'. Pump 1500 gal of 15% acid & 23 bbl 2% KCL down tbg. POOH w/ 7. RIH w/Arrowset 1-X packer set on 121 jts of 2-3/8" tubing. Packer set @3821'. 8. Test packer to 500 PSI. OK. 9. ND BOP/NU wellhead. 10. Swab well. 11. RDPU & RU. Clean location. RUPU 04/04/08 1 hereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan. SIGNATURE	ALTERING CASING PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion. PART JOB starting any completion or recompletion. PART JOB ALTERING CASING PLUG & ABANDONMENT THAT ABANDONMENT DATE O5/08/2008 TELEPHONE NO 806-592-6280