## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE CONSERVATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	WELL API NO 30-025-28346
DISTRICT II 1301 W Grand Ave, Artesia, NM 88210 MAY n g 2008	5 Indicate Type of Lease  STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 4
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 143
2. Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location  Unit Letter P: 1160 Feet From The South 330 Fee	t From The East Line
Section 4 Township 19-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3610' GL	
Discours Classes Control of the Cont	
Pit or Below-grade Tank Application or Closure  Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	teria:
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Control NOTICE OF INTENTION TO:	Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
FERFORM KEMEDIAL WORK     1 COO MAD NOW ADOLE	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUDITY OF THE CASING Multiple Completion CASING TEST AND CEMENT OTHER: CASING TEST AND CEMENT OTHER: Return to produce the completed Operations (Clearly state all pertinent details, and give pertinent dates	NS. PLUG & ABANDONMENT  IT JOB  action X  , including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF CASING TEST AND CEMENT OTHER: CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return to produce the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. ND wellhead/NU BOP.	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return to produce of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @4075.	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.  The starting any completion or recompletion.  The starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: CASING TEST AND CEMENOTHER: Return to product of the proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. Hes accordance in the product of the proposed of th	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.  The starting any completion or recompletion.  The starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.	PLUG & ABANDONMENT  IT JOB  Inction  X  Including estimated date of starting any completion or recompletion.  5' and down to 4324'. RD power swivel &
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: CASING TEST AND CEMENOTHER: Return to product of the proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.  The starting any completion or recompletion.  The starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.	PLUG & ABANDONMENT  IT JOB  Including estimated date of starting any completion or recompletion.  S' and down to 4324'. RD power swivel & RD HES. POOH w/PPI packer
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.	PLUG & ABANDONMENT  T JOB  Inction  X  Including estimated date of starting any completion or recompletion.  The starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PSP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.  RUPU 04/08/08 RD  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	PLUG & ABANDONMENT  IT JOB  Inction  It is including estimated date of starting any completion or recompletion.  S' and down to 4324'. RD power swivel & RD HES. POOH w/PPI packer  PU 04/15/08  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to product on the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed on the RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.  RUPU 04/08/08 RD	PLUG & ABANDONMENT  IT JOB  Inction  It is including estimated date of starting any completion or recompletion.  S' and down to 4324'. RD power swivel & RD HES. POOH w/PPI packer  PU 04/15/08  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return to productions:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.  RUPU 04/08/08 RD  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	PLUG & ABANDONMENT  IT JOB  Inction  X  It including estimated date of starting any completion or recompletion.  So and down to 4324'. RD power swivel & RD HES. POOH w/PPI packer  PU 04/15/08  That any pit or below-grade tank has been/will be the OCD-approved
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return to product of the proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. If the RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.  RUPU 04/08/08 RD  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	PLUG & ABANDONMENT  To Job  Inction  In
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return to product on the proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed or RUPU & RU. ND wellhead/NU BOP.  2. RIH w/bit & drill collars. Tag @4075'. RU power swivel & stripperhead. Drill thru CIBP @407 stripperhead. POOH w/bit & drill collars.  3. RU Gray slickline & get static bottom hole pressure reading @4324 & 4200'. RD Gray.  4. RU wireline & perforate casing @4122-26', 4231-38' @4 JSPF. RD wireline.  5. RIH w/PPI packer set @4260'. RU HES & perform PPI acid job w/5200 gal of 15% PAD acid. He of the production of the production.  6. RIH w/ESP equipment on 126 jts of 2-7/8" tubing. Intake set @4046'  7. ND BOP/NU wellhead.  8. RDPU & RU. Clean location and return well to production.  RUPU 04/08/08 RD  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines according to NMOCD guidelines or an (attached) alternative plan plan  SIGNATURE TITLE Administrative TITLE Administrative mendy johnson@oxy.com  For State Use Only	PLUG & ABANDONMENT  IT JOB  Inction  X  Including estimated date of starting any completion or recompletion.  5' and down to 4324'. RD power swivel &  RD HES. POOH w/PPI packer  PU 04/15/08  that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 05/08/2008  TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return to product on the proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed on the proposed of the pro	PLUG & ABANDONMENT  IT JOB  Inction  X  Including estimated date of starting any completion or recompletion.  5' and down to 4324'. RD power swivel &  RD HES. POOH w/PPI packer  PU 04/15/08  that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 05/08/2008  TELEPHONE NO. 806-592-6280