

APPROVED BY

CONDITIONS OF APPROVAL IF ANY.

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

JUN 1 1 2008 OIL CONSERVATION DIVISION FILE IN TRIPLICATE DISTRICT I WELL API NO. 1220 South St. Francis Dr. 1625 N French Dr., Ho 30-025-28353 Santa Fe, NM 87505 **DISTRICT II** 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE X 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A South Hobbs (G/SA) Unit / DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 10 8. Well No. 1. Type of Well: 150 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location Unit Letter 330 Feet From The North 1220 Feet From The Section 10 19-S Range **NMPM** County 38-E 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3621' KB Pit or Below-grade Tank Application or Closure Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness Below-Grade Tank: Volume __ bbls; Construction Material 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB OTHER: OTHER: Convert to ESP from Beam 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. Kill well. 2 Remove pumping unit. Unseat pump and POOH w/rods & pump. 3. ND wellhead/NU BOP. 4. Scanalog tubing out of hole. 5. RIH w/bit & drill collars. Tag @4242'. RU power swivel & stripper head. Drill through CIBP @4242'. Push down to 4295'. Drill up remainder of CIBP. Drill on cement from 4295-4332'. Circulate hole clean. RD power swivel & stripper head. POOH w/bit & drill collars. 6. RU HES & log well from PBTD @4335' to 3270'. 7. RU wireline & perforate casing @4151-54', 4168-75', 4200-08', 4211-14', 4246-50', 4258-61', 4263-66', 4269-78', 4280-90' @4 JSPF. RD wireline. 8. RIH w/PPI packer set @4050'. RU HES & acid treat well w/3000 gal of 15% NEFE HCL acid. RD HES. ***see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 06/10/2008 TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy johnson@oxy.com TELEPHONE NO 806-592-6280 For State Use Only PETROLEUM ENGINEER

SHU 150

- 9. Perform chemical squeeze.
- 10. POOH w/PPI packer.
- 11. Run back in hole w/ESP equipment on 129 jts of 2-7/8" tubing. Intake set @4072'.
- 12. RDPU & RU. Clean location.
- 13. Return well to production.