the second s		
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103	
Office District 1 1625 N. French Dr., Hobbs, NM 8240	May 27, 2004 WELL API NO.	
DISTRICT OIL CONSERVATION DIVISION	30-025-33377	
1301 W Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 1 9 2004 220 South St. Francis Dr. Santa Fe, NM 87505	5. Indicate Type of Lease STATE X FEE	
District IV 1220 S St. Francis Dr., Sarta Fe, NM 8/410 Santa Fe, NM 8/505	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: Teague 2 State	
PROPOSALS.) 1. Type of Well:	8. Well Number	
Oil Well X Gas Well Other	3 /	
2. Name of Operator	9. OGRID Number 005380	
XTO Energy, Inc.	10. Pool name or Wildcat	
200 N. Loraine, Ste. 800 Midland, TX 79701	Teague: Paddock, Blinebry	
4. Well Location		
Unit Letter <u>E: 1650</u> feet from the <u>North</u> line and	330 feet from the West line	
Section 2 Township 24S Range 37E	NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
Pit or Below-grade Tank Application or Closure		
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction	Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF:	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat:	SEQUENT REPORT OF:	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.	SEQUENT REPORT OF: ALTERING CASING AND NG OPNS. PLUG AND ABANDONMENT ion X e pertinent dates, including estimated date	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING AND ABANDONMENT NG OPNS. PLUG AND ABANDONMENT ion X ion X e pertinent dates, including estimated date a wellbore diagram of proposed completion wellbore diagram of proposed completion wellbore diagram of proposed completion	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. 5/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment. See Attached	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING AND ABANDONMENT NG OPNS. ALTERING CASING ADD ADD ADD AND ADD AND ADD AND ADD ADD	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. 5/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment.	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT ion X e pertinent dates, including estimated date a wellbore diagram of proposed completion vtr. Circ 80 bbls of 2% KCL wtr to at tool. Tbg free fr 5336' to Monk Scanalog trk. Scan out of hole	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. 5/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment. See Attached I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT ion X e pertinent dates, including estimated date a wellbore diagram of proposed completion vtr. Circ 80 bbls of 2% KCL wtr to at tool. Tbg free fr 5336' to Monk Scanalog trk. Scan out of hole	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OTHER: Stimulat: 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. S/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment. See Attached Intereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE WW HUK TITLE	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT ion I ion I e pertinent dates, including estimated date a wellbore diagram of proposed completion vtr. Circ 80 bbls of 2% KCL wtr to nt tool. Tbg free fr 5336' to Monk Scanalog trk. Scan out of hole	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OTHER: Stimulat: 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. S/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment. See Attached Title Requilator I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE MAY TITLE Requilator Type or print name Sherry Pack Sher State Liea Only Sher	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING AND ABANDONMENT NG OPNS. PLUG AND ABANDONMENT ion X e pertinent dates, including estimated date a wellbore diagram of proposed completion Atr. Circ 80 bbls of 2% KCL wtr to at tool. Tbg free fr 5336' to Monk Scanalog trk. Scan out of hole e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan ry Analyst. DATE 6/18/2008 herry_pack@xtoenergy.com Telephone No. 432.620.6709	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: OTHER: Stimulat: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 4/30/08 MIRU PU. 5/1/08 POOH w/rods. NU BOP. Load TCA & brk circ w/74 bbls of 2% KCL w catch trk. Unable to work tbg free. 5/2/08 RU pump trk. Kill well w/35 BBW. RU Rotary WL. RIH w/Free poin surface. RIH w/ chem cutter & cut off tbg off. @ 5278'. RD WL. RU Bo w/ 167 jts of 2-7/8" J-55 tbg. RD scan equipment. See Attached I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE WY SIGNATURE TITLE Requilato E-mail address: St Type or print name Sherry Pack	SEQUENT REPORT OF: ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING AND ABANDONMENT NG OPNS. PLUG AND ABANDONMENT ion X e pertinent dates, including estimated date a wellbore diagram of proposed completion Atr. Circ 80 bbls of 2% KCL wtr to at tool. Tbg free fr 5336' to Monk Scanalog trk. Scan out of hole e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan ry Analyst. DATE 6/18/2008 herry_pack@xtoenergy.com Telephone No. 432.620.6709	

ENERGY NVAU #Teague 2 State API 30-025-33377 Form C-103 cont'd

- 5/5/08 SICP "0". PU & RIH w/4-11/16" overshot w/2-7/8" grapple, 3-3/4" bumper sub, 3-3/4" jars, 6 - 3-1/2" DC on 2-7/8" L-80 tbg. Tag fish @ 5,278'. Work over & latch onto fish. POOH w/2-7/8" L-80 tbg & LD fish. PU & RIH w/4-3/4" bit on 2-7/8" L-80 tbg. Tag @ 5,381'. POOH w/6 jts of 2-7/8" L-80 tbg. SWI & SDON
- 5/6/08 POOH w/2-7/8" N-80 tbg. LD bit. PU & RIH w/sonic hammer tool on 2-7/8" N-80 tbg. RU CUDD Acidizing equip. Wash Blinebry perfs fr 5,271' - 5,354' w/192 BBW. Acidize Blinebry perfs fr 5,354' - 5,271' w/5000 gals of 20% 90/10 acid. Flushed w/35 bbls of 2% KCL wtr. Ave rate 4.4 BPM, Ave press 1,300 psig. ISIP 661 psig, 5" 502 psig, 10" 429 psig, 15" 342 psig. RD CUDD equipment. SWI for 1 hr. Open well up Vac. RU swab. BFL 700' FS. Made 12 runs in 3 hrs & Rec 60 bbls of wtr & 0 oil. EFL 1,800' FS. RD swab. BLWTR 344. SWI & SDON
- 5/7/08 RU swab. BFL 1,400' FS. Made 37 runs in 10 hrs & Rec 164 bbls of wtr & 0 oil. EFL 3,600' FS. RD swab. BLWTR 180. SWI & SDON
- 5/8/08 RU swab. BFL 1,400' FS. Made 3 runs & Rec 15 bbls of wtr & 0 oil. EFL 2,000' FS. RD swab. POOH w/2-7/8" N-80 tbg & LD sonic hammer tool. PU & RIH w/BJ 5-1/2" treating pkr on 2-7/8" N-80 tbg. Set pkr @ 5,207'. SWI & SDON
- 5/9/08 SITP-"Vac" SICP -"0". RU Petroplex Acidizing equipment & monitor TCA. Acidize Blinebry perfs fr 5,271' - 5,354' w/2,700 gals of 15% acid mix w/240 gals of xylene & 60 gals of Petro A while dropping 157 1.3 BS. Flushed w/35 bbls of 2% KCL wtr. ISIP 415 psig, 5" 232 psig, 10" 94 psig, 15" 48 psig. RD acidizing equipment. Ave rate 5.0 BPM, Ave press 1,100 psig, min/max press - 400/1,250 psig. SWI & SDON.
- 5/12/08 SITP "Vac" SICP "0". Rel pkr. POOH LD 2-7/8" N-80 tbg & pkr. RU Bo Monk test trk. PU & RIH w/2-7/8" slotted MA & test 170 jts of 2-7/8" 6.5#, J-55, EUE, 8rd tbg below slips to 5000 psig. RD test trk. ND BOP. Set 5-1/2" TAC w/18 pts tens. NU WH. SWI & SDON.



- 5/13/08 SITP "0" SICP "0". PU & RIH w/pmp & rods as followed. 1-1/4" x 8' GA, 2.5 - 1.5 - RXBC - 24' - 3' pmp, 1 - 7/8" stabilizer sub, 6 - 1-1/2" K-Bars, 138 -3/4" D-96 rods, 68 - 7/8" EL rods & 1-1/4" x 26' PR w/1-1/2" x 16' liner. SWO & HWO. RU pmp trk. Load tbg w/15 bbls of 2% KCL wtr. Pump up to 500 psig in 4 strks. RD pmp trk. RDMO PU. RWTP
- 5/22/08 In 24 hrs, well made 0 BO, 220 BW & 2 MCF running @ 100% on POC w/2,762 FAP.



• ...

.

-