## Form C-103 Revised 5-27-2004

## State of New Mexico State of New Mexico A part of the state of New Mexico State of New Mex

FILE IN TRIPLICATE

DISTRICT   1220 South St. Francis Dr. 1625 N French Dr., Hobbs, NM 88240   111 2 2 2002   South St. Francis Dr. South St. Francis Dr.	WELL API NO 30-025-07525
DISTRICT II  1625 N. French Dr., Hobbs, NM 88240  JIII 2 8 2003  Santa Fe, NM 87505	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 821 CDCC	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 32
1 Type of Well.	8. Well No. 211
Oil Well X Gas Well Other  2. Name of Operator	9 OGRID No. 157984
Occidental Permian Ltd.	9 OGRID No. 13/984
3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR I Box 90 Denver City, TX 79323	
4 Well Location  Unit Letter P: 990 Feet From The North 2310 Feet From The West Line	
1 770	
Section 32 Township 18-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3638' DF	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
I I	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	ALTERING CASING
	ALTERING CASING  NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORT OF THE PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING  NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORT OF THE PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING  NS. PLUG & ABANDONMENT  T JOB  Acid treat  X
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUDE OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: OTHER: OTHER: OTHER: OAPPORTUDE OF THE OAPPORTUDE OAPPO	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF THE CASING Multiple Completion CASING TEST AND CEMENT OTHER: OTH	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: O	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF CASING TEST AND CEMENT OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP.  2. POOH w/ESP equipment.  3. RIH w/bit. Tag @4241'. POOH w/bit.  4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline.	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORTUGE OF CASING TEST AND CEMENT OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP.  2. POOH w/ESP equipment.  3. RIH w/bit. Tag @4241'. POOH w/bit.  4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline.  5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit.	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP.  2. POOH w/ESP equipment.  3. RIH w/bit. Tag @4241'. POOH w/bit.  4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline.  5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit.  6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline.  7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'.	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'.  9. ND BOP/NU well head.	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP.  2. POOH w/ESP equipment.  3. RIH w/bit. Tag @4241'. POOH w/bit.  4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline.  5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit.  6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline.  7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'.	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  /Acid treat  x  including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08	ALTERING CASING PLUG & ABANDONMENT T JOB Acid treat A including estimated date of starting any completion or recompletion.  It block. Flush w/50 bbl of fresh water. RD HES.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPORT OF THE CASING Multiple Completion CASING TEST AND CEMENT OTHER: OAP OTHER:	ALTERING CASING PLUG & ABANDONMENT T JOB Acid treat A including estimated date of starting any completion or recompletion.  It block. Flush w/50 bbl of fresh water. RD HES.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OAP  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed Number 1. RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PPI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sall. 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT T JOB  Acid treat
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTH	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  Acid treat  X  Including estimated date of starting any completion or recompletion.  It block. Flush w/50 bbl of fresh water. RD HES.  RDPU 05/22/08  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative.	ALTERING CASING  PLUG & ABANDONMENT  IT JOB  Acid treat  X  Including estimated date of starting any completion or recompletion.  It block. Flush w/50 bbl of fresh water. RD HES.  RDPU 05/22/08  that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal & Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative mendy johnson@oxy.com	ALTERING CASING  PLUG & ABANDONMENT  T JOB  Acid treat  X  Acid treat  X  Acid treat  X  Acid treat  Acid treat  X  ABANDONMENT  X  X  ACID TREACH TO THE STAND TO THE ST
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal & Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative mendy johnson@oxy.com	ALTERING CASING  PLUG & ABANDONMENT  T JOB  Acid treat  X  Acid treat  X  Acid treat  X  Acid treat  Acid treat  X  ABANDONMENT  X  X  ACID TREACH TO THE STAND TO THE ST
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: OAP.  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the RUPU & RU. Perforate tubing @3690'. ND wellhead/NU BOP. 2. POOH w/ESP equipment. 3. RIH w/bit. Tag @4241'. POOH w/bit. 4. RU wireline and run CNL/CCL/GR from PBTD to 3300'. RD wireline. 5. RIH w/bit. Tag @4191'. Pump 5 bbl of 15% NEFE acid & 22 bbl of 10# brine. POOH w/bit. 6. RU wireline and perforate hole @4052-54', 4060-68', 4072-74'. RD wireline. 7. RIH w/PI packer set @4017'. RU HES & acid treat well w/2200 gal of acid and 750# of rock sal 8. Run back in hole w/ESP equipment on 116 jts of 2-7/8" tubing. Intake set @3723'. 9. ND BOP/NU well head. 10. RDPU & RU. Clean location and return well to production.  RUPU 05/16/08  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify to constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE  TITLE Administrative  TYPE OR PRINT NAME Mendy(A) Johnson E-mail address: mendy_johnson@oxy.com	ALTERING CASING  PLUG & ABANDONMENT  T JOB  Acid treat  X  Acid treat  Acid treat  X  Acid treat  Acid treat  X  ABANDONMENT  X  ABANDONMENT  Acid treat  Acid tre