Submit 3 Copies to Approciate District	State of New Mexico Energy, Minerals and Natural	Resouces		FORM C-103 Revised March 25, 1999	
Office <u>DISTRICT1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>DISTRICT11</u> 811 South First, Artesia, NM 88210 <u>DISTRICT111</u> 1000 Rio Brazos Rd., Aztec, NM 87410 <u>DISTRICT1V</u> 1220 South St. Francis Dr., Santa Fe, NM 87505 <u>SUNDRY NG</u> (DO NOT USE THIS FORM FOR PROC DIFFERENT RESERVOIR. USE "APPE	OIL CONSERVATION DI 1220 South St. Francis I Santa Fe, NM 8750 OTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLU FLICATION FOR PERMIT" (PORM C-101) FOR	Drive 5 G BACK TO A	VELL API NO. 30-025-03818 5. Indicate Type of Lease STA 6. State Oil & Gas Lease No. 7. Lease Name of Unit Agreem		
PROPOSALS.) 1. Type of Well: 2. Name of Operator	GAS WELL OTHER		8. Well No. 9. Pool name or Wildcai	10	
4. Well Location Unit Letter H : Section 1 7 11. NOTICE OF II	Houston, Texas 77056-4400 1650 Feet From The North Township 17S Range 36 10. Elevation (Show whether DF, RKB, RI Check Appropriate Box to NTENTION TO: Image Image Image North Linex Plug and Abandon	F, GR, etc.)	e, Report, or Other Data IBSEQUENT REPOR	RT OF:	
Perform Remedial Work Temporarily Abandon Pull or Alter Casing Other	Change Plans	Commence Drilling Operations		Plug and Abandonment	
	(Clearly state all perfine	nt details, and give p	ertinent dates, includi	ing estimated date	

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PLUGGING PROCEDURE & WELLBORE DIAGRAM ATTACHED.

.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the inform	nation above is true and co	mplete to the best of my know	ledge and belief.	TITLE	Engineering Technician	DATE	10/21/2003
TYPE OR PRINT NAME	Kaye Alley		A		TELEPH	ONE NO.	(918) 491-4816
(This space for State Use) APPROVED BY CONDITIONS OF APPROVA	Hary I	J. Win	TOC FIEL	D REPR	ESENTATIVE II/STAFF MANAC	ER N	<u> 0 3 2003</u>

SERVICES MICLAND TX

Apache Corporation

Proposed Plugging Procedure

State LA #11 Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI producer. Nothing in hole

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- 1. Dig & line 250 bbl working pit, test anchors as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP. RIH w/ tubing to CIBP @ 4,310'. Load hole w/ mud, pump 35 sx C cmt on top of CIBP.
- 3. POOH w/ tbg.
- 4. RIH w/ wireline and cut 5½" casing @ 3,300', POOH w/ wireline. RU casing tools and POOH w/ 5½" casing.
- 5. RIH w/ tubing +/- 3,400' (50' inside casing stub). Load hole w/ mud and pump and pump 50 sx C cmt w/ 2% CaCl₂. WOC and tag this plug. casing stub plug
- 6. POOH w/ tbg to 3,000'. Load hole w/ mud and pump 35 sx C cmt @ 3,050'. Base of salt plug
- 7. POOH w/ tbg to 2,017'. Load hole w/ mud and pump 35 sx C cmt @ 2,017'. Top of salt plug
- 8. ND wellhead and stretch 8-5/8" casing. If casing is free, cut 8-5/8" casing @ +/- 350' (if casing free below 1,000', cut at freepoint and pump/tag 60 sx stub plug), POOH w/ wireline. RU casing tools and POOH w/ 8-5/8" casing.
- 9. RIH w/ tubing +/- 350' (50' inside casing stub and 50' below 13-3/8" shoe). Load hole w/ mud and pump and pump 115 sx C cmt w/ 2% CaCl₂. WOC and tag this plug. casing stub & surface casing shoe plug
- 10. ND BOP and NU wellhead. RIH w/ tbg to 60' and pump 20 sx C cmt 60' to surface. surface plug
- 11. SI well. RDMO. Empty pit.
- 12. Cut off wellhead and anchors, level location. Leave location clean and free of trash.

State LA #11 procedure.doc

State LA #11 - Proposed Wellbore Diagram

API # - 30 025 03819

1650' FNL, 1980' FEL, Sec 1, T17S, R 36E, Lea County, New Mexico DF @ 3840'


