Submit 3 Copies To Appropriate District	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, winerals and Natural Resources	WELL API NO. 30-025-20883
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE SFEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. B-1839-1
SUNDRY NOT	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit Tract 26
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well	8. Well Number 1
2. Name of Operator	illips Company ATTN: Celeste Dale	9. OGRID Number 217817
3. Address of Operator	A" Street, Bldg. 6 #247, Midland, TX 79705-5406	10. Pool name or Wildcat Vacuum Glorieta
4. Well Location Unit LetterD:	990_feet from theNorth line and330_	feet from theWestline
Section 27	Township 17-S Range 35-E	NMPM County Lea
	11. Elevation (Show whether DR, RKB, RT, GR, etc 3,935' GL; 3,947' RKB	
Pit or Below-grade Tank Application a complexity of the strength of the streng		stance from nearest surface water N/A
		Construction MaterialSTEEL
12. Check	Appropriate Box to Indicate Nature of Notice	, Report or Other Data
		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON A REMEDIAL WOR CHANGE PLANS COMMENCE DR	RK
PULL OR ALTER CASING		
OTHER:	OTHER:	
 Describe proposed or comp of starting any proposed we or recompletion. 	oleted operations. (Clearly state all pertinent details, and ork). SEE RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion

SEE ATTACHED PROPOSED PLUGGING PROCEDURE, CURRENT & PROPOSED PLUGGED WELLBORE DIAGRAMS.

The Oil Conservation Division Must be notified 24 hours prior to the beginning of plugging operations	AUG 1 8 2003 HOBBS OCD
I hereby certify that the information above is true and	complete to the best of my knowledge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed according to r	NMOCD guidelines 🛛, a general permit 🗋 or an (attached) alternative OCD-approved plan 🗌.
SIGNATURE The Head	TITLE Area Manager, P&A Operations (Baisic Energy Services) DATE 08/15/08
Type or print name: James F. Newman P.E. E-mail a	address: James.Newman@BasicEnergyServices.com Telephone No. 432-687-1994
For State Use Only	OC DESTRECT SUFERVISOR/GENERAL MANAGEAUG 792008
APPROVED BY: Mur (// tillens	DATE

APPROVED BY: <u>Mus () Xillens</u> Conditions of Approval (if any):

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date July 2, 2008 RKB @ <u>3947'</u> DF @ <u>3946'</u> Subarea Buckeye GL @ 3935' Vacuum Glorieta East Unit, Tract 26 Well No 1 Lease & Well No 990' FNL & 330' FWL, Sec 27, T-17-S, R-35-E, UL "D" Legal Description New Mexico State 12-1/4" Hole County Lea Vacuum Glorieta Field 7/17/64 6/25/64 Rig Released Date Spudded 30-025-20883 API Number Status Temporarily Abandoned State O&G Lse No. B-1839-1 Drilled as State 5-27 No. 8 Stimulation History: Lbs. Max Max Gals Sand Press ISIP Rate Down <u>Interval</u> <u>Type</u> <u>Date</u> Perforate 6132'-6172', 1 JSPF (select fire) 7/21/64 2700 2200 1,000 6132-6172 7/23/64 Acid IPF 82 BO, 0 BW 2,000 6132-6172 12/17/70 15% NE HCI Perforate 4 squeeze holes @ 1700'; squeeze w/700 sacks 8/26/81 circulate 250 sacks cement to surface. 8-5/8" 32# & 24# @ 1627' Cmt'd w/ 1450 sx lead cmt, circ 1/25/94 Run MIT, held OK Set 4-1/2" CIBP @ 6086' 5/8/01 TOC @ Surface Casing Leak @ 1700' - Sqz'd w/700 sx Temporarily Abandon Top Salt @ ~ 1775' TOC 4-1/2" Csg @ 2780' (T.S.) Base of Salt @ Formation Tops: 1630' Rustler 4-1/2" CIBP @ 6086' Top Salt 1775' 2902' Yates <u>Glorieta</u> Seven Rivers 3065' 6132' - 6144' Base Salt == == 6148' - 6156' 3729' ---_--6168' - 6172' Queen Grayburg 4342' 7-7/8" Hole San Andres Glorieta 6001 4-1/2" 9 5# J-55 @ 6237' 6132 Paddock Cmt'd w/870 sx cement PBTD 6086' TOC @ 2780' (T S) ТD 6240'

F \Jim Data\Client Files\CONOCO\Wellbore Diagrams\Vacuum Field\VGEU 26-01 WBDs xls



ConocoPhillips Company Vacuum Glorieta East Unit 26-01 API #30-025-20883 Vacuum Glorieta Field Lea County, New Mexico

Proposed Plugging Procedure

See attached wellbore diagrams for wellbore configuration

Casings: 85%" 24 & 36# casing @ 1,627' cmt'd w/ 1,450 sx, circulated 41/2" 9.5# casing @ 6,237' cmt'd w/ 870 sx, TOC @ 2,780' by T.S. Perforationa: 6,132, 6,172', (Claricta)

Perforations: 6,132 –6,172' (Glorieta)

TA'd w/ CIBP @ 6,086' (set 05/08/01)

Tubulars: none

- Contact NM Digtess (1-800-321-2537) minimum 48 hrs prior to move-in
- Verify anchors tested within last two years
- Notify NMOCD & BLM 48 hrs prior to move in, and 4 hrs prior to plugs
- Document daily tailgate safety meetings w/ crews
- Observe ConocoPhillips 10 2 4 work break program

2%" tubing capacity = 0.00387 bbls/ft 4½" 9.50# casing capacity = 0.0162 bbls/ft = 10.960 ft/ft³ 8%" 24# casing capacity = 0.0636 bbls/ft = 2.797 ft/ft³

- 1. Set steel pit and flow down well as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 5,000# hydraulic BOP.

HAZARDS	EFFECT	SOLUTIONS
Rigging up Plugging Equipment	Injury to Personnel	 Check for overhead obstructions Observe Safety procedures while rigging up JSA
Lifting/Moving heavy equip.	Injury to Personnel	 Inspect and use rated chains/slings Proper hook/shackle placement
Static Electricity	Injury to Personnel and Equipment	Ground Rig to Well-Bore
H₂S	Injury to Personnel	 Monitoring equipment Safety Plan Emergency Contacts All on site H2S Trained

RIH w/ 2³/₆" workstring tubing, tag CIBP @ ~6,086'. RU cementer and displace hole w/ 100 bbls plugging mud (casing capacity 98 bbls). Pump 25 sx C cmt 6,086 – 5,725' (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 361' in 4¹/₂" 9.50# casing), displacing w/ 22 bbls mud. PUH laying down tubing to 4,342'.



HAZARDS	EFFECTS	SOLUTIONS
Running tubing	Injury to Personnel, Equipment & Well-Bore	 Proper pipe handling practices check Slips/Tongs/Elevators
Mixing Plugging Mud	Health Hazard	 Proper PPE Respiratory Protection
High pressure Pumping	Injury to Personnel and Environmental Issues	 Establish & Use Safe Area Inspect all hoses/connections

- **4.** Load hole w/ plugging mud and pump 25 sx C cmt 4,342 3,981' (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 361' in 4½' 9.50# casing) displacing w/ 15 bbls plugging mud. PUH laying down tubing to 2,900'. **San Andres plug**
- **5.** Load hole w/ plugging mud and pump 25 sx C cmt 2,900 2,539' (1.32 ft³/sk yield, 33.0 ft³ slurry volume, calculated fill 361' in 4½' 9.50# casing) displacing w/ 9.5 bbls plugging mud. POOH standing back 1,200' and laying down remainder. **Yates & Base of Salt plug**

HAZARDS	EFFECTS	SOLUTIONS
Laying down tubing	Injury to Personnel	 Proper pipe handling practices check Slips/Tongs/Elevators
Fall from Height	Injury to Personnel	 100% Tie-Off in derrick Platforms w/Rails even consider if less than 4'
Mixing Plugging Mud	Health Hazard	Proper PPE Respiratory Protection
High pressure Pumping	Injury to Personnel and Environmental Issues	 Establish & Use Safe Area Inspect all hoses/connections

6. RU & test lubricator to 1,500 psi. RIH w/ wireline & perforate 4½" casing @ 1,775'. POOH w/ wireline. RD lubricator.

HAZARDS	EFFECTS	SOLUTIONS
Fall lanes	Injury to Personnel	Rig-up outside of Anchors, 50' from well-bore
Static Electricity	Pre-Detonation of Explosives, Injury to Personnel and Equipment	Ground Wireline to well-bore
Explosive Guns	Injury to Personnel and Equipment	 Ensure there is no power source while assembling wire detonator to wireline first - then to charge

7. RIH w/ packer to ~1,200'. Load hole w/ plugging mud, set packer, and establish rate into perforations at 1,500 psi or less. Squeeze 50 sx C cmt w/ 2% CaCl₂ 1,775 – 1,527' (1.32 ft³/sk yield, 66.0 ft³ slurry volume, calculated fill 195' in 7%" open hole) displacing w/ 9.5 bbls (tubing volume = 4.6 bbls). WOC & tag this plug no lower than 1,527'. POOH w/ packer standing back 400' and laying down remainder. Top of Salt & Surface casing shoe plug

HAZARDS	EFFECTS	SOLUTIONS
Mixing CaCl2	Health Hazard Inhalation Chemical burn	 Refer to MSDS Proper PPE
High pressure Pumping	Injury to Personnel, Equipment and Environmental Issues	 Establish & Use Safe Area Inspect all hoses/connections

ND BOP and RIH w/ tubing to 400'. Circulate 30 sx C cmt 400' to surface (1.32 ft³/sk yield, 13.2 ft³ slurry volume, calculated fill 434' in 4½" 9.50# casing). *Freshwater & surface plug*



9. RDMO location.

HAZARDS	EFFECTS	SOLUTIONS
Lowering Derrick	Injury to Personnel & Equipment Pinch points	 JSA <u>Bleed air from raising cylinder</u>
Loose Equipment	Injury to Personnel and Vehicles	 Secure all loose equipment Vehicle Inspections prior to movement

10. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

HAZARDS	EFFECTS	SOLUTIONS
Explosive Atmospheres	Injury to personnel and Equipment Damage	 Digtess Excavation & Hot Work Permits Monitor Atmosphere
Cutting/Capping Wellhead	Injury to Personnel	 Secure wellhead on site helper watching area
Grass/Brush Fires	Injury to Personnel, Equipment & Land	 Clear area w/backhoe Fire watch Emergency Contacts

.

PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit



VGEU 26-01 WBDs xls