Submit 3 Copies To Appropriate District	State of]	New M	exico		Form	C_{-102}	
Office	Energy, Minerals and Natural Resources		Form C-103 Revised March 25, 1999				
District I 1625 N. French Dr., Hobbs, NM 88240	Lifergy, winicials	anu mati	Iral Resources	WELL API NO.		<u>1 25, 1999</u>	
District II				30-025-208			
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV	ATION	I DIVISION				
District III	1220 South	St. Fra	ncis Dr.	5. Indicate Type		,	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe	NM 8	7505		FEE [
1220 S. St. Francis Dr., Santa Fe, NM		,			Gas Lease No.		
87505				B-1423-2			
SUNDRY NOTICI	ES AND REPORTS ON	WELLS	5	7. Lease Name	or Unit Agreemen	t Name	
(DO NOT USE THIS FORM FOR PROPOSA	LS TO DRILL OR TO DEEP	PEN OR PL	UG BACK TO A			i i unito.	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			OR SUCH	Vacuum Glorieta East Unit			
PROPOSALS.) 1. Type of Well:				Tract #10			
	Other						
2. Name of Operator				9 Wall Ma			
ConocoPhillips Co.				8. Well No.			
3. Address of Operator	· · · · · · · · · · · · · · · · · · ·			#2	*****		
4001 Penbrook, Odessa, TX 79	7()			9. Pool name or			
4. Well Location	/02			Vacuum Glo	rieta		
4. Well Location					0		
Unit Letter G : 2,180	feet from the North	1	inc and 1 090	Contraction of the			
01111 Letter0 2,180		I	ine and1,980	feet from the	eEast	line	
Section 28	Township	17-S	Range 35-1			~ .	
	10. Elevation (Show w				M Lea (County	
	3,944 '	neiner D	n, NND, NI, ON, eic.				
11 Chook Am		liante N	Anna ANTA'				
	propriate Box to Inc	ncate N					
NOTICE OF INT		_		SEQUENT RE			
	PLUG AND ABANDON	\boxtimes	REMEDIAL WORK		ALTERING CAS	ING 🔲	
		-					
	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND		
PULL OR ALTER CASING	MULTIPLE		CASING TEST AN	~ —	ABANDONMEN	Т	
	COMPLETION		CEMENT JOB	D 🗌			
			OEMENT SOD			• •	
OTHER:			OTHER:			П	
12. Describe proposed or completed of	perations (Clearly stat	e all nerti	inent details and giv	a nartinant datas	including actimate		
starting any proposed work). SEE	RULE 1103 For Mult	inle Com	nletions. Attach wel	llhore diagram of i	nronosed complete		
recompilation.			protions. Attuon we		proposed completi		
-							
See attached procedure & we	ilbore diagrams.			0112	12.		
• • • • • • • • • • • • • • • • • • • •				9101112	13 14 15		
				50189101112 50189101112	13 10 15 10 11 18 19 2		
				49			
				12 MUN 50	10 00		
				N NUT	ieu 8		

and the second of

•

W

See attached procedure & well	bore diagrams.	50189101 59	12737475761718
HC PLI TC	E COMMISSION MUST BE NOTIFIE DURS PRIOR TO THE BEGINNING UGGING OPERATIONS FOR THE C D BE APPROVED.		1273747576 W2003 Hobbs OCD 2292927576 U2020 U200 U200 U200 U200 U20 U2
I hereby certify that the information above	y is true and complete to the best of m	y knowledge and belief.	
SIGNATURE	TITLEI	Engineer	DATE11/09/03
Type or print name James F. Newman	, P.E. Triple N Services, Inc.		Telephone No. 432-687-1994
(This space for State use) APPPROVED BY Hary W. L Conditions of approval, if any	June OC FIELD REPRESENTA	TIVE II/STAFF MANAGEI	DATE
			NOV 1 2 2003



ConocoPhillips

Proposed Plugging Procedure Page 1 of 1

Vacuum Glorieta East Unit Tract 10 #2 Vacuum Glorieta Field Section 28, T17S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI producer - CIBP set @ 6,050' on 02/27/01

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- 1. Set steel pit and flow well down as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP. RIH w/ workstring tbg to CIBP @ 6,050'.
- 3. RU cementer and circulate hole w/ mud, pump 25 sx C cmt on CIBP 6,050 5,800'. Glorieta plug
- 4. POOH w/ tbg to 4,080' and pump 25 sx C cmt 4,080 3,800'. Grayburg plug
- 5. POOH w/ tbg to 2,979' and pump 25 sx C cmt 2,979 2,700'. base of salt plug
- 6. RU lubricator and RIH w/ wireline and perforate 41/2" casing @ 1,701'. POOH w/ wireline.
- 7. RIH w/ packer to 1,300' and establish rate into perforations, squeeze 80 sx C cmt w/ 2% $CaCl_2$ 1,701 1,535'. WOC & tag this plug. surface casing shoe & top of salt plug
- 8. RIH w/ wireline and perforate 41/2" casing @ 50'. POOH w/ wireline.
- 9. ND BOP and NU wellhead. Squeeze 20 sx C cmt 50' to surface. surface plug
- 10. SI well. RDMO. Clean steel pit and dispose of bottoms.
- 11. Cut off wellhead and anchors, level location. Leave location clean and free of trash.

		Field Name:	Vacuum G	orieta		· · · · · ·		
		County:	Lea		Well Type:		SI producer	
		State:	New Mexic	.	Depth:		6,251	
		RRC District:			Drilling Com	menced:	August 6, 1	964
		Section:	28				August 19, 1964	
		Block:			Date Well Plu			
2		Survey:	T-17-S; R-3	5-E	Longitude:		1	
Ś.		Unit Letter G,	-		Latittude:			
				······	Freshwater D	epths:		·····
		API #:	42-02	5-20832		•		
		Lease or ID:	B-1	423-2				
		-Marshare da	Bear Bailte		Casing			
		Descrip		Size	Depth	тос	Cement	Hole Siz
				(inches)	(feet)	(feet)	(sacks)	(inches)
		Surfac	ce:	8-5/8"	1,651	surface	800	12-1/4
								[
		Produc	tion:	4-1/2"	6,249	2,500	700	7-7/8
				[T	1		
Top of Salt	8				1			
Fop of Salt				1		1		
	● ● ● 8-5/8" @ 1,651'	1. S.		E	xisting Plugs	Ця.	I	
	1				Тор	Depth	Volume	Volume
		D	escription		(feet)	(feet)	(sacks)	(cu ft)
		1 CIBP set 2/			6,050	6,052	(500(3)	CIBP
					0,000	0,002		
						+		
					ļ			
								
Page of Coll								
Base of Salt 5 2,879'								l L
					Perforations			
						Тор	Depth	
			Form	ation		(feet)	(feet)	
l l l l l l l l l l l l l l l l l l l			Glorieta (Paddock)		6,105	6,166	
								· · · · ·
No.								
4								
					· · · · · · · · · · · · · · · · · · ·	1		
		2 S T		- -	Formations	1.1		
			Na	100 C			ormation	
			Top of Salt			1,585		
		Base of Salt			2,879			
						<u> </u>		
						<u> </u>		
	CIBP set @ 6,050'					 		
			- 199 - 1944		Comments	l Alexandra da la	S Page 10 Sold States	
	Glorieta (Paddock) perforations 6,105 - 6,166	2/27/01: Set CIE			A THE PART AND A SHORE THAT			
		2/27/01: Set CIB	or @ 0,050'	a lested casi	ng			
S.								
×	700 sx, TOC 2,500' calc					-		
repared By:	Jim Newman						Troth	TIPLE N WICES IN

····· •····

