*						
Submit 3 Copies To Appropriate District	State of New M			Form C-103		
Office District I	Energy, Minerals and Nati	ural Resources	WELL API NO.	May 27, 2004		
1625 N. French Dr., Hobbs, NM 87240 District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATIO	N DIVISION	30-02	25-34632		
District III	1220 South St. Fr		5. Indicate Type of Lease STATE X FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM	87505	6. State Oil & C			
1220 S St Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: Eunice Monument South Unit			
1. Type of Well: Oil Well X Gas Well	Other		8. Well Number	748		
2. Name of Operator			9. OGRID Num	ber		
XTO Energy, Inc. 3. Address of Operator			005380 10. Pool name or Wildcat			
200 N. Loraine, Ste. 800	200 N. Loraine, Ste. 800 Midland, TX 79701			Eunice Monument; Grayburg-San Andres		
4. Well Location						
Unit Letter G :	1510' feet from the No	orth line and	2543' feet f	from the <u>East</u> line		
Section 15	Township 21S	Range 36E	NMPM	County Lea		
	11. Elevation (Show whether	r DR, RKB, RT, GR, el	tc.)			
Pit or Below-grade Tank Application	or Closure		<u> </u>			
Pit type Depth to Groundwater _		esh water well Di	stance from nearest s	urface water		
Pit Liner Thickness: mil	Below-Grade Tank: Volum	ebbls; Constructi	on Material			
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	Appropriate Box to Indicat					
OTHER: Clean Out, Acid Stimula		OTHER:				
<ul><li>13. Describe proposed or completed of starting any proposed work). or recompletion.</li></ul>	operations. (Clearly state all p	ertinent details, and giv		including estimated date n of proposed completion		
See Attached for Procedure	<u>.</u>			,		
		AUG 1 9 201 HOBBS	OCD			
I hereby certify that the information ab grade tank has been/will be constructed or cl						
SIGNATURE Kauty Wa			ry Analyst	DATE 08/07/08		
Type or print name Kristy Ward	E	-mail address: kr	risty_ward@xtoe Te	nergy.com lephone No. 432-620-6740		
For State Use Only		LD REPRESENTATIVE	11 18 7 A 1949 A A A A	AUG 282008		
APPROVED BY Cample	W. Huy T	ITLE	WOIATT MANA			

÷---

.

Conditions of Approval, if any:

004
-----

-



ELEVATION:	GL – 3,572' KB – 3,578'	TD – 3,950'					
WELL DATA:							
Current Status:	Producing. Last Well Test: 6/6/08 - 13 bopd / 529 bwpd / 3 mcfpd						
Surface Casing:	8-5/8" 24#. Set at 518'. Cmnt'd w/350 sx. Circulated.						
Prod. Casing:	5-1/2" 15.5#. Set at 3,950. Cmnt'd w/725 sx. Circulated.						
COMPLETION:							
Perforations:	3,790 - 3,798'	Grayburg 2	8'	8/99			
	3,806 - 3,816'	Grayburg 2A	10'	8/99			
	3,826 - 3,836'	Grayburg 2A	10'	8/99			
	3,848 - 3,854'	Grayburg 3	6'	8/99			
	3,860 - 3,872'	Grayburg 3	12'	8/99			
	3,880 - 3,886'	5 0	6'	8/99			
:	3,892 - 3,900'	Grayburg 4	8'	8/99			
	3,908 – 3,916'	Grayburg 4	8'	8/99			
<b>OBJECTIVE:</b> Clean Out, Acid Stimulate, and Scale Squeeze Well							

## **RECOMMENDED PROCEDURE**

(Verify that anchors have been set and tested per NM OCD & OSHA guidelines)

- 1. MIRUPU. MI and rack 2-7/8" workstring. POOH w/ rods. ND WH. NU BOP.
- 2. MIRU Scanalog. POOH w/ production tbg and pump and scanalog tbg while POOH. Check for signs of scale buildup on pump and/or rods.
- 3. RIH w/4-3/4" bit on workstring to 3,950'. Clean out fill if necessary. Circulate hole clean. POOH.
- 4. RIH w/ Sonic Hammer on 2-7/8" workstring. RU stripping head.



## Stimulation Procedure LEA COUNTY, NEW MEXICO August 7, 2008

- 5. RU. SH perfs w/3,000 gals brine (approx. 30-40 bbls per stand) while circulating to reverse pit (pit should have screen to catch solids). Circulate hole clean. Check samples of solids for signs of scale and send to Champion for analysis.
- 6. POOH & LD sonic hammer. PU & RIH w/ 5-1/2" packer on workstring. Set packer at ~3,750'. RU pumping company on backside and pressure test TCA to 500#.
- 7. If pressure holds ok, proceed with procedure. If not, notify Midland for further instructions.
- 8. MIRU acid company. Test lines to 4,000 psi. Treat the isolated interval with 5,000 gals of 20% NEFE 90/10 (90% Acid/10% Toulene) in 5 stages dropping rock salt for block between each stage. Max treating rate/pressure 4 BPM/1,500 psi. Use the following pump schedule but adjust the volumes as necessary on job to achieve good block action:
  - a. 500 gals acid
  - b. 200 # rock salt in 4 bbls 9# brine
  - c. 750 gals acid
  - d. 500 # rock salt in 10 bbls 9# brine
  - e. 1,000 gals acid
  - f. 750 # rock salt in 15 bbls 9# brine
  - g. 1,250 gals acid
  - h. 1,050 # rock salt in 20 bbls 9# brine
  - i. 1,500 gals acid
  - j. Total of 5,000 gals of 20% 90/10 Acid and 2,500# rock salt.
- 9. RDMO.
- 10. Flow back or RU swab and swab back acid load. Determine flow rate and oil cut. If decision is made to chemically squeeze well, continue to step #11. If not, skip to step #14.
- 11. MIRU.
- 12. Squeeze perfs and open hole w/ scale inhibitor as per Champion's recommendation down tbg in 5 stages dropping rock salt for block between each stage. Start with 200# block and adjust as necessary. Treatment should be designed assuming 800 bfpd total rate. Flush per Champion's recommendation. SI overnight.
- 13. RDMO.
- 14. POOH w/ packer and workstring.



## Stimulation Procedure LEA COUNTY, NEW MEXICO August 7, 2008

15. RIH with production tbg, rods, and pump. Production equipment should be designed for ~800 bfpd or better estimate based on swab results. ND BOP. NU WH. Put well in test and RWTP. RDMOPU.

2 1 1 1 M

## CURRENT WELLBORE DIAGRAM

. . . . .

