Form 3160-5 (April 2004)	UNITED STATES				FORM APPROVED OMB NO 1004-0137
(April 2004)		NT OF THE INTERIOR	OCE)-HOBBS	Expires March 31, 2007
			NELLO		5 Lease Serial No.
	Do not use this form for proposals to drill or to re-ontor an			NM LC0317408 3 6 If Indian, Allottee or Tribe Name	
	abandoned well. Use For	m 3160-3 (APD) for suc	fi proposale		
SUBMIT IN TRIPLICATE - Other instructions on reverse Side					7 If Unit or CA/Agreement, Name and/or No NM70948A
1. Type of Well X Oil Well	Gas Well Other		SFD - 2 200	ני	8 Well Name and No
2. Name of Operat			ADDC	MAN	Eunice Monument #626
XTO Energy	Inc.		UDDS	ULL	South Unit
3a Address3b Phone No (include area code)200 N. Loraine, Ste. 800 Midland, TX 79701432-620-6740					30-025-31465
4. Location of Well (Footage, Sec., T, R, M., or Survey Description)					10 Field and Pool, or Exploratory Area Eunice Monument; Grayburg-
2650' FSL & 1630' FWL					San Andres
Unit Ltr. F, Section 4, T-21S, R-36E 🖌					11. County or Parish, State
12.					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION					
					(Start/Resume) Water Shut-Off
		Alter Casing	Fracture Treat	Reclamatio	
	Subsequent Report	Casing Repair	New Construction	Recomplet	
	Final Abandonment Notice	Change Plans	Plug and Abandon	Temporari	,
		Convert to Injection	Plug Back	Water Disp	
Attach the E following co testing has b determined t 1. MIRU. 2. Drill 500-6 3. RWTP. next 4. MIRUP 5. Drill 2-7/8 6. Unset for co	Bond under which the work will be per mpletion of the involved operations in been completed. Final Abandonment is hat the final site is ready for final inspe Rack up 3,900' of 2-7/8" out CIBP at 3,600' & cle 00 bfpd rate. ND BOP. NU RDMOPU. Put well in test step. U. Rack up 3,900' of 2-7/ out CIBP at 3,806' & cle " WS. Set pkr @ 3,741'. L	formed or provide the Bond N if the operation results in a mu Notices shall be filed only afte tion.) J-55 WS. ND WH. NU van well out to PBTD WH. . If well fails to p 8" J-55 WS. ND WH. N an out well to TD @ &T BS (sqz'd perfs f pkr. RU swab. Swab s below pkr & perfs	No. on file with BLM. Itiple completion or re r all requirements, inc BOP. PU & RIH at 3.086'. RIH 3.870'. PU & RI 3.870'. PU & RI fr 3.648-3.738' on perfs fr 3. above pkr. Det	/BIA. Required s completion in a r shuding reclamatio w/4-3/4" bi d w/producti arbons and/o (H w/4-3/4" RIH w/5-1/2") to 500 ps 816-3,865'. cermine flow	on equipment based on a or excess water, proceed to bit & DCs on 2-7/8" WS. pkr & collar locator on i. Monitor backside & check rate & oil cut.
See next	page for Squeeze procedu	re.)_	APPROVED
14 I hereby certify	that the foregoing is true and correct (Typed)		Tıtle	15	AUG 2 7 2008
	y Ward		Regula	tory Analyst	
Kristy Ward			Date 7/22/200	8	JAMES A. AMOS SUPERVISOR-EPS
		SPACE FOR FEDERAL	L OR STATE OFF	ICE USE	
Approved by	())	17A	Title		Date
certify that the app	oval, if any, are attached. Approval o plcant holds legal or equitable title to e the applicant to conduct operations th	those rights in the subject lea	or Office se		
Title 18 U.S.C Se States any false, for	ction 1001, and Title 43 U S.C. Section ctitious or fraudulent statements or rep	n 1212, makes it a crime for an resentations as to any matter w	ny person knowingly a ithin its jurisdiction	nd willfully to mai	ke to any department or agency of the United

\$



EMSU 626 Grayburg Recompletion and Reactivation Procedure LEA COUNTY, NEW MEXICO June 19, 2008

Squeeze Well

- 1. POOH w/pkr and WS. PU and RIH w/5-1/2" CICR on WS. Set CICR at ~ 3,640'.
- MIRU sqz company (to be determined later). Load BS and monitor during cmt sqz. Establish injection rate dwn WS. Sqz perfs from 3,744 – 3,865' as per forthcoming procedure. Sting out reverse circulate clean and POOH. Shut-in overnight.
- 3. PU & RIH w/4-3/4" bit & DC's on 2-7/8" WS. Tag top of CICR @ 3,640'. RU power swivel.
- 4. DO CICR/sqz to ~3,810'. Circulate hole clean. Pressure test csg to 500 psi. Report results to Midland.
- 5. MIRU Wireline. TIH with 3-3/8" casing gun and perforate 3,775 3,783' (8', 24 holes) and 3,752 3,758' (6', 18 holes) with 3 JSPF, 120 degree phasing, and premium charges. Correlate perforating with the *Spectral Density Dual Spaced Neutron Log* run but Halliburton on 12/16/1991. POOH. RDMO wireline company.
- 6. PU and TIH with 5-1/2" RBP, collar locator, and treating packer on WS. Set RBP at 3,790'. Test to 500 psi. (Log shows casing collars at 3,771' and 3,798')
- 7. MIRU acid/pumping company. Test lines to 3,000 psi.
- Pull packer to 3,768' and reset. Monitor backside. Breakdown perfs fr 3,775 3,783' and pump 1,000 gals (24 bbls) of 15% NEFE acid at a max rate/pressure of 1
 BPM/900 psi. If perfs communicate up, PUH to ~3,750' and set pkr. Pump remainder of job.
- 9. Unset packer and RIH to RBP. Unset RBP. PUH to 3,765' and set RBP. PUH to 3,750' and set packer. (Log shows casing collars at 3,748' and 3,771')
- 10. Monitor backside. Breakdown perfs fr 3,752 3,758' and pump 800 gals (19 bbls) of 15% NEFE acid at a max rate/pressure of 1 BPM/900 psi.
- 11. Unset packer and RIH to RBP. Unset RBP. RIH to 3,790' and set RBP. PUH to 3,768' and set packer. (Log shows casing collars at 3,771' and 3,798').

PROCEDURE BY LDP



EMSU 626 Grayburg Recompletion and Reactivation Procedure LEA COUNTY, NEW MEXICO June 19, 2008

- RU swab and swab perfs fr 3,775 3,783'. Monitor backside for communication. Determine flow rate and oil cut. If perfs communicate, PUH w/pkr to 3,750' and swab both sets of perfs (3,752 – 3,783'). Then continue on to step #16. If no communication, continue to step #14. Report results to Midland.
- 13. Unset packer and RIH to RBP. Unset RBP. PUH to 3,765' and set RBP. PUH to 3,750' and set packer. (Log shows casing collars at 3,748' and 3,771').
- RU swab and swab perfs fr 3,752 3,758'. Monitor backside for communication. Determine flow rate and oil cut. Report results to Midland.
- 15. RD swab. Unset RBP and packer and POOH. ND BOP. NU WH. RIH with production equipment based on a rate derived from swab results.
- 16. RWTP. RDMOPU. Put well in test.

RECOMMENDED: ane Pearson 25/08 **APPROVED:** Guv Havkus **APPROVED:** amni

UPDATED WELLBORE DIAGRAM

