State of New Mexico	
Energy, Minerals and Natural Resources De	epartment

Energy, Minerals and Natural Resources Departmen		
FILE IN TRIPLICATE OIL CONSERVATION DIVISION	Revised 5-27-2004	
DISTRICT I 1625 N. French Dr., Hobbs, NM 885 CEE MEE 120 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-31423	
DISTRICT II	5 Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 889 EP 15	STATE X FEE	
	6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, M TATO TATA SUB	7. Lease Name or Unit Agreement Name	
SUNER Y SOUCHS AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 4	
I Type of Well.	8. Well No. 235	
Oil Well Gas-Well Other Injector	9. OGRID No 157984	
2. Name of Operator Occidental Permian Ltd.	9. OOKID NO 137984	
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)	
HCR 1 Box 90 Denver City, TX 79323		
4. Well Location	From The West Line	
Sin boot K 2100 For the one bound 2111		
Section 4 Township 19-S Range 38-E	NMPM Lea County	
3622' KB		
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Mat	erial	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP		
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN		
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed c RUPU & RU. ND wellhead/NU BOP. POOH w/tw/ing and packer. Packer would not come loose. PU rotary wireline and cut IPC tubing 	ompletion or recompletion.	
² 2. POOH w/tubing and packer. Packer would not come loose. RU rotary wireline and cut IPC tubing. RD rotary wireline. Jar on stuck packer. Came loose. POOH w/packer.		
3. RIH w/bit & drill collars. Tag fill @4284'. POOH w/bit & drill collars.		
4. RIH w/cement retainer. Set retainer @4096'. RU HES and squeeze off all perfs from 4130-4260' w/300 sxs of Premium Plus cement w/2% Calc chloride. Sting out of cement retainer and reverse out, leaving 287 sxs in formation. RD HES.		
5. RIH w/bit & dtill collars. Tag cement @4093'. Drill out cement retainer @4096'. Drill out cement from 4099' to 4235'. Circulate clean. POOH		
w/bit & drill collars.		
6. RU wireline & perforate casing @4201-05' (2 JSFP), 4213-16' (2 JSPF), 4221-23' (1 JSPF), 4226-27' (1 JSPF). RIH w/CIBP set @4228 (new PBTD). Perforate casing @4093-99', 4101-07', 4132-38', 4146-4154', 4158-60', 4168-71', 4174-77', 4179-82', 4191-94', 4196-98' @2 JSPF. RD		
	a on attached sheet***	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify the constructed or	hat any pit or below-grade tank has been/will be	
closed according to NMOCD guidelines , a general permit or an (attached) alternative	OCD-approved	
SIGNATURE Mendy CLAPhone TITLE Administrative.	Associate DATE 09/16/2008	
TYPE OR PRINT NAME Mendy A. Johnson, () E-mail address: <u>mendy_johnson@oxy.com</u>	TELEPHONE NO. 806-592-6280	
For State Use Only		
APPROVED BY		
	DATES F P 2 2 2008	
CONDITIONS OF APPROVAL IF ANY:	DATES <u>E P 2 2 2008</u>	

; ;

SHU 235

- RIH w/PPI packer set @3934'. RU HES & acid treat well w/5376 gal of 15% NEFE HCL acid in 5 settings. RD HES. POOH w/PPI packer.
- 8. RIH w/5-1/2" Arrowset packer set on 130 jts of 2-3/8" tubing. Packer set @4063'.
- 9. ND wellhead/NU BOP.
- 10. Test casing to 480# and chart for the NMOCD.
- 11. RDPU & RU. Clean location and return well to injection.

RUPU 08/12/08 RDPU 08/22/08



