	o Appropriate Distric	<u> </u>	tate of New M	lexico		Form C-103	
District I 1625 N. French Di	625 N. French Dezer (1955, 1) Mar 224				June 19, 2008 WELL API NO.		
	OIL CONSERVATION DIVISION			30-025-24388 5. Indicate Type STATE	of Lease		
District III 1000 Rio Brazos Rd, Aztec, Si F. P. 2 9 2008 District IV 1220 S. St Francis Dr. Santa Fe, NM 87505 Santa Fe, NM 87505			6. State Oil & Ga K-03354				
87505 SUNDRY. NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				 7. Lease Name or Unit Agreement Name New Mexico State -7- 			
PROPOSALS.)	ll: Oil Well 🛛		Other		8. Well Number	1	
2. Name of Op	erator	/			9. OGRID Numb 2832	ber	
Bridwell Oil 3. Address of C Post Office	Operator	ita Falls, Texas 763(07		10. Pool name or Wildcat Flying M; San Andres		
4. Well Location					/		
Unit L Section		et from the North li To	ine and 660 feet f wnship 98	Range 33E	NMPM	County Lea	
				PR, RKB, RT, GR, etc			
	<u> </u>	4380 UL					
	12. Chec	k Appropriate Bo	ox to Indicate	Nature of Notice	, Report or Other	Data	
		INTENTION T	0 [.]	SUE	BSEQUENT RE	PORT OF:	
	MEDIAL WORK	PLUG AND AE	BANDON 🛛	REMEDIAL WO	RK 🗌	ALTERING CASING	
TEMPORARILY		CHANGE PLA				P AND A	
PULL OR ALTE			OMPL	CASING/CEMEN			
DOWINIOLE C	OWWINGEL		_	-		_	
OTHER:				OTHER.	1		
of starti	e proposed or co	i work). SEE RULE	E 1103. For Mult	iple Completions: A	Attach wellbore diag	es, including estimated date ram of proposed completion	
or recol	mpletion.						
or recol	mpletion.	on	1 1.			10 2440'5	
of reco	mpletion.	on Servicing Rig, pull at 4350' dump	rods, pump, and t	tubing out of well.	to 4450' PEA	f.@2440' Squ	
or reco	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a	Servicing Rig, pull at 4350', dump 2 sac	rods, pump, and t ks cement. Perfo with 4 shots. Su	tubing out of well. prations are at 4396' arface casing shoe is	to 4450'. PEA at 372'. PEA	f.@2440' Squ f.@1878' Sque	
or recol	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa	acks cement, plac		to 4450'. at 372'. e 4.5" casing from 32	f.@2440'Squ f.@1878'Squ ^{22' to 422'.}	
or recol	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sac cement plug at grour	nd surface . 60 '	to surface	4.5 Casing nom 52	f. @ 2440' Squ f. @ 1878' Squ 2' to 422'. woc + TAg	
or recol	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at grour off 3' below ground l	acks cement, plat ad surface . 60 ' ₁ level, weld plat w		4.5 Casing nom 52	f. @ 2440' Squ f. @ 1878' Squ 22' to 422'. WOC + TAg	
01 1600	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at groun off 3' below ground 1 t Date: As Soon As 1	acks cement, plat ad surface . 60 ' ₁ level, weld plat w	to Saaface_ vith well name and o The Oil Conserva	perator, cover.	be notified	
or recol	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at grour off 3' below ground l	acks cement, plat ad surface . 60 ' ₁ level, weld plat w	to Saaface_ vith well name and o The Oil Conserva	pperator, cover.	be notified	
	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at groun off 3' below ground 1 t Date: As Soon As 1	acks cement, plat ad surface . 60 ' ₁ level, weld plat w	to Saaface_ vith well name and o The Oil Conserva	perator, cover.	be notified	
	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at groun off 3' below ground 1 t Date: As Soon As 1	acks cement, plat ad surface . 60 ' ₁ level, weld plat w	<i>to Sarface</i> vith well name and o The Oil Conserva 24 hours prior to	perator, cover.	be notified	
	Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o	Servicing Rig, pull at 4350', dump 2'sac e 4.5" casing at 422' culation, pump 50 s cement plug at groun off 3' below ground 1 t Date: As Soon As 1	Possible	<i>to Sarface</i> vith well name and o The Oil Conserva 24 hours prior to	perator, cover.	be notified	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	Rig Release	The Oil Conserva 24 hours prior to Date:	perator, cover. ation Division Must to the beginning of p	be notified	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	Rig Release	<i>to Sarface</i> vith well name and o The Oil Conserva 24 hours prior to	perator, cover. ation Division Must to the beginning of p	be notified	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	Acts centent, play nd surface-60' level, weld plat w Possible Rig Release	The Oil Conserva 24 hours prior to Date:	ation Division Must o the beginning of p	be notified lugging operations	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	Rig Release	best of my knowled	ation Division Must to the beginning of p	be notified lugging operations 9/26/2008	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start that the information Steve	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	Rig Release	best of my knowled	ation Division Must o the beginning of p lge and belief. D s@wf.net	<i>be notified</i> lugging operations	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start that the information Steve me_	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	d surface- 60 level, weld plat w Possible d complete to the Complete to the E-mail addr	best of my knowled President	lge and belief.	9/26/2008 ATE	
Spud Date:	mpletion. Plug & Abando 1. MIRU Well 2. Set a CIBP a 3. Perforate the 4. Establish cir 5. Set 5 sacks c 6. Cut casing o Estimated Start that the information Steve me Steve	Servicing Rig, pull at 4350', dump 2 sac e 4.5" casing at 422' culation, pump 50 sa cement plug at groun off 3' below ground l t Date: As Soon As l	d surface- 60 level, weld plat w Possible d complete to the Complete to the E-mail addr	best of my knowled President	Ige and belief.	9/26/2008 ATE	

't

10/2/2008

30-025-24388-00-00

Wellbore Diagram

NEW MEXICO 7 STATE No. 001

Company Name: BRIDWELL OIL CO					
Location: Sec:	7 T: 9S R: 33E Spot:				
Lat: 33.5494068795722 Long: -103.599421236065					
Property Name: NEW MEXICO 7 STATE					
County Name:	Lea				

Cement from 372 ft. to surface Surface: 8.625 in. @ 372 ft. Hole: 8.625 in. @ 372 ft.

Cement from 4480 ft. to surface Packer. 4.5 in. @ 4360 ft. Tubing: 2.375 in. @ 4355 ft. Production. 4.5 in. @ 4480 ft.

Hole: 4 5 in. @ 4480 ft.

TVD: 4480

PBTD:

String Information						
String	Bottom (ft sub)	Diameter (inches)	Weight (lb/ft)	Length (ft)		
HOL1	372	8.625				
SURF	372	8.625	20	372		
HOL3	4480	4.5		-		
PKR	4360	4.5		5		
PROD	4480	4.5	9.5	4480		
T1	4355	2.375		4355		

Cement Information

String	BOC (ft sub)	TOC (ft sub)	Class	Sacks
PROD	4480	0	С	250
SURF	372	0	С	275

Perforation Information

Тор	Bottom		0.644/54	No Chie	D4 6
(ft sub)	(ft sub)		Shts/Ft	No Shts	Dt Sqz
4396	4450	_			

Formation Information St Code Formation

Depth

r263

TD: