District I 1625 N. French Dr., Hobbs, NM 88240		1	Form C-103	
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	urál Resources	June 19, 2009 WELL API NO.	<u>8</u>
District II	OH' CONCERNATION	DIMIGION	30-005-01098	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease	_	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE X FEE		
District IV 1220 S St. Francis Dr., Santa Fe, NM	Santa Fe, NIVI 8	/505	6. State Oil & Gas Lease No.	
87505			303737	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name West Cap Queen Sand Unit		
1. Type of Well: Oil Well Gas Well Other Injector			8. Well Number 11	
2. Name of Operator CELERO ENERGY II, LP		9. OGRID Number 247128		
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701		10. Pool name or Wildcat Caprock Queen		
4. Well Location			- P	7
	feet from the South	line and 660	feet from the Eastline	1
Section 17		ange 31E	NMPM County Chaves	
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.,		o la dia
	4140' GL			
12. Check A	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data	
NOTICE OF IN	ITENTION TO:	CIID	SEQUENT REPORT OF:	
NOTICE OF INTENTION TO: SUB				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	-	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB 🔲	
DOWNHOLE COMMINGLE				
OTHER:	П	OTHER: Acdzd &	z ran MIT	
13. Describe proposed or comp	oleted operations. (Clearly state all ork). SEE RULE 1103. For Multip	pertinent details, an	d give pertinent dates, including estimated da tach wellbore diagram of proposed completion	te on
•				
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" I	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested	ump 64 bbls acid, toluene 80/20 mix @ 4.8 TP increase to 545#. Pump flush 4.8 BPM, IH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Reti	ormation pressure dropped 100#. 15 mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set pl down csg, pulled 20 pts tension or urn well to injection.	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested to pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid	ormation pressure dropped 100#. 1s mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set p I down csg, pulled 20 pts tension or	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested to pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Reti	ormation pressure dropped 100#. 15 mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set pl down csg, pulled 20 pts tension or urn well to injection.	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested to pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Retr	ormation pressure dropped 100#. 15 mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set pl down csg, pulled 20 pts tension or urn well to injection. Rig Release D	st stage of rock salt. 305#, 121 BLTR. T okr @ 2590'. Tested n pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TIH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Reti	ormation pressure dropped 100#. 15 mins 206#, 10 mins 306#, 15 mins PC, J-55, 4.7#, 8rd, EUE tbg. Set pl down csg, pulled 20 pts tension or urn well to injection. Rig Release D	st stage of rock salt. 305#, 121 BLTR. T okr @ 2590'. Tested n pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TIH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held	,
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Return the service of t	above is true and complete to the b	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested in pkr. Held ok. Run eate:	TP increase to 545#. Pump flush 4.8 BPM, TIH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Retr	above is true and complete to the b	st stage of rock salt. 305#, 121 BLTR. T okr @ 2590'. Tested n pkr. Held ok. Run	TP increase to 545#. Pump flush 4.8 BPM, TIH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held	,
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit for TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Retrieved Thereby certify that the information SIGNATURE Type or print name Lisa Hunt	above is true and complete to the base of	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested in pkr. Held ok. Run eate:	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held e and belief. DATE 09/30/2008	
8/7/08-8/13/08 MIRU well service. CO to 2830 BPM, TO 571#, when acid hit of TP 611#, 50 bbls. ISIP 330#, 5 pkr w/on/off tool, 83 jts 2 3/8" If on/off tool, circ 60 bbls pkr fluid 30 mins. Chart is attached. Return the service of t	above is true and complete to the base of the E-mail address	st stage of rock salt. 305#, 121 BLTR. Tokr @ 2590'. Tested in pkr. Held ok. Run eate: Dest of my knowledg latory Analyst	TP increase to 545#. Pump flush 4.8 BPM, TH w/2 3/8" x 5 1/2" nickel plated arrow set to 500#. Held ok. ND BOP. Back off good MIT chart. Pressure up to 580#. Held e and belief. DATE 09/30/2008 hergy.com PHONE: (432)686-1883	

