

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87400

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

87505

Energy, Minerals and Natural Resources

June 19, 2008

RECEIVED

OCT 02 2008

HOBBS OIL

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-22983

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
E.W. Walden

8. Well Number 8

9. OGRID Number

147179

10. Pool name or Wildcat

Eumont; Yates-7 Rivers-Queen Oil

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other2. Name of Operator
Chesapeake Operating, Inc.3. Address of Operator P.O. Box 18496
Oklahoma City, OK 73154-0496

4. Well Location

Unit Letter K : 2280' feet from the South line and 1980 feet from the West line
Section 15 Township 22S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3397' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Dear Sirs/Madams,

Please find the following in order to plug and abandon this well:

Plug and abandonment procedure.

Actual & proposed well bore schematic

NMOCD's C-144(CLEZ) pit permit.

THE OIL CONSERVATION DIVISION **MUST**
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.

Spud Date: 01/28/1969

Rig Release Date: 02/15/1969

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Linda Good TITLE Sr. Reg. Compl. Sp. DATE 09/30/2008Type or print name Linda Good E-mail address: linda.good@chk.com PHONE: (405)767-4275

For State Use Only

APPROVED BY: [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE OCT 06 2008

Conditions of Approval (if any):



**E W Walden #8
Plug and Abandonment
Lea County, New Mexico**

Plug and Abandonment Procedure

1. Notify the NM OCD 24 hours in advance prior to commencing plug and abandonment operations.

Location: Section 15, 22S-37E, 2,280' FSL & 1,980' FWL

Surface Casing: 8-5/8" 24# 0-344'

Production

Casing: 5 1/2" 14# J-55 0-4,102', ID=5.012", Drift=4.887", Burst=3,120#

PBTD/TD: 4,093'/4,102'

Current Perfs: Grayburg 3,772' – 3,855'
3,895' – 3,910'
Penrose 3,449' – 3,484'

Formation Tops:	T. Salt	1,210'
	B. Salt	2,400'
	T. Yates	2,544'
	T. 7 Rivers	2,768'
	T. Queen	3,338'
	T. Grayburg	3,631'

Procedure

Hold Tailgate Safety meeting prior to beginning work each morning and as required for specific operations.

2. Rack and tally 137 joints of 2-7/8" N-80 workstring.
3. MIRU PU. ND WH. NU BOP.
4. Load well with 9.5# brine with 12.5 # of gel per bbl and pressure up to 500# and test for leak-off.
5. RIH w/ gauge ring and junk basket to PBTD @ 4,093'. RIH and set CIBP @ 3,720', tag CIBP w/ wireline to verify depth, and then dump bail 35' cement.
6. RIH and set CIBP @ 3,400', tag CIBP w/ wireline to verify depth, and then dump bail 35' cement.
7. Perforate casing w/ 4 squeeze holes @ 2,450' (Bottom of Salt @ 2,400') and sqz a 100' *-MINIMUM 25sx.cmt.* cement plug inside and out. Pull up hole, wait 4 hours and tag plug.
8. Perforate casing w/ 4 squeeze holes @ 1,260' (Top of Salt @ 1,210') and sqz a 100' cement plug inside and out. Pull up hole, wait 4 hours and tag plug.

→ 25 sx. cmt. @ 394'; 8⁵/₈" csg. shoe, WOC + Tag.

9. PUH w/ tbg to 60'. Fill casing back to surface w/ cement. POH w/ tbg. Top off casing w/ cement.
10. RDMO. Install dry hole marker and cut off dead man. Restore location.

Contacts

Completion Superintendent

Lynard Barrera
Office: 575-391-1462
Cell: 575-631-4942

Asset Manager

Kim Henderson
Office: 405-879-8583
Cell: 405-312-1840

Production Foreman

Melvin Harper
Office: 575-391-1462
Cell: 575-631-5348

Field Engineer

Doug Rubick
Office: 575-391-1462
Cell: 575-441-7326



Proposal for Workover

E W WALDEN 8

Field: PENROSE SKELLY
County: LEA
State: NEW MEXICO
Location: SEC 15-22S-37E, 2280 FSL & 1980 FWL
Elevation: GL 3,397.00 KB 3,408.00
KB Height: 11.00

Spud Date: 1/28/1969
Initial Compl. Date:
API #: 3002522983
CHK Property #: 891414
1st Prod Date: 3/8/1969
PBDT: Original Hole - 4093.0
TD: 4,102.0

