Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137

Expires March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELL

Do not use this form for proposals to drill or to re-enter

LC-031740-A 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side				7 If Unit or CA/Agreement, Name and/or No NM - 70948A	
1. Type of Well Oil Well Gas Well X Other 2. Name of Operator XTO Energy Inc. 3a. Address 200 N. Loraine, Ste. 800 Midland, 4. Location of Well (Footage, Sec., T, R, M, or Survey Inc.) 1860' FSL & 1980' FEL; Unit Ltr. J,	3b. Phone No. (include area code) TX 79701 432-620-6740 Description)				ment #410 WIW
12. CHECK APPROPRIATE			NOTICE, REP	11. County or P Lea ORT, OR OTHI	NM NM
TYPE OF SUBMISSION	TYPE OF ACTION				
X Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injects	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclamation Recomplete	te [Water Shut-Off Well Integrity X Other Reactivate Injection Well

- If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)
 - MIRUPU. MI & rack up 4,200' of 2-7/8" J-55 workstring. ND WH. NU BOP. PU & RIH w/4-3/4" bit and DC's on 2-7/8" WS. MIRU.
 - Drill out CIBP @ 3,900' and clean well out to PBTD @ 4,150'. Circulate clean. POOH w/bit, DC's, and WS. LD bit and DC's. RDMO Rev unit.
 - 3. PU & RIH w/Sonic Hammer on 2-3/8" WS. RU stripping head.

which would entitle the applicant to conduct operations thereon.

- MIRU acid co. SH perfs from 3,968-4,138' w/9# brine while circulating to reverse pit. Circulate clean and close in backside & SH perfs from 3,968-4,138' w/2,000 gals, 20% 90/10 acid in injection mode w/ a max pressure of 2,000# tubing & 500# on backside.
- 5. Flush acid w/25 bbls brine water. Drop ball to shift sleeve in tool.
- 6. Flow back or RU swab and swab back acid load. POOH & LD Sonic Hammer and WS.
- PU & RIH w/5-1/2" injection packer and on/off tool w/1.43" profile nipple on 2-3/8" J-55 IPC injection tbg. Set packer at +/-3,880'. Do not set packer in a csg collar.
- Get on/off tool. Pump & circulate packer fluid. Get back on on/off tool. Test tubing/casing annulus to 500 psi. ND BOP. NU WH. Return well to injection. RDMOPU.

H-7766	The Duriet To	LIKE Approval From U			
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title				
Kristy Ward	Regulatory Anal	Regulatory Analyst			
Granty Ward	Date 09/12/08	APPROVED			
THIS SPA	ACE FOR FEDERAL OR STATE OFFICE USE				
Approved by	Title	NOV 1 2008			
Conditions of approval, if any, are attached. Approval of this certify that the applicant holds legal or equitable title to those					

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

WELL DATA SHEET

