Submit 3 Copies To Appropriate District Office District I Energy, Minerals and Natural Resources	Form C-103			
1625 N French Dr., Hobbs, NM 88240	WELL API NO. 30-025-06620			
1301 W Grand Ave, And 10 10 18 21 2008 IL CONSERVATION DIVISION	5. Indicate Type of Lease STATE FEE			
1000 Rio Brazos Ri 1Aziec, NN 87410  District IV  Santa Fe, NM 87505  1220 S. St. Francis Dr., Santa Fe, NM  87505	6. State Oil & Gas Lease No.			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name HARRY LEONARD E			
1. Type of Well: Oil Well Gas Well Other	8. Well Number 1			
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323			
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705	10. Pool name or Wildcat PENROSE SKELLY GRAYBURG			
4. Well Location				
Unit Letter G: 1980 feet from the NORTH line and 1980 feet from the I				
Section 16 Township 21-S Range 37-E NMF  11. Elevation (Show whether DR, RKB, RT, GR,				
3494'GL	eic.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
<u> </u>	DRILLING OPNS. P AND A			
PULL OR ALTER CASING	TENT JOB			
OTHER: ADD PERFS & REFRAC GRAYBURG OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
CHEVRON U.S.A. INC. INTENDS TO ADD PERFS & REFRAC THE GRAYBURG THE INTENDED PROCEDURE & CURRENT & PROPOSED WELLBORE DIAGR. APPROVAL.	RESERVOIR. AMS ARE ATTACHED FOR YOUR			
Spud Date: Rig Release Date:				
I hereby certify that the information above is true and complete to the best of my knowl	- d d h - 1' - C			
SIGNATURE SIGNATURE IN TITLE REGULATORY SPE				
Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375				
For State Use Only  NOV 1 0 2000				
APPROVED BY: TITLE PETROLEUM EN Conditions of Approval (if any):	MOV 1 2 2008			
Commission of Approving (it mit)).				

Harry Leonard E #1 Penrose Skelly; Grayburg T21S, R37E, Section 16

Job: Add Perfs and ReFrac Grayburg

## Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 9/12/08. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 3. MI & RU workover unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. POH LD rods and pump. Remove WH. Install BOP's and test as required. Release TAC. POH w/ 2-7/8" tubing. Scan tubing using Tuboscope scanner while POH. LD all its. but yellow band.
- 4. PU and GIH with 6 1/4" MT bit on production tbg, and WS as needed to 6400'. Reverse circulate well clean from 6400' using 8.6 PPG cut brine water, if possible. POH with tbg string and bit. LD bit.
- 5. MI & RU WL. GIH w/7" CIBP to 6380'. Set CIBP at 6380'. POH. LD setting tool. GIH and dump bail 35' cmt on top of CIBP at 6380'. POH. GIH w/7" CIBP to 5780'. Set CIBP at 5780' POH. LD setting tool.
- 6. GIH with 3 1/8" slick casing guns and perforate the following intervals with 4 JSPF at 120 degree phasing using 23 gram premium charges:

Тор	Bottom	Net Ft.	No. Perfs
3994	4004	10	40
3977	3987	10	40
3950	3956	6	24
3938	3946	8	32
3884	3894	10	40

7. POH. GIH and dump bail 35' of cement on top of CIBP at 5780'. POH RD & release WL. Note: Use Baker Atlas Cement Bond Log dated 6/3/2002 for depth correction.

- 8. RIH w/ 7" PPI packer w/ SCV and 12' element spacing: Test PPI packer in blank pipe. Mark Settings.
- 9. MI & RU DS Services. Acidize perfs 3770-4004' with 3,600 gal 15% NEFE HCl acid\* at a maximum rate of 1 BPM and a maximum surface pressure of 4000 psi as follows:

Interval	Amt. Acid	Max Rate	PPI Setting
3994-4004'	200 gal	1 BPM	3993-4005'
3977-3987'	200 gal	1 BPM	3976-3988'
3960-3972'	200 gal	1 BPM	3959-3971'
3950-3956'	200 gal	1 BPM	3947-3959'
3938-3946'	200 gal	1 BPM	3935-3947'
3924-3934'	200 gal	1 BPM	3923-3935'
3912-3918'	200 gal	1 BPM	3911-3923'
3898-3908'	200 gal	1 BPM	3897-3909'
3884-3894'	200 gal	1 BPM	3883-3895'
3872-3880'	200 gal	1 BPM	3870-3882'
3860-3866'	200 gal	1 BPM	3856-3868'
3846-3854'	200 gal	1 BPM	3845-3857'
3833-3843'	200 gal	1 BPM	3832-3844'
3822-3824'	200 gal	1 BPM	3819-3831'
3812-3818'	200 gal	1 BPM	3809-3821'
3800-3808'	200 gal	1 BPM	3797-3809'
3781-3791'	200 gal	1 BPM	3780-3792'
3770-3774'	200 gal	1 BPM	3765-3777'

Displace acid with 8.6 PPG cut brine water -- do not over displace. Use a SCV to control displacement fluid. Record ISIP, 5 & 10 minute SIP's. RD and release DS services. Note: Pickle tubing in 1 run of 500 gals acid, prior to acidizing perfs. Pickle acid is to contain only ½ gal A264 and 1 gal W53. Also, if communication occurs during treatment of any interval, monitor casing pressure and attempt to complete stage w/o exceeding 500 psi csg pressure. If cannot, then move PPI to next setting depth and combine treatment volumes of the intervals.

* Acid system to contain:	1 GPT A264	Corrosion Inhibitor
•	8 GPT L63	Iron Control Agents
	2 PPT A179	Iron Control Aid
	20 GPT U66	Mutual Solvent
	2 GPT W53	Non-Emulsifier

- 10. Release PPI & PU to approximately 3675'. Set pkr @ 3675'. Fish SCV. Swab back all intervals together. Recover 100% of treatment and load volumes before shutting well in for night, if possible. Report recovered volumes, pressures, and/or swabbing fluid levels.
- 11. Open well. Release PPI pkr. POH w/ tbg and PPI pkr. LD PPI tool.

- 12. PU and GIH w/ 7" Arrow-Set 10k pkr & On-Off tool w/ 2.25" "F" profile and 3-1/2" EUE 8R L-80 work string, testing to 8500 psi. Set pkr at approximately 3670'. Install frac head. Pressure annulus to 500 psi to test csg and pkr. Leave pressure on csg during frac job to aid in observing communication.
- 13. MI & RU DS Services and Tracer-Tech Services (Mike Mathis (866) 595-3115). Frac well down 3 ½" tubing at **40 BPM** with 88,000 gals of YF125, 176,000 lbs. 16/30 mesh Jordan Sand, and 30,000 lbs **resin-coated** 16/30 mesh CR1630 proppant. Observe a maximum surface treating pressure of **8500 psi**. Tag frac with 2 radioactive isotopes (1 in regular sand stages, and 1 in resin-coated proppant stage). Pump job as follows:

Pump 2,000 gals 2% KCL water containing 55 gals Baker RE 4777-SCW Scale Inhibitor at 6 BPM

Pump 1,000 gals 2% KCL water spacer at 20 BPM

Pump 14,000 gals YF125 pad containing 5 GPT J451 Fluid Loss Additive at 40 BPM

Pump 14,000 gals YF125 containing 0.5 PPG 16/30 mesh Jordan Sand & 5 GPT J451 FL Additive

Pump 12,000 gals YF125 containing 1.5 PPG 16/30 mesh Jordan Sand

Pump 12,000 gals YF125 containing 2.5 PPG 16/30 mesh Jordan Sand

Pump 14,000 gals YF125 containing 3.5 PPG 16/30 mesh Jordan Sand


Pump 16,000 gals YF125 containing 4.5 PPG 16/30 mesh Jordan Sand


Pump 6,000 gals YF125 containing 5 PPG resin-coated 16/30 mesh CR1630 proppant.

Flush to 3730' with WF125. **Do not overflush.** Shut well in. Record ISIP, 5, 10, and 15 minute SI tbg pressures. SWI. RD & Release DS Services and Tracer-Tech Services. **Leave well SI overnight.** 

- 14. Open well. Bleed pressure from well, if any. Release pkr. POH LD 3 ½" work string, on-off tool, and pkr.
- 15. PU and GIH with 6 1/4" MT bit on production tubing to 4500'. If fill is tagged above 4500', cleanout to 5745' using 8.6# PPG cut brine water using air unit if necessary. POH with 2 7/8" tbg and bit. LD bit.
- 16. PU & GIH with 7" pkr on 2 7/8" tbg string to 3600'. Set pkr at 3600'. Open well. GIH and swab well until there is no sand inflow. Swab well for at least 3 hours before logging. MI & RU Baker Atlas electric line unit. Install lubricator and test to 1000 psi. GIH and conduct after-frac PRISM GR/Temp/CCL from 4300' to 3400'. POH. RD & release electric line unit. Note: Use Baker Atlas Cement Bond Log dated 6/3/2002 for depth correction.
- 17. Release pkr. POH 2-7/8" tubing and pkr.
- 18. RIH w/ 2-7/8" production tubing and hang off per ALS recommendation. NDBOP. NUWH. RIH w/ rods and pump per ALS.
- 19. RD Key PU & RU. Turn well over to production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

Engineer – Richard Jenkins 432-687-7120 Office 432-631-3281 Cell





. . . . . .