Submit 3 Copies To Appropriate District Office District Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
1625 N French Dr., 1400 NM 88240 2008 District II O 2008 OH. CONSERVATION DIVISION	WELL API NO. 30-025-32159
	5. Indicate Type of Lease STATE FEE
District III 1000 RiolBrazos Rou Azico, NM 87410 1220 South St. Francis Dr. District IV Santa Fe, NM 87505 1220 S St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name B.F. HARRISON "B"
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 18
2. Name of Operator	9. OGRID Number 4323
CHEVRON U.S.A. INC. 3. Address of Operator	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705	TEAGUE,N. GLORIETA/PADDOCK
4. Well Location	
Unit Letter D: 990 feet from the NORTH line and 660 feet from the WEST Section 9 Township 23-S Range 37-E NMPM	
Section 9 Township 23-S Range 37-E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	County LEA
3319' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	
OTHER: ADD PERFS & FRAC STIM GLORIETA OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
CHEVRON U.S.A. INC. INTENDS TO ADD PERFS & FRAC STIMULATE THE GLORIETA.	
THE INTENDED PROCEDURE & CURRENT & PROPOSED WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL	
Spud Date: Rig Release Date:	
Spud Date. Rig Release Date.	
I hereby certify that the information above is true and complete to the best of my knowledge	ge and belief.
SIGNATURE SIGNATURE REGULATORY SPE	CCIALIST DATE 11-04-2008
Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.c For State Use Only	om PHONE: 432-687-7375
PETROLEI IM ENG	NEER NOV 1 2 2008
APPROVED BY: TITLE TITLE Conditions of Approval (if any):	DATE NOV 1 2 2000

B. F. Harrison B # 18
Teague North Field
T23S, R37E, Section 9
Job: Add Perfs In Glorieta Formation And Frac

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 10/1/2008. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 3. MI & RU workover unit. Bleed pressure from well, if any. Pump down csg with 8.6 PPG cut brine water, if necessary to kill well. Remove WH. Install BOP's and test as required.
- 4. MI & RU electric line unit. GIH to top of fish inside 2 7/8" tbg at 3862'. Fire string shot and back-off 2 7/8" tbg at coupling above top of rod fish. POH with string shot. RD and release electric line unit.
- 5. POH with 2 7/8" tbg. PU & GIH with DC's, bumper jars, and accelerator jars on 2 7/8" work string to top of 2 7/8" tbg in 5 ½" casing at approximately 3862'. Screw into top of 2 7/8" tbg at approximately 3862'. Jar TAC free and POH with 2 7/8" work string and fish. LD TAC, DC's and jars.
- 6. PU and GIH with 4 3/4" MT bit and 2 7/8" work string to PBTD at 5130'. Reverse circulate well clean from 5130' using 8.6 PPG cut brine water. POH with work string and bit. LD bit.
- 7. MI & RU Gray WL electric line unit. Install lubricator and test to 1000 psi. GIH with 3 3/8" RHSC Gunslinger EXP-3325-321T casing guns (0.42" EH & 47" penetration) and perforate open-hole from 5042-46', 5080-90', and 5106-22' with 4 JSPF at 120 degree phasing, using 25 gram premium charges. POH. RD & release electric line unit. Note: Use csg collars from Schlumberger GR/CNL Log dated 5/21/00 for depth correction.
- 8. PU and GIH w/ 5 ½" 10K treating pkr & On-Off tool w/ 2.25" "F" profile and 161 jts. of 3 ½" EUE 8R L-80 work string, testing to 8500 psi. Set pkr at approximately 4900". Install frac head. Pressure annulus to 350 psi to test csg and pkr. Leave pressure on csg during frac job to observe for communication. Note: Do not exceed 350 psi casing pressure due to emt sqzd perfs in wellbore from 3896-4874".

9. MI & RU DS Services and Tracer-Tech Services (Mike Mathis (866) 595-3115). Frac well down 3 ½" tubing at 30 BPM with 55,000 gals of 50-70 Quality CO2 Foamed WF150 and 82,500 lbs. 16/30 mesh Jordan Sand. Observe a maximum surface treating pressure of 8000 psi. Tag frac with 1 radioactive isotope in all sand stages. Pump job as follows:

Pump 20,000 gals WF150 70Q Foam pad
Pump 11,000 gals WF150 50Q Foam pad containing 0.5 PPG 16/30 mesh Jordan Sand
Pump 4,000 gals WF150 50Q Foam containing 1 PPG 16/30 mesh Jordan Sand
Pump 4,000 gals WF150 50Q Foam containing 2 PPG 16/30 mesh Jordan Sand
Pump 5,000 gals WF150 50Q Foam containing 3 PPG 16/30 mesh Jordan Sand
Pump 5,000 gals WF150 50Q Foam containing 4 PPG 16/30 mesh Jordan Sand and PropNET
Pump 6,000 gals WF150 50Q Foam containing 5 PPG 16/30 mesh Jordan Sand and PropNET.

Flush to 4900' with 1,790 gals WF150. **Do not overflush.** Shut well in. Record ISIP, 5, 10, and 15 minute SI tbg pressures. SWI. RD & Release DS Services. **Leave well SI overnight. Note: DS should bring enough PropNet to location to add to all sand stage if needed for pressure reduction.**

- 10. Open well. Bleed off pressure. Pump down the with 8.6 PPG cut brine water if necessary to kill well. Release pkr and POH with 3 ½" work string. Lay down 3 ½" work string and pkr.
- 11. PU and GIH with 4 ¼" MT bit on 2 7/8" work string to COTD at 5130'. If fill is found, clean out to 5130' using 8.6 PPG cut brine water. POH with 2 7/8" work string and bit. LD bit. Note: If well will not circulate, use air unit and cleanout using foam.
- 12. PU & GIH with 5 ½" pkr on 2 7/8" tbg string to 4900'. Set pkr at 4900'. Do not swab well. MI & RU Baker Atlas electric line unit. Install lubricator and test to 1000 psi. GIH and conduct after-frac PRISM GR/Temp/CCL log from 5130' up to 4500'. POH. RD & release electric line unit. Note: Correlate logs and run flat with Schlumberger GR/CNL Log dated 5/21/00. Also, do not swab well before running PRISM Log.
- 13. MI & RU pump truck. Pump down tbg with 50 bbls 8.6 PPG cut brine water containing 110 gals Baker RE-4777 Scale Inhibitor followed by 200 bbls 8.6 PPG cut brine water at 5 BPM and 2500 psi maximum pressure. RD and release pump truck. Release pkr. POH LD 2 7/8" work string and packer.
- 14. PU and GIH w/ BP mud anchor jt of 2 7/8" tbg, 2 7/8" x 4' perforated sub, SN, 1 jt. 2 7/8" EUE 8R J-55 IPC tbg, 39 jts 2 7/8" EUE 8R J-55 tbg, TAC, and 123 jts 2 7/8" EUE 8R J-55 tbg, testing to 5000 psi. Set TAC at 3815', with EOT at 5105' and SN at 5070'.
- 15. Remove BOP's and install WH. GIH with rods, weight bars, and pump per ALS recommended design. RD & release workover unit.

16. Turn well over to production. Leave well shut in for 2 weeks after rig moves off for CO2 to soak. Put well on production. Report producing rates, choke sizes, flowing pressures and/or fluid levels.

AMH 10/21/2008



