	ent Form C-103 Revised 5-27-2004
LE IN TRIPLICATE OV 1, 7 2008 OIL CONSERVATION DIVISION	Novised 5 27 2001
ISTRICT I 1220 South St. Francis Dr. 25 N. French Dr. Hohrs, WT, 88240 Santa Fe, NM 87505 ISTRICT II Santa Fe, NM 87505	WELL API NO 30-025-26120
	5 Indicate Type of Lease
01 W Grand Ave, Artesia, NM 88210 ISTRICT III	STATE FEE FEE 6 State Oil & Gas Lease No
100 Rio Brazos Rd, Aztec, NM 87410	o state off & Gas Lease No
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	South Hobbs (G-SA) Unit Section 9
Type of Well:	8 Well No
Oil Well X Gas Well Other	125 9. OGRID No. 157984
Occidental Permian Ltd.	9. OGRID No. 157984
Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
4008 N. Grimes PMB-269, Hobbs, NM 88240 Well Location	1
	et From The West Line
	<u> </u>
Section 9 3 Township 19-S Range 38- 11. Elevation (Show whether DF, RKB, RT GR, etc.)	E NMPM County
3622' KB	
t or Below-grade Tank Application or Closure	
t Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
t Liner Thickness mil Below-Grade Tank: Volume bbls; Construction M	
2. Check Appropriate Box to Indicate Nature of Notice, Report, or	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	PNS PLUG & ABANDONMENT
ULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	
THER Return well to production X OTHER	
	s, including estimated date of starting any completion or recompletion. olds, POOH.
THER Return well to production X OTHER B. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Kill well. MIRU PU. NU BOP. Test casing for leaks RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH w/ 5-1/2" packer, RBP on workstring. Set RBP @ 4240', Packer @ 4295'. If pressure test he RIH w/ 5-1/2" CIBP, set @ 4195', cap w/ 10' sand 4185'. Tag top of sand to confirm PB, POOH RIH w/ 5-1/2" DICR, set @ 4100'. Establish injection rate into perfs in preparation for cement squesting and retainer to 4180', circulate clean. Squeeze all Grayburg perfs from 4108-76' with cement. RIH w/ 4-3/4" bit, drill out cement and retainer to 4180', circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement to the best of my knowledge and belief. I further certify that the information above is true and complete to the best of my knowledge and belief. I further certify	s, including estimated date of starting any completion or recompletion. olds, POOH. ueeze. an and POOH. SEE ATTACHED
THER Return well to production X OTHER B. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Kill well. MIRU PU. NU BOP. Test casing for leaks RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH w/ 5-1/2" packer, RBP on workstring. Set RBP @ 4240', Packer @ 4295'. If pressure test he RIH w/ 5-1/2" CIBP, set @ 4195', cap w/ 10' sand 4185'. Tag top of sand to confirm PB, POOH RIH w/ 5-1/2" DICR, set @ 4180'. Pressure test, POOH RIH w/ 5-1/2" CICR, set @ 4100'. Establish injection rate into perfs in preparation for cement squesting and retainer to 4180', circulate clean. O. Pressure test, testholds; drill out cement and retainer to 4180', circulate clean. O. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. O. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. O. Pressure test, testholds; drill out cement to 4180', cap w/ 8' sand to 4408 Wereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify nstructed or	s, including estimated date of starting any completion or recompletion. olds, POOH. ueeze. an and POOH. SEE ATTACHED
THER Return well to production X OTHER B. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Kill well. MIRU PU. NU BOP. Test casing for leaks RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH w/ 5-1/2" packer, RBP on workstring. Set RBP @ 4240', Packer @ 4295'. If pressure test he RIH w/ 5-1/2" CIBP, set @ 4195', cap w/ 10' sand 4185'. Tag top of sand to confirm PB, POOH RIH w/ 5-1/2" DICR, set @ 4100'. Establish injection rate into perfs in preparation for cement squesting and retainer to 4180', circulate clean. Squeeze all Grayburg perfs from 4108-76' with cement. RIH w/ 4-3/4" bit, drill out cement and retainer to 4180', circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement to the best of my knowledge and belief. I further certify that the information above is true and complete to the best of my knowledge and belief. I further certify	s, including estimated date of starting any completion or recompletion. olds, POOH. ueeze. an and POOH. SEE ATTACHED
THER Return well to production X OTHER B. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Kill well. MIRU PU. NU BOP. Test casing for leaks RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH w/ 5-1/2" packer, RBP on workstring. Set RBP @ 4240', Packer @ 4295'. If pressure test he RIH w/ 5-1/2" CIBP, set @ 4195', cap w/ 10' sand 4185'. Tag top of sand to confirm PB, POOH RIH w/ 5-1/2" packer set @ 4180'. Pressure test, POOH RIH w/ 5-1/2" packer set @ 4100'. Establish injection rate into perfs in preparation for cement squestion generation for cement and retainer to 4180', circulate clean. 0. Pressure test, testholds; drill out cement and retainer to 4180', circulate clean. 0. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. 0. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. 0. RIH w/ 5-1/2" CIBP, set @ 4416', cap w/ 8' sand to 4408 ereeby certify that the information above is true and complete to the best of my knowledge and belief. I further certify is nstructed or or an (attached) alternative or an (attached) alternative or an (attached) alternative or an is true and complete to the best of my knowledge and belief. I further certify is not an information above is true and complete to the best of my knowledge and belief. I further certify is nor an (attached) alternative or an is not according to N	s, including estimated date of starting any completion or recompletion.
THER Return well to production X OTHER 3. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed Kill well. MIRU PU. NU BOP. Test casing for leaks RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH with 4-3/4". Dril out CIBP, clean out well to 4300', circulate clean, POOH RIH w/ 5-1/2" packer, RBP on workstring. Set RBP @ 4240', Packer @ 4295'. If pressure test he RIH w/ 5-1/2" CIBP, set @ 4195', cap w/ 10' sand 4185'. Tag top of sand to confirm PB, POOH RIH w/ 5-1/2" CICR, set @ 4180'. Pressure test, POOH RIH w/ 5-1/2" CICR, set @ 4100'. Establish injection rate into perfs in preparation for cement squeeze all Grayburg perfs from 4108-76' with cement. RIH w/ 4-3/4" bit, drill out cement and retainer to 4180', circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. D. Pressure test, testholds; drill out cement & CIBP @ 4196' continue to CO to 4420' Circulate clean. RIH w/ 5-1/2" CIBP, set @ 4416', cap w/ 8' sand to 4408 tereby certify that the mformation above is true and complete to the best of my knowledge and belief. I further certify nstructed or or an (attached) alternative plan	s, including estimated date of starting any completion or recompletion.

۰.

- 12. RIH w/ 4-1/2" treating packer on 2-7/8" workstring, set @ 4290', Acid treat according following schedule: 20 Bbls 15% NEFE HCI acid, 500# gelled rock salt block, 20 Bbls Acid, 500# block, 20 Bbls Acid, flush acid with 50 bbls fresh water.
- 13. POOH

•

A.

- 14. RIH w/ RSP production equipment
- 15. Return well to production