Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised May 08, 2003 District 1 WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-27433 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 STATE 😠 FEE [] District 1V 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A J STATE D''C'' DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Mallon PROPOSALS.) Well No. 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator 9. OGRID Number GRUY PETROLEUM MANAGEMENT CO. ATTN: DON ALDRIDGE 3. Address of Operator 10. Pool name or Wildcat P.O. 140907, IRVING, TEXAS 75014-0907 LOVINGTON PENN NE 4. Well Location 1980 Unit Letter feet from the NORTH 1830 line and feet from the line Section 20 Township **16S** Range **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL - 3815.71 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON X **REMEDIAL WORK** ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. **PLUG AND** ABANDONMENT **PULL OR ALTER CASING MULTIPLE** CASING TEST AND COMPLETION **CEMENT JOB** OTHER: \Box OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. CRUY PETROLEUM MANAGEMENT CO. REQUESTS APPROVAL TO PLUG AND ABANDON THE SUBJECT WELL PER NMOCD SPECIFICATIONS AS PER THE ATTACHED PLUGGING PROCEDURE. IF YOU SHOULD HAVE ANY QUESTIONS OR COMMENTS PLEASE CONTACT DAVID EYLER AT 432-687-3033. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BECKINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE_ TITLE. 11/10/03 DATE_ Type or print name DAVID A. EYLER Telephone No. 432.687.3033 (This space for State use) OC DISTRICT SUPERVISOR/GENERAL MANAGER NOV 2 5 2003

TITLE

APPROVED BY

Conditions of approval, if any:

Gruy Petroleum Management Company

State "C" #4

A.P.I. #: 30-025-27433

Lease Serial #:

Field: Lovington Penn NE

Location: 1980' FNL & 1830' FEL, Unit Letter G, Sec. 20, Twp. 16S, Rge. 37E

Lea County, New Mexico

Completion Date: 1981

Total Depth:

11,544' P.B.T.D.: CIBP @ 11,103' w/35' cmt.

Casing Data:

13-3/8" 48# @ 435' w/ 425 sxs. - Cement circulated to surface.

8-5/8" 24# & 28# @ 4320' w/ 2200 sxs. – Cement circulated to surface. 5-1/2" 17# N-80 & K-55@ 11544' w/ 700 sxs. – TOC = +/- 8345' (TS)

Tubing Data:

None None

Rod Data: Open Perfs:

None

Remarks:

Perfs @ 11310'-11387' - CIBP @ 11103' w/35' cmt.

Csg. collapsed 2713'-3119' - Swedged back out (12/92)

Sqz'd csg. leaks @ 5605'-5667' (12/92)

Csg. inspection log showed various csg. problems @ 1400'-6650' (05/02)

PXA PROCEDURE

1) MIRU workover rig, PXA equipment and 11,100' workstring.

- 2) ND wellhead and NU BOP's; PU & RIH w/ tubing to top of plug @ 11068'; Circulate well w/ PXA mud; POOH laying down tbg. to 7730'; Mix & pump a 25 sx. class "H" cmt. plug @ 7730'- 7830'(Tubb); POOH laying down tbg. to 6250'; Mix & pump a 25 sx. class "H" cmt. plug @ 5550'-5750' (casing leaks); POOH w/ tbg. standing back 4400' & laying down the balance.
- 3) ND BOP's & NU casing equip.; Work stretch on 5-1/2" csg.; RUWL & csg. cutter & RIH & cut 5-1/2" casing (est. csg. recovery @ 4320'); POOH & RDWL; POOH laying down 5-1/2" casing; ND csg. equip. & NU BOP's.
- 4) RIH w/tbg. OE to 50' below csg. cut; Mix & pump a 200', 80 sx. class "H" cmt. plug 50' below csg. cut and 150' above 8-5/8" csg. shoe; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug.
- 5) POOH laying down tbg. to 2150'; Mix & pump a 35 sx. class "H" cmt. plug @ 2050'-2150'(Salt); POOH w/ laying down tbg. to 450'; Mix & pump a 35 sx. class "C" cmt. plug @ 350'-450'(Fresh water).
- 6) POOH w/ laying down tubing to 63' & mix & pump a 20 sx. cmt. surf. plug @ 3'-63'. FOOH w/ tubing.
- 7) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 8) RDMO rig and PXA equipment. Clean location.

