Submit 3 Copies To Appropriate District State of New Mexico Office <b>RECEIVED</b> State of New Mexico <u>District I</u> 1625 N Franch Dr. Hobbs, NM 88240	Form C-103 June 19, 2008
District II District II Distr	WELL API NO. 30-005-00858
1000 Rio Brazos Ed. Azistan BROOCD 1220 South St. Francis DI.	5. Indicate Type of Lease STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Rock Queen Unit
1. Type of Well: Oil Well 🔲 Gas Well 🗌 Other Injector	8. Well Number 58
2. Name of Operator CELERO ENERGY II, LP	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601 Midland, TX 79701	10. Pool name or Wildcat Caprock Queen
4. Well Location	
Unit LetterH: 1980feet from the Northline and 660Section25Township13SRange31E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM County Chaves
4392' GR	
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRIL	
	proved for plugging of well bore only.
	ability under bond is retained pending receipt C-103.(Subsequent Report of Well Plugging)
	nich may be found at OCD Web Page under rms, www.cmnrd.state.nm.us/ocd.
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: Att or recompletion.</li> </ol>	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
11/20/08 - MIRU. NU BOP. TIH w/ 3 <sup>3</sup> /4" bit & PU 6 - 3 1/8" DC & tally. PU 2 3/8" th 11/21/08 - TIH w/open ended 2 3/8" tbg 6 jts; it stopped 252'. Run 3 <sup>3</sup> /4" bit & PU 3 DC	eg; tagged @ 2950'. 's; tagged 95'. Drld down 258'. Pulled out &
it drug. Run 3 <sup>3</sup> ⁄ <sub>4</sub> " taper mill, 3 DC's; tagged @ 95', milled down to 148'. 11/24/08 - : Started milling @ 148'; milled down to 178'. TOOH w/ DC's & mill. ND E <sup>1</sup> ⁄ <sub>2</sub> " & they were stuck. Apollo shot WH & slips came free. Pulled a piece of 4 <sup>1</sup> ⁄ <sub>2</sub> & 2 <sup>1</sup> ⁄ <sub>2</sub>	its. of 4 <sup>1</sup> / <sub>2</sub> " csg that was parted. TIH w/
mule shoe jt. & tbg. Tag @ 93', milled down to 210'. TOH w/ tbg, DC's & mill. TIH w/ & it went to 670' but went outside 4 1/2" csg. TOH w/ tbg. Run 7 7/8" impression block,	Mule shoe jt & 2 $3/8$ " tbg, tag @ 178', turn it no impression.
11/25/08 - TIH w/ 6"guide shoe & 3 jts. of 6" wash pipe, tag @ 93', turn it to get over 4 TOH w/ 6" wash pipe & guide shoe. TIH w/ cutrite shoe & 6" wash pipe & tag @ 118', p	2" csg & got down to 118' and stopped
pipe & shoe and recovered 1 - 6' piece & 1 - 4' piece of csg.	
12/1/08 - Broke off swivel & RU Apollo Wireline to run expo's camera. Run camera do 2 jts of 6" washpipe. Run camera again down to 91'. Looks like fish came up hole. Pull camera down to top of fish @ 88' & it was 7' long. Pulled out. TIH w/shear w/4.010 gra	ed out camera. Pulled 6" washpipe out. Run
anything. *Continued on back of page.	· · · · · · · · · · · · · · · · ·
Spud Date: Rig Release Date:	. * 4. · ·
Therefore a state of the state	·
I hereby certify that the information above is true and complete to the best of my knowledge	
SIGNATURE TIAN HUN TITLE Regulatory Analyst	DATE_12/16/2008
Type or print name Lisa Hunt E-mail address: LHunt@celeroene For State Use Only	PHONE: (432)686-1883
CLUSTINGT SUPERVISOR/GENE	DATE DEC 2 2 2008
APPROVED BY:	DATEOU8
commone of reproval (wairy).	

## Rock Oueen Unit #58 – Continued

12/2/08 - TIH w/spear w/6" grapple on it; went down to 120' & came back out. Didn't have anything. TIH w/camera & piece of 4 1/2" was still @ 82'; came out. TIH w/.7 5/8" shoe, one jt of 7 5/8" WP, XO to 6" washpipe; tagged top of 4 1/2" csg @ 124'. Run camera in & look @ top of 4 1/2; came out w/camera. Milled down to 144'. TOH w/ 6" & 7 5/8" & shoe, had piece of 4 1/2" 18'long. Run camera down 126' to top of 4 1/2". The 8 5/8" csg looks good. POOH w/camera.

12/3/08 - TIH w/6" shoe & 6" washpipe; tagged 4 1/2" csg @ 126'. Turn it, got over 4 1/2" csg & went down to 149'. Run inside 6" w/4 ½" spear & tbg; tagged @ 126'. Work it, got in 4 ½", got hold of 4 ½" & pulled 10 pts. Set down, pick up came loose. TOH w/tbg & spear & had 23.4' piece of 4 1/2". Tried to run 6" on down. Tagged @ 149'. RU swivel & milled to 153', fell out, run on down to 232' & stopped. PU 2'.- TIH w/tapered mill & 4 - 3 1/8" DC & one it of 2 3/8" tbg; tagged @ 149'.

12/4/08 - Started milling. After 5 mins, fell in & went down to 176'. Mill 45 mins, didn't make any hole. TOH w/tbg & mill had 68.4' of 4 ½ csg. LD. Tried to run 6" on down; would go. TIH w/spear & tbg down to 176'; didn't feel anything. TOH w/tbg & spear had 31.22' it of 4 1/2" csg. LD. Pulled 6" washpipe out; took off shoe. Got welder to cut off cutrite & put a cutlip on shoe. TIH w/shoe & 6" washpipe; tagged (a) 235'. Turn it, got over  $4 \frac{1}{2}$ " & run down to 266'.

12/5/08 - Run 1 more jt of 6" wash pipe, x-over & 1 jt of 4 1/2" csg. Landed @ 322'. TIH w/2 3/8" tbg to 238'; it stopped, turned it, wouldn't go & pulled out. TIH w3 ¼" tapered mill, 1 - 3 1/8" DC & tbg to 238'. Dressed off 4 ½" csg, went down to 497'; pulled out. TIH w/4 1/2" AD-1 pkr & tbg to 238'; it stopped, worked it, turned it, wouldn't go, came out. We had backed off safety collar. Pulled & LD 1 it 4 1/2" csg. TIH w/new safety collar & tbg got on pkr. Pulled tbg & pkr. Run jt of 4 1/2" csg pack off, installed WH & BOP. TIH w/open ended 2 3/8" tbg down to 2950'. RU Superior & spotted cmt plug. Pumped 12 bbls of class C w/2% CACL & 9 bbls FW. Pulled 17 stands of 2 3/8" tbg.

12/8/08 - Run in tagged cmt @ 2913'. Called OCD & they said that was good. TOH w/tbg. RU Apollo & went in to 2300' & perf'd. Well started flowing. RD Apollo. Well flowed 290 bbls of wtr back & then died. TIH w/tbg to 2200'. Spotted 65 sx cmt plug w2%' CACLI & 4 bbls F.W. Pulled up to 1200'. Closed csg & braden head. Pumped 15 bbls of water. No pressure @ 3 bbls bpm. The second second states and the I have a state of the me

12/9/08 - TP.100 & csg 100. Bled off. Run tbg 2' @ 1203'; tagged cmt. TOH w/tbg. Closed BOP. Left well flowing to pit 8 hrs. Flowed 109 bbls wtr. Flowed 10 bbls per hour.

## 

12/10/08 - Well flowed over night, 50 bbls water & quit. TIH w/3 <sup>3</sup>/<sub>4</sub>" tapered mill & 4 – 3 1/8" DC & tbg; tagged @ 230'. Dressed off top of 4 1/2" csg. TOH w/tbg, DC & mill. TIH w/ 3 3/4" bit, 4 - 3 1/8" DC & tbg;tagged top of 4 1/2" @ 230". Turned it & didn't go. TOH w/tbg, DC & bit. TIH w/3 <sup>3</sup>/<sub>4</sub>" tapered mill, 4 – 3 1/8" DC & tbg. Dress off top of 4 <sup>1</sup>/<sub>2</sub>" csg. TOH w/tbg, DC & mill. TIH w/3 3/4" bit, 4 - 3 1/8" DC & tbg; tagged top of 4 1/2" csg @ 230'. Turned it & went in. Run tbg down to 1203'. Tagged cmt. Drld 6" fell out; went to 2300'. Didn't hit anything. TOH w/tbg. LD DC & bit. TIH w/ 4' of 2 3/8" sub, 3 3/4" AD-1 pkr & tbg down to 2009'. Set pkr. RU Superior to pump cmt. Pump 5 bbls wtr to see if we could pump into form. Pumped tbg 28.6 bbls class C cmt w/2% CACL 2# of sand per sx of cmt. 1.5 bpm TP 0 & 10.2 bbls FW. Last 5 bbls had 60# psi. ISIP 60#.

12/11/08 - Went down tagged cmt @ 2190'. TOH w/tbg & pkr. RU Apollo to perf. RIH stopped @ 730'. Worked it & wouldn't go. Pulled perf gun out of hole. TIH w/3 <sup>3</sup>/<sub>4</sub>" tapered mill, 1 - 3 1/8" DC & tbg down to 730'. Milled up & down from 730' to 750'; came out. RIH w/ perf gun stopped @ 743'. TOH w/perf gun. TIH w/3 3/4" tapered mill, 3 3/4" string mill, 1;-3 1/8" DC & tbg to 743'. Worked up & down from 735 to 750'; 5 times; cleaned it up. TOH w/tbg, DC & mills. RIH w/perf gun; stopped @ 743'. TOH w/perf gun. Called to get smaller guns. TIH w/ 3 ¼ tapered mill, 3 ¼" string mill, 1 – 3 1/8" DC & tbg to 735'. Milled up & down from 735' to 750'; 5 times; cleaned up. TOH w/tbg, DC & mills. Perf guns arrived. RIH w/2" perf gun, stopped @ 743'. TOH w/perf gun. TIH w/tbg down to 1274'. RIH w/tbg gun down to 943; stopped. TOH w/tbg gun. RU sinker bar on rig. TIH tagged @ 943' but went down slow to 1250'. TOH w/sinker bar, circulated well for about 30 mins. Cleaned it up, got paraffin & red bed back. TIH w/tbg gun & perf @ 1530'. TOH w/gun. RD Apollo. RIH w/tbg to 1544'. RU Superior to pump cmt plug. Pumped 50 sx Class C 12 bbls, 2 bpm, TP 500# density 14.8 & 6 bbls FW, TP 650, 2 bpm. Circ up the 8 5/8", ISIP 350. Bleed off. Pulled tbg out of hole.

12/12/08 - RIH tagged cmt @ 772'. Pulled up to 350'. RU Diamondback to cmt well. Pumped 100 sx Class C w/2% CACL. Pumped 100 sx Class C 25 bbls 2 bpm TP 300. Circ to surface. Pulled tbg, LD, ND BOP. Took off braden head & filled csg up to TOC. RD Diamondback. RD rig. Install surface marker. Clean & clear location. Pumped 60 sx @ 2900'. Pumped 60 sx @ 2300'. Pumped 50 sx @ 1530'. Pumped 100 sx @ 350'. Pumped 10 sx @ surface.

	CELERO E		
FIELD: LEASE/UNIT: COUNTY:	Caprock Rock Queen Chaves	DATE: Dec. 16, 2008 BY: GSA WELL: 58 STATE: New Mexico	
SPUD: 1/56 COME	S: P&A'd Injector (12-08) : W. M. Tulk #8	KB = 4392' GL = API = 30-005-00858	
	Filled casing with 10 sx cen Spotted 100 sx cement plug 8-5/8" 24# @ 297' cmt'd. w/ 175 sx (circ 30 sx) Top of 4 1/2" casing @ 235' +/ at the beginning of the plugging	from 350' to surface.	
	Perforated holes @ 1530' and p	umped 50 sx cement (TOC @ 772').	
	÷.,		· .
		· · · · · · · · · · · · · · · · · · ·	
	Perforated holes @ 2390' and p	umped 60 sx and then 120 sx cement (TOC @ 2190').	
	TOC @ 2670' (calc)		
	Spotted 60 sx cmt plug @ 2950 4-1/2'' 9.5# @ 3058'	'. Tagged TOC @ 2913'.	
	<b>cmt'd. w/ 75 sx (DNC)</b> <u>Top of Queen @ 3058':</u> <b>Queen Open Hole:</b> 3058' - 30	76' (1-56)	
PBTD - 3076 TD - 3076			
	12/16/200	08 RQU #58	3

•

•