Submit 3 Copies To Appropriate DESTECEIVED State of New Mexico Office District 1	Form C-1 May 27, 20	
1625 N. French Dr , Hobbs, NM 88240	WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W Grand Ave, Artesia, NM 88210 DEC 23 2008 DEC CONSERVATION DIVISION	30-025-27904	
1301 W Grand Ave , Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87000000000000000000000000000000000000	5. Indicate Type of Lease STATE X FEE	
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S St Francis Dr., Santa Fe, NM 87505	LG 718	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Brent US State	
1. Type of Well: Oil Well \mathbf{X} Gas Well \square Other	8. Well Number \checkmark	
2. Name of Operator Lime Rock Resources A, L.P.	9. OGRID Number 255333	
3. Address of Operator	10. Pool name or Wildcat	
Heritage Plaza, 1111 Bagby St. Suite 4600, Houston, TX 77002	Sandhills Grbg-SA	
4. Well Location	1	
Unit Letter <u>K</u> : <u>1,650</u> feet from the South line and <u>1,650</u>	_feet from the West line	
Section 32 Township 20 South Range 39 East N	MPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.		
3,553' GR		
Pit or Below-grade Tank Application 🗌 or Closure 🗌		
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDi	stance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice	Report on Other Data	
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DF		
PULL OR ALTER CASING Imultiple compl Imultiple compl Casing/cement OTHER: Imultiple compl OTHER: Imultiple compl Imultiple compl	[
	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008:	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8	NT JOB [] nd give pertinent dates, including estimated Attach wellbore diagram of proposed comple 35 sxs cement on top of CIBP. POOH to to pump into holes. Call Mark Whitaker	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable DCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8 and circulate 15 sxs cement back to surface.	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 80 and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location.	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8' and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. Appriliable VELU IS P&A'd	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8' and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. Appriliable VELU IS P&A'd	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8/and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. MELL IS P&A'd.	NT JOB	
OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 8' and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. Appriliable VELU IS P&A'd	NT JOB	
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 80 and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. MELL IS P&A'd. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	NT JOB	
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 80 and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. WELL IS P&A'd. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □ SIGNATURE	NT JOB	
OTHER: □ OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 1103. For Multiple Completions: A or recompletion. 12/09/2008: MIRU. ND wellhead and NU BOP's. 12/10/2008: Pull rods and pump. POOH with tubing. 12/11/2008: RIH & set CIBP @ 4,250'. POOH. RIH with tubing & circulate hole with mud. Spot 1,696' & spot 25 sxs cement. POOH. WOC. 12/12/2008: RIH & tag cement @ 1,545'. POOH. RIH & perf @ 1,230'. RIH with packer. Unable OCD. POOH. RIH & spot 25 sxs cement @ 1,280'. POOH & WOC. RIH & perf @ 80 and circulate 15 sxs cement back to surface. 12/13/2008: RD. Cut off wellhead. Cut off anchors. Level & clean up location. MELL IS P&A'd. I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed or closed according to NMOCD guidelines □, a general permit □	NT JOB	

.

APPROVED	BY:	- 7 (am
APPROVED Conditions of	f Appr	oval (i	if any

