

## RECEIVED

State of New Mexico

Energy, Minerals and Natural Resources Department

Form C-103

FILE IN TRIPLICATE  JAN 0.5 7009  OIL CONSERVATION DIVISION	Revised 5-27-2004
DISTRICT I 1625 N. French Dr., Hobbs, NI HOBBSOCD 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-07544
DISTRICT II	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III	6. State Otl & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	Section 33
1. Type of Well:	8. Well No. 131
Oil Well X Gas Well Other	
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	10. Pool name or Wildcat Hobbs (G/SA)
3. Address of Operator	10. Foot name of windcat Hoods (G/SA)
1017 W. Stanolind Rd., Hobbs, NM 88240	
5,00	et From The West Line
Unit Letter L : 2310 Feet From The North 330 Feet	tr From The West Line
Section 33 Township 18-S Range 38-	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3635' DF	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mɪl Below-Grade Tank: Volume bbls; Construction Ma	terrai
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Company of the	
	Other Data SEQUENT REPORT OF:
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:  ALTERING CASING
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF:  ALTERING CASING  PLUG & ABANDONMENT
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	SEQUENT REPORT OF:  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Plug bar  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	SEQUENT REPORT OF:  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  T including estimated date of starting any
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU	SEQUENT REPORT OF:  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  T including estimated date of starting any
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG  3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING	SEQUENT REPORT OF:  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  T including estimated date of starting any
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG  3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING  4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815'	SEQUENT REPORT OF:  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  T including estimated date of starting any
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG  3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING  4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815'  5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  , including estimated date of starting any completion or recompletion.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: OTHER: Plug bar  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG  3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING  4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815'  5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG  6. SCAN 124 JTS 2 7/8" TBG OUT – YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TOP  TO SUBSTITUTE OF THE SUBSTITUTE OF TO 3815'  TO SUBSTITUTE OF THE SUBSTITUTE OF THE SUBSTITUTE OF TO 3815'  TO SUBSTITUTE OF THE SUBSTITUT	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  , including estimated date of starting any completion or recompletion.
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG  3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING  4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815'  5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG  6. SCAN 124 JTS 2 7/8" TBG OUT – YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TO RIH W/5" CIBP, SET CIBP @ 4187'	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  In including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER:  OTHER: Plug ban  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU  2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING  4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815'  5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG  6. SCAN 124 JTS 2 7/8" TBG OUT – YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TO RIH W/5" CIBP, SET CIBP @ 4187'  8. RIH W/PKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000#	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  In including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: OTHER: Plug bas 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP 1/4 BBLS WHILE PULLING 4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815' 5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG 6. SCAN 124 JTS 2 7/8" TBG OUT – YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TO RIH W/5" CIBP, SET CIBP @ 4187' 8. RIH W/PKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000# 9. SET PKR 1014', ACIDIZE, ROCK SALT BLOCK, RD HALLIBURTON 10. PMP 100 BBLS SCALE SQZ, FLUSH W/ 200 BBLS FW	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  In including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  CHANGE PLANS  COMMENCE DRILLING OP PULL OR ALTER CASING  Multiple Completion  CASING TEST AND CEMEN OTHER:  OTHER:  Plug bas  13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertunent dates proposed work) SEE  RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the proposed of t	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Sk/acid treat  In including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Plug bar  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed.  1. RU PU 2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING 4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815' 5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG 6. SCAN 124 JTS 2 7/8" TBG OUT - YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TOP TO 1000# 187.  7. RIH W/5" CIBP, SET CIBP @ 48187' 8. RIH W/PKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000# 10. PMP 100 BBLS SCALE SQZ, FLUSH W/ 200 BBLS FW 11. PMP 35 BBLS 10# BRINE DWN TBG TO KILL WELL  ***SEE ATTACHED***	ALTERING CASING  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Ek/acid treat  It is including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS  HELD, RELEASE PKR, MORE TO 4014'
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Plug bas  13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertunent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ¼ BBLS WHILE PULLING 4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815' 5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG 6. SCAN 124 JTS 2 7/8" TBG OUT - YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TO RIH W/5" CIBP, SET CIBP @ 4187' 8. RIH W/FKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000# 9. SET PKR 1014', ACIDIZE, ROCK SALT BLOCK, RD HALLIBURTON 10. PMP 100 BBLS SCALE SQZ, FLUSH W/ 200 BBLS FW 11. PMP 35 BBLS 10# BRINE DWN TBG TO KILL WELL  ***SEE ATTACHED***  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	ALTERING CASING  ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Ek/acid treat  It is including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS  HELD, RELEASE PKR, MORE TO 4014'
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Plug bar  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed.  1. RU PU 2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING 4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815' 5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG 6. SCAN 124 JTS 2 7/8" TBG OUT - YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TOP TO 1000# 187.  7. RIH W/5" CIBP, SET CIBP @ 48187' 8. RIH W/PKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000# 10. PMP 100 BBLS SCALE SQZ, FLUSH W/ 200 BBLS FW 11. PMP 35 BBLS 10# BRINE DWN TBG TO KILL WELL  ***SEE ATTACHED***	ALTERING CASING  NS. PLUG & ABANDONMENT  IT JOB  Ek/acid treat  Including estimated date of starting any completion or recompletion.  HAN 40, RD TESTERS  HELD, RELEASE PKR, MORE TO 4014'  that any pit or below-grade tank has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Plug bar 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. HAD 250# ON TBG & CSG. PUMP 25 BBLS 10# BRINE DWN TBG & 60 BBLS DWN CSG 3. POOH W/ 125 JTS 2 7/8" TBG & ESP EQUIP, PMP ½ BBLS WHILE PULLING 4. RIH ON TBG TO 4200'. PULL ABOVE LINER TOP TO 3815' 5. 300# ON TBG & CSG. PMP 25 BBLS 10# DWN TBG & 60 BBLS DWN CSG 6. SCAN 124 JTS 2 7/8" TBG OUT – YELLOW 37, BLUE 77, GREEN 10, RED 0, GREEN LES TOP TO 1000 A 187' 8. RIH W/5" CIBP, SET CIBP @ 4187' 8. RIH W/5" CIBP, SET CIBP @ 4187' 8. RIH W/PKR ON TBG, TAG CIBP @ 4817', PICKED UP PKR TO 4180, TEST CIBP TO 1000# 9. SET PKR 1014', ACIDIZE, ROCK SALT BLOCK, RD HALLIBURTON 10. PMP 100 BBLS SCALE SQZ, FLUSH W/ 200 BBLS FW 11. PMP 35 BBLS 10# BRINE DWN TBG TO KILL WELL ***SEE ATTACHED***  I hereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING    ALTERING CASING       NS.

For State Use Only

TITLE THE ENGINEER DATE JAN 0 6 2009



- 13. RIH W/ ESP EQUIP AND 124 JTS TBG, INTAKE @ 3868', BOTTOM MOTOR @ 3903'
- 14. INSTALL PENETRATOR
- 15. RD PU AND REV UNIT

RU PU 11/11/08 RD PU 11/13/08