Submit 3 Copies To Appropriate District State of New M Office Epergy, Minerals and Nat	
1625 N French Dr. Hobbs NN Start File File	WELL API NO.
$\frac{\text{District II}}{1201 \text{ W}_{\odot}}$ 14 14 19 19 19 19 10 $\times$ OIL CONSERVATION	N DIVISION 30-025-35497 5. Indicate Type of Lease
District III JAN 0 2 2008 1220 South St. Fra	TUBESOCO STATE FEE
District IV Salita PC, INVI 6	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa F. OBBSOCD 87505	
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PI DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F	LUG BACK TO A TEXACO STATE 5
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	1
2. Name of Operator	9. OGRID Number
Devon Energy Production Company, LP	6137
<ol> <li>Address of Operator</li> <li>North Broadway, Suite 1500, Oklahoma City, Oklahoma 73102</li> </ol>	10. Pool name or Wildcat Vacuum; Atoka-Morrow, N.
4. Well Location	
Unit Letter P : 660' feet from the South line and 660' feet from the East line	
	nge 35E Lea County
11. Elevation (Show whether Di	
3987' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING DULTIPLE COMPLETION	CASING TEST AND
	OTHER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. MIRU. POOH w/ rod string, pump, and 2-3/8" production tubing.	
2. TIH and set CIBP @ 12,140'. Dump 35' cement on top. Circulate wellbore w/10 ppg mud.	
3. Spot 25 sx cement @ 9,990'. Calc TOC at 9,737' (top of Wolfcamp 4. Cut 5. $1/2$ '' series of $(2)/2$ and POOL w(series - Spot 20 m)	
4. Cut 5-1/2" casing off @ +/- 6,900' and POOH w/casing. Spot 30 sx cement @ 6,950. WOC and tag. Calc TOC @ 6,852' 5. Spot 30 sx cement @4,764. WOC and tag. Calc TOC at 4,648'	
6. Spot 30 sx cement @ 3,150'. Calc TOC at 3,150' (base of salt @ 3,150')	
7. Spot 30 sx cement @ 2,020'. Calc TOC at 1,904' (top of salt @ 2,020') 8. Spot 30 sc cement @ 430' - 540'. WOC & Tag.	
9. Spot 30 sx surface plug from 110' to surface.	
10. Cut wellhead off, set dry hole marker, clean location.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE: Eng	ineering Intern DATE_12/30/08_
Type or print name Kris Glasser E-mail address: kris.glasse	r@dvn.com Telephone No. 405-552-8011
(This space for State use)	
APPPROVED BY CAME HILL TITLE DATE AN 1 2 2009	
Conditions of approval if any 4	
Conditions of Approval: the operator	
shall give 24 hour notice the the appropriate District office before work begins.	



