	E
Submit 3 Copies To Appropriate District State of New Mex Office District I RECEIVED Interals and Natura	ico Form C-103 Il Resources June 19, 2008
1625 N. French Dr., Hobbs, NM 87240	WELL AFTINO.
District II 1301 W Grand Ave., Artesia, NM 883AN 2 8 2149 CONSERVATION District III	DIVISION 5. Indicate Type of Lease
District III 1220 South St. Fran 1000 Rio Brazos Rd., Aztec, NM §741AppsonCD Santa Fe, NM 875	505 STATE X FEE
District IV <b>HODDSOOD</b> 1220 S. St. Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELL	S 7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) PROPOSALS.)	R PLUG BACK TO A   Funice Monument South Unit
1. Type of Well: Oil Well X Gas Well Other	8. Well Number 609
2. Name of Operator	9. OGRID Number
XTO Energy, Inc.	005380 10. Pool name or Wildcat
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	Eunice Monument: Grayburg-San Andres
4. Well Location Lot 12	
Unit Letter D feet from the South line and feet from the FWL line	
Section 4 Township 21S R	ange 36E NMPM County Lea
11. Elevation (Show whether D	R, RKB, RT, GR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
	χ.
	· · · · · · · · · · · · · · · · · · ·
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>	
1. MIRU PU. MI & rack 2-7/8" N-80 WS. POOH w/rods & pmp. ND WH. NU BOP. MIRU. POOH & scanalog tubing out	
of hole.	
<ol> <li>RIH w/4-3/4" bit &amp; scraper on 2-7/8" WS to 3849'</li> <li>WS. Set packer @ 3590'. RU &amp; pressure test TCA to</li> </ol>	. POOH. PU & RIH w/5-1/2" treating packer on 2-7/8"
WS. Set packer & SSSU. No & pressure test for a	, 300 parg.
Continue on next nore	
Continue on next page.	
Spud Date: Rig Releas	e Date:
I hereby certify that the information above is true and complete to the b	post of my knowledge and helief
Thereby certify that the information above is the and complete to the t	isst of my knowledge and benef.
SIGNATURE Juny Ward TITLE Regulatory Analyst DATE 01-21-09	
Type or print name Kristy Ward E-ma	kristy_ward@xtoenergy.com il address:PHONE_432-620-6740
For State Use Only DISTRICT 1 SUPERVISOR JAN 3 0 2009	
APPROVED BY COM TITLE DATE	
Conditions of Approval (if any):	

DCD



- 3. MIRU acid co. Test lines to 4000 psig. Treat the isolated interval with **4,000 gals of 20% NEFE 90/10** in 4 stages while dropping rock salt for block between each stage. Use the following pump schedule:
  - a. EIR with water
  - b. 500 gals acid
  - c. 200 # rock salt in 4 bbls 9# brine
  - d. 1000 gals acid
  - e. 500 # rock salt in 10 bbls 9# brine
  - f. 1000 gals acid
  - g. 750 # rock salt in 15 bbls 9# brine
  - h. 1500 gals acid
  - i. Over-flush with 15 bbls water
  - [Total of 4000 gals of 20% 90/10 Acid and 1450# rock salt (order out 2000#)]
- 4. RDMO.
- 5. Flow back or RU swab and swab back acid load. If decision is made to chemically squeeze well, continue. If not, skip to step #9.
- 6. MIRU PU company.
- 7. Squeeze perfs with scale inhibitor down tubing in 4 stages dropping rock salt for block between each stage. Start with 200# block and adjust as necessary. Treatment should be designed assuming 500 bfpd total rate. Flush.
- 8. RDMO.
- 9. POOH and LD packer and 2-7/8" workstring. RIH with production tubing.
- 10. ND BOP. NU WH. RIH with rods and pump. Production equipment should be designed for 600 bfpd or better estimate based on swab results. RWTP. RDMO PU.

## CURRENT WELLBORE DIAGRAM

