Submit 3 Copies To Appropriate District	State of New Me		Form C-103
Office District I	Energy, Minerals and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.
District.II 1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION		30-025-35567
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 8	7505	STATE 🗷 FEE 🗋
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.
OUNDDY NOTIO			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: STATE A A/C 2
1. Type of We"			8. Well Number
Oil Well 🛴 Gas Well 🌃	Other		080 🗸
2. Name of Operator			9. OGRID Number
PETROHAWK OPERATING COMPAN	<u>Y</u>		194849
3. Address of Operator			10. Pool name or Wildcat
1000 LOUISIANA, STE 5600, HOUSTON, TX 77002			JAIMAT TANSILL YATES 7 RVRS (pro gas)
4. Well Location			
Unit Letter F	1980 feet from the NO	RIH line and	1980 feet from the WEST line
Section 11 Township 22S Range 36E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GR 3546			
Pit or Below-grade Tank Application or Closure			
Pit type Depth to Groundwater _	Distance from nearest fres	h water well Dis	tance from néarest surface wâter
Pit Liner Thickness: mil	Below-Grade Tank: Volume.	bbls; Construction	on Material
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING		1	SEQUENT REPORT OF: ALTERING CASING
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Please see attached Proced	ure with Wellbore Schemat	ics.	FEB 0 2 2009
The Oil Concentation	n Division Must be notified		
	ne beginning of plugging ope		HOBBSOCD
24 110410 prior to	10 2 2g// 13 5 F 12 3g// 13 6 F 0	. data i i	
		• ′	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been all be constructed or closed according to NMOCD guidelines. , a general permit or an (attached) alternative OCD-approved plan			
SIGNATURE AND LAND	TIT		Consultant DATE 02/02/2009
Type or print name EDDIE SEAY	E-n	nail address:	seay04@leaco.net Telephone No. 505–390–2454
For State Use Only	Maion Marow	میں کی	- 1 - 1
APPROVED BY	TIT	LE MAG	DATE <u>2/3/2009</u>
Conditions of Approval, if any:	V		, ,

COMPLIANCE OFFICER

Petrohawk Operating Company

State A A/C -2 Well # 80
Jalmat Field
Sec 11F, T 22S, R 36E
Lea County, New Mexico

Plug & Abandonment Procedure:

- 1. MIRU Plugging Rig. ND wellhead. NU BOPS.
- 2. PU 2 3/8" work string and TIH w/ open ended tubing to CIBP located at 2880'. Load hole with 10 ppg gelled brine.
- 3. Mix and spot 300' (34 sks Class "C") cement plug on top of CIBP from 2880' 2580'.
- 4. Perforate 5 ½" casing at 1750'. Mix and pump 200' (52 sks Class "C") cement plug through perfs at 1750' leaving top of cement inside the 5½" casing at 1550'. WOC and tag top of plug to verify depth. SPOT 255x5 OR 100' CMT (WHICH EVER IS GREATER) depth. SPOT 255x5 OR 100' STAG, SHOE PLUG.

 5. Perforate 5½" casing at 350'. Mix surface cement plug (95 sks
- 5. Perforate 5 ½" casing at 350'. Mix surface cement plug (95 sks Class "C") and squeeze through perfs at 350' attempting to circulate cement to surface. Leave top of cement inside casing at the surface.
- 6. Cutoff wellhead, cap well and install P&A marker.
- 7. Clean location for OCD inspection.

01/29/2009

