

Submit 3 Copies To Appropriate District State of New Mexico Office No. 1 April 19 10 10 10 10 10 10 10 10 10 10 10 10 10	Form C-103 Assources May 27, 2004	
District I Energy, Minerals and Natural Re 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District III 1301 W Grand Ave, Anglia (MASA) 2008 OIL CONSERVATION DIV	ISION 30-025-38638 5. Indicate Type of Lease	
District 1 1220 South St. 1 Tanels 1	STATE X FEE	
1220 S St Francis Dr , Santa Fe, NM	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BA DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 456	
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323	
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705	10. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES	
4. Well Location		
Unit Letter F: 1360 feet from the NORTH line and 1980 feet from the WEST line		
Section 36 Township 17-S Range 34-E 11. Elevation (Show whether DR, RKB)	NMPM County LEA	
4003'	All, GR, etc.)	
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit type ☐ Depth to Groundwater ☐ Distance from nearest fresh water w	ell Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data	
	SUBSEQUENT REPORT OF:	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REM	MEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	MMENCE DRILLING OPNS. □ P AND A □	
PULL OR ALTER CASING MULTIPLE COMPL CAS	SING/CEMENT JOB	
	IER: NEW WELL COMPLETION	
13. Describe proposed or completed operations. (Clearly state all pertin of starting any proposed work). SEE RULE 1103. For Multiple Control of Section 2015.		
or recompletion.	or recompletion.	
07-28-08: MIRU. TIH W/GA RING TO 4900. TIH W/CCL/GR/CBL 4904-1904. PERF 4767-74, 4778-82, 4740-48, 4755-64, 4712-20,		
	1904. PERF 4767-74, 4778-82, 4740-48, 4755-64, 4712-20,	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40,	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 6 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 6 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDI	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG e @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8".	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN.	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 1 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 1 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H CIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 1 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H CIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 1 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'.	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H CIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE 11-08-08: ON 24 HR OPT. INJECTING 137 MCF CO2 @ 1743 PSI.	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 0 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'. S. GOOD. RIG DOWN. FINAL REPORT my knowledge and belief. I further certify that any pit or below-	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H CIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE 11-08-08: ON 24 HR OPT. INJECTING 137 MCF CO2 @ 1743 PSI.	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG e @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'. S. GOOD. RIG DOWN. FINAL REPORT my knowledge and belief. I further certify that any pit or belowneral permit or an (attached) alternative OCD-approved plan	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDE 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T H CIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE 11-08-08: ON 24 HR OPT. INJECTING 137 MCF CO2 @ 1743 PSI.	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 0 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'. S. GOOD. RIG DOWN. FINAL REPORT my knowledge and belief. I further certify that any pit or below-	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDD 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T HCIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE 11-08-08: ON 24 HR OPT. INJECTING 137 MCF CO2 @ 1743 PSI. I hereby certify that the information above is true and complete to the best of grade tank has been will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE Regular Type or print name Denise Pinkerton E-mail address: leakejd@chevron.ce For State Use Only	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 1 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 1 S00# GOOD. RU SWAB. 08-05-08: SWAB. RIG 2 B. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'. S. GOOD. RIG DOWN. FINAL REPORT The symmetry of an (attached) alternative OCD-approved plan or approved plan	
4722-32, 4684-91, 4695-4708, 4656-60, 4666-74. 07-29-08: ACIDIZE PERFS 4656-4782 W/8000 GALS 15% HCL. SET CIE ACIDIZE PERFS 4596-4634 W/3500 GALS 15% HCL. 07-30-08: SET CIE 4408-12, 4400-4405, 4388-96, 4363-66. ACIDIZE PERFS 4363-4478 W/450 TO TAG @ 4518. TIH W/BIT TO 2492. 08-01-08: DRILL OUT CP PLUC TIH W/TBG TO 2497. 08-04-08: SET PKR @ 4300. CHART & TEST TO DOWN. 09-15-08: CONVERSION TO INJECTION: MIRU. OPEN UP BACKSIDD 09-17-08: LATCH ONTO PKR. TEST TO 500 PSI. BACKSIDE DIDN'T HCIRC PKR FLUID. 09-19-08: CHART CSG TO 500 PSI FOR 30 MINUTE 11-08-08: ON 24 HR OPT. INJECTING 137 MCF CO2 @ 1743 PSI. I hereby certify that the information above is true and complete to the best of grade tank has been will be constructed or closed according to NMOCD guidelines , a get SIGNATURE TITLE Regular Type or print name Denise Pinkerton E-mail address: leakejd@chevron.ce For State Use Only	P @ 4650. PERF 4628-34, 4612-16, 4604-06, 4596-4606. BP @ 4520. PERF 4468-74, 4458-60, 4454-56, 4437-40, 0 GALS 15% HCL. 07-31-08: WELL ON VAC. PU TBG 0 @ 4520 & 4650. WASH OUT FRAC BALLS TO 4920. 500# GOOD. RU SWAB. 08-05-08: SWAB. RIG E. 325 PSI. 09-16-08: CHANGE OVER TOOL TO 2 3/8". OLD. 09-18-09: TIH W/PKR & TBG. SET PKR 4302'. S. GOOD. RIG DOWN. FINAL REPORT The property of the control	



Central Vacuum Cry = 450 Section 36 The Sipilo Range. APET 30-095-36-86



DATE 9/19/08
WELL NAME QUO #456
WELL NAME QUO #456
SUPERVISOR GUA A
PACKER TYPE DISSURT IX 10K
PACKER SETTING DEPTH 4302
PACKER SETTING DEPTH 4302
PERFORATIONS 4363' 4782' 11

7