Submit 3. Copies To Appropriate District State of New 1			Form C-103
Office District I 1625 N French Dr., Hobbs, NM 87240	ntural Resources	AND A ADLAND	June 19, 2008
	ON DIVIGION	WELL API NO. 30-025-046	504
1301 W. Grand Ave., Artesia, NM 88210 First 2 / 36200 Garatte CA T	ON DIVISION Grancis Dr	5. Indicate Type of Le	1
District III 1000 Rio Brazos Rd, Aztec, NM 87410 District IV 1000 Rio Brazos Rd, Aztec, NM 87410 District IV		STATE X	FEE 🗆 🖊
District IV 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lea	ase No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Eunice Monument So	
1. Type of Well: Oil Well X Gas Well Other		8. Well Number 306	
2. Name of Operator		9. OGRID Number	
XTO Energy, Inc.		005380 V	
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701		10. Pool name or Wildcat <u>Funice Monument</u> ; Grayburg-San Andres	
4. Well Location		<u>Larree Hondillerie, a</u>	r dybar g Sair Andres
Unit Letter E : 1980' feet from the	lorth line and	660' feet from th	e West line
Section 11 Township 21S	Range 36E	NMPM C	County Lea
11. Elevation (Show wheth			
		,	
12. Check Appropriate Box to Indicat	e Nature of Notice, R	Report, or Other Dat	a
	1		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		RT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	□ A	LTERING CASING 🔲
TEMPORARILY ABANDON	COMMENCE DRILLI	NG OPNS. 🔲 P	AND A
PULL OR ALTER CASING	CASING/CEMENT JO	ов 🗆	
DOWNHOLE COMMINGLE			
OTHER: Acid Stimulate	OTHER:		
13. Describe proposed or completed operations. (Clearly state all of starting any proposed work). SEE RULE 1103. For Multipor recompletion.	pertinent details, and give ple Completions: Attach	e pertinent dates, includ wellbore diagram of pro	ing estimated date oposed completion
1. MIRU PU. MI & rack 6400' of 2-3/8" N-80 WS. ND	WH. NU BOP. MIRU Sca	analog. POOH & scana	alog prod.tbg
out of hole. Check for scale buildup on pump a	nd/or rods.		
2. PU & RIH w/4-3/4" bit & bent sub on 2-3/8" WS. RIH & work tbg into window @ 3647'. CO to 5236' MD. 3. MIRU Cudd acidizing. SH lateral open hole from 3647' down to 5236' w/600 bbls brine while circulating			
to pit. Circulate clean. Close in backside & SI			
90/10 Acid/Tol w/max pressure of 2500 psig on			,000 gars 20%
4. Work tbg out of lateral section & RIH to 3710'			
Procedure Cont'd. on next page.			
Spud Date: Rig Re	ease Date:		
I hereby certify that the information above is true and complete to t	he best of my knowledge	and belief	
SIGNATURE (KNorth Ward)	ne stor of my rais wisage	una conor.	
SIGNATURE TO SIGNATURE T	TLE Regulator		TE02/24/09
Type or print name Kristy Ward E	kristy_ward@xtoe mail address:		ONE <u>432-620-6740</u>
For State Use Only	petroleum e	-NGINEE'H	MAR 0 4 2009
APPROVED BY T	TTLE <u>Emiliaradai f</u>		E
Conditions of Approval (if any):			

Eunice Monument South Unit #306 Acid Stimulate Cont'd.

- 5. Sonic Hammer perfs from 3710' down to 3760' w/25 bbls of brine while ciculating to pit. Circulate clean. Close in backside and Sonic Hammer perfs from 3760' up to 3710' with 600 gals 20% 90/10 Acid/Tol with a max pressure of 2500 psig on tubing and 500 psig on backside.
- 6. RIH to 3768' and Sonic Hammer vertical open hole from 3768' down to 3820' with 25 bbls brine while circulating to pit. Circulate clean. Close in backside and Sonic Hammer open hole from 3820' up to 3768' with 800 gals 20% 90/10 Acid/Tol with a max pressure of 2500 psig on tubing and 500 psig on backside.
- 7. Flow/Swab back acid load. Determine flow rate and oil cut. POOH and LD workstring and Sonic Hammer.
- 8. RU tubing tester and spooler. Assemble Wood Group pump and RIH pump and hydrostatic test production tubing in the hole. ND BOP. NU WH. Production equipment should be designed for 600 bfpd or better estimate based on swab results. ND BOP. NU WH. Put well in test and RWTP. RDMO PU.