Submit 3 Copies To Appropriate District	State of New Me	xico	Form C-103
Office District I	Energy, Minerals and Natural Resources		June 19, 2008
1625 N French Dr., Hobbs, NM 88240			WELL API NO. / 30-025-25711
District II 1301 W Grand Ave, Artesia, NM 8 RECEOUEDNSERVATION DIVISION		5. Indicate Type of Lease	
		STATE STATE	
1000 Rio Brazos Rd., Aztec, NM 87410 MAR 1 6 200 South St. Francis Dr. District IV		6. State Oil & Gas Lease No.	
1220 S St Francis Dr., Santa Fe, NM 87505 HOBBSOCD			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CENTRAL VACUUM UNIT
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other C02/WTR INJECTION			8. Well Number 100
2. Name of Operator			9. OGRID Number 4323
CHEVRON U.S.A. INC.			/.
3. Address of Operator			10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS 79705			VACUUM GRAYBURG SAN ANDRES
4. Well Location			
Unit Letter F: 1372 feet from the NORTH line and 2544 feet from the WEST line			
Section 6 Township		NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3993' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
PULL OR ALTER CASING		CASING/CEMEN	Т ЈОВ 🔲
OTHER: INTENT TO C/O & A	DD PERES	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estin			d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion			
CHEVRON U.S.A. INC. INTENDS TO C/O FOR FILL & INCREASE THE PERF DENSITY IN THE LOWER PORTION OF THE UPPER SAN ANDRES & THE UPPER PORTION OF THE LOWER SAN ANDRES.			
THE OTTER SAN ANDRES & THE OTTERTORTION OF THE LOWER SAN ANDRES.			
THE INTENDED PROCEDURE AND WELLBORE DIAGRAM IS ATTACHED FOR YOUR APPROVAL.			
Spud Date:	Rig Release Da	ate	
Spud Date.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
AC		,	
Alamit Derta h			
SIGNATURE	FINT LE TONTITLE RE	EGULATORY SPE	CIALIST DATE 03-13-2009
Type or print name DENISE PINKERTON E-mail address: <u>leakejd@chevron.com</u> PHONE: 432-687-7375			
Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375 For State Use Only Image: Comparison of the state			
DISTRICT 1 SUPERVISOR MAR 1 8 2009			
APPROVED BY:DATEDATE			
Conditions of Approval (if any):			
v			

CVU 100 API No. 30-025-25711 Vacuum (Grayburg-San Andres) Field Lea County, NM

Workover Procedure

 \leq

- 1. Rig up pulling unit. Kill well. ND wellhead and NU BOP.
- 2. Release packer set at 4225' and TOH w/ 2-3/8" injection tubing.
- 3. TIH w/ 3-7/8" cone buster mill, drill collars on 2-3/8" workstring. Tag fill.
- 4. Rig up reverse unit and power swivel. Clean out fill to TD. If tight spots are encountered swedge out as necessary

Note: the casing has been swedged out previously from 4316' to 4361' and 4718' to 4750'. During the last workover in 2002, the maximum depth reached was 4718'. Original PBTD is 4760'.

- Circulate the hole clean. Pump 20-40 sand to spot a sand plug from 4600' to TD (casing capacity = 14.6 lb sand/ft). Spot 15% HCL acid from 4620' to 4250'. TOH.
- Rig up wireline truck. Get on depth with the casing collars (there is no short joint). Perforate the 4-1/2" casing with 2 JSPF @ 120 degree phasing as follows: 4436'-64', 4484'-92', and 4510'-4556'. Rig down wireline truck.
- 7. TIH w/ 4-1/2" treating packer on 2-3/8" workstring and set at 4200'.
- 8. Acidize perfs with 8,000 gallons 15% NEFE HCl in 4 stages using rock salt as a diverter. Shut in for one hour and slowly flow back load. Shut down flowback if sand reaches the surface. TOH w/ packer and workstring.
- 9. TIH w/ 3-7/8" milltooth bit on 2-3/8" workstring and run to bottom. Tag and record top of sand plug. TOH.
- 10. TIH w/ 4-1/2" injection packer and on-off tool (w/ pump out plug) on 2-3/8" injection tubing. Set packer at 4225'. Release on-off tool and circulate 10 ppg packer fluid.
- 11. Latch back onto packer. ND BOP and NU wellhead.
- 12. Perform MIT test.
- 13. Rig down pulling unit.

كمعمر

- 14. Pressure up on tubing and pump out plug.
- 15. Return to injection.

PTB 1/28/09

CVU 100 Wellbore Diagram

