Form 3160-5 (August 2007)				FORM APPROVED OMB NO. 1004-0135 Expires July 31, 2010 5 Lease Serial No NMNM26396 6 If Indian, Allottee or Tribe Name 7 If Unit or CA/Agreement, Name and/or No. NMNM72384	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM26396		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					
1. Type of Well	1. Type of Well ☐ Oil Well ☐ Other			3016 JV-P 01	
2 Name of Operator BTA OIL PRODUCERS		AM INSKEEP aoil.com	9 API Well No 30-025-27824-	-00-S1	
3a Address 104 SOUTH PECOS MIDLAND, TX 79701	• 3 • F	b Phone No (include area cod Ph: 432.682.3753 Ext: 139 Fx: 432 683.0325	e) 10 Field and Pool, o ANTELOPE R	IDGE; ALOKA	
-	4. Location of Well (Foolage, Sec. T. R. M., or Survey Description) Sec 35 T22S R34E SESW 660FSL 1980FWL			n, and State , NM	
12. CHECK	APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTHI	ER DATA	
TYPE OF SUBMISSION	N TYPE OF ACTION				
Notice of Intent	Acidize	Deepen Fracture Treat	Production (Start/Resume) Reclamation	Water Shut-Off	
Final Abandonment Noti	ice Casing Repair Change Plans	□ New Construction Plug and Abandon   Plug Back	<ul> <li>Recomplete</li> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>	□ <sup>Other</sup>	
If the proposal is to deepen dir Attach the Bond under which t following completion of the in	ed Operation (clearly state all pertinent ectionally or recomplete horizontally, gi the work will be performed or provide th volved operations If the operation resu inal Abandonment Notices shall be filed by for final inspection )	ive subsurface locations and me ne Bond No, on file with BLM/E lts in a multiple completion or r	asured and true vertical depths of all pe BIA. Required subsequent reports shall ecompletion in a new interval, a Form	ertinent markers and zones be filed within 30 days 3160-4 shall be filed once	
	oses to P&A this well as follows:	RECEIVE	D		
1) MI & RI completion un 2) Circ hole w/ 9.3# salt of 3) Raise end of tbg to 55 4) Circ hole w/ 9.3# salt 5) Spot P&A plants as fol 78 sx @ 5583	admud	MAR 1 8 200: HOBBSOCI			
78 sx 10 5065 (Mashbell 78 sx 10 3500 (Must be t	78 synd 5065 (Must be tagged after spotting) 78 synd 3500 (Must be tagged after spotting)		SEE ATTACHED FOR		
78 sx (2) 1933 (Must be f 32 sx (2) sufface	tagged after spotting)		CONDITIONS OF APP	PROVAL	
14. I hereby certify that the foreg	Electronic Submission #67	_ PRODUCERS, sent to the	Hobbs		
Name(Printed/Typed) BOB	Name(Printed/Typed) BOB STUCKLEY		NAGER		
Signature (Electr	Signature (Electronic Submission)		2009		
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE		
Approved By JAMES A AMO	os d	14 TitleSUPERV	ISOR EPS	Date 03/13/20	
Conditions of approval, if any, are a certify that the applicant holds lega which would entitle the applicant to	attached Approval of this notice does n l or equitable title to those rights in the s o conduct operations thereon	ot warrant or subject lease Office Hobbs		2009	
Title 18 U S.C. Section 1001 and T States any false, fictitious or frauc	itle 43 U S C Section 1212, make it a ci dulent statements or representations as to	rime for any person knowingly a o any matter within its jurisdiction	ind willfully to make to any department	nt or agency of the United	
** BLM	REVISED ** BLM REVISED *	** BLM REVISED ** BL	M REVISED ** BLM REVISE	ED **	

## Additional data for EC transacuon #67924 that would not fit on the form

32. Additional remarks, continued

7) Cut off wellhead and install dry hole marker

Schematic attached

BTA Oil Producers NMNM26396: Maddox Fed, 8016 JV-P 1 660' FSL & 1980' FWL Sec. 35, T22S-R34E Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

Step 1. RIH and tag CIBP @ 10550' +/-, plus the 1200' of cable. Spot 25 sx plug on top of CIBP.

Step 2. Spot 180' plug from 8580'-8420' (Top of Bone Springs).

Step 3. Spot 170' plug from 5614'-5444' (DVT and Top of Delaware).

Step 4. Spot 150' plug from 5010'-4860' (Shoe), WOC and tag.

Step 5. Spot 100' plug from 3988'-3888' (Base of Salt), WOC and tag.

Step 6. Spot 100' plug from 3550'-3450' (Top of Salt), WOC and tag.

Step 7. Spot 120' plug from 1882'-1762' (Shoe), WOC and tag.

Step 8. Set surface plug from 60'-surface.

See attached standard COA's.

James A. Amos 575-234-5909

3/13/09

Surt 60 КВ = X-Mas Tree Top Conn. 32 **Tubing Detail** Anhy 2200 TOS 2500 +/-BOS 3938 wor Tag Shoe 120 plug 1882-1762 1 100 plug 3550-3450 r. - 20" 94 & 133# K-55 Surf. Csg. Cmtd w/ 2950 Sx 77 TO WOL Tay TOP Salt Tag Bose Salt 100 plug 3988- 3888 WUC 10 wor Tay shoe 150 plug 5010-4860 @ 4935' - 13-3/8" 61 & 68# S-80 & K-55 Inter uniu W/ 3900 SX DV Tool @ 5,493' Top of Del/DV Tool Dil 5576 BS Top BS 8500 Cintd w/ 3900 Sx 170'plug 5614-54114 180'plug 8580-8420 BS TOP SPOJ 2554 ON CIBP CIBP@ 10550' W/ 40' Cml A0510 2 Bone Spring Perfs 10,594 - 612' & 10,738 - 750' RBP @ 10792' (Can't retrieve) WC 10590 CIBP @ 11370' W/ 40' Cmt άX. Ann 1/160 @ 11690' - 9-5/8" 47 & 53.5# S-95, SS-95, SM-95 & JL-95 Interm Csg Cmtd w/ 4200 Sx in 2 stgs <u> SOMAN</u> CIBP @ 12650' W/ 40' Cmt Cmt Sqz'd Atoka Perfs 12,332 - 12,356' @ 11,394-13,078' -- 7-5/8" 30# P-110 Liner Cmtd w/ 300 Sx CIBP @ 12970' W/ 40' Cmt Morrow EO Perfs 13.011 - 13.023\* 10510 Morrow A Perfs 13,277 - 13,286 Morrow C Perfs 13,464 -468'; 13,513 - 516' @ 12,739-13,648' - 5"23.2#L-80 Liner Cmtd w/ 200 Sx 13.650 MORROW COMPLETION TJW Drawn Revised 8/8/2008 Maddox Federal #1 LEASE Antelope Ridge (Morrow) FIELD 660' FSL 1980 FWL Sec. 35 T22S R34E LOCATION Approved STATE New Mexico COUNTY Lea Date Atoka PRODUCING FORMATION Created by Neevia Document Converter trial version http://www.neevia.com

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.