$\sim 10^{-10}$	
Submit 3 Copies To Appropriate District State of New Mexico Office The State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	June 19, 2008 WELL API NO.
District I 1625 N. French Dr., Hobbs, NM 8 District II 1301 W Grand Ave., Artesia, NM 88210 District III ADD: 0 a pro1220 South St. Francis Dr	30-025-36083
District III 1000 Rio Brazos Rd., Aztec, NM 87410 PR 06 2009 Santa Fe, NM 87505	
	STATE STATE FEE
1220 S St. Francis Dr., Santa Fe, NHOBBSOCD 87505	6. State Oil & Gas Lease No. 30950
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	O A 7. Lease Name or Unit Agreement Name: Amerada State
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well 🕅 Gas Well 🗌 Other	1 /
2. Name of Operator Energen Resources Corporation	9. OGRID Number 162928
3. Address of Operator	102 920 10. Pool name or Wildcat
3300 N. "A" St., Bldg 4, Ste. 100, Midland, TX 79705	Saunders, San Andres
4. Well Location	
Unit Letter <u>M</u> : 990 feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line	
Section 4 Township 15-S Range 33-	E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, C	JR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
	RILLING OPNS. P AND A
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
See attached procedure	
	- ·-··.
SEE CHANGES	
The Oil Conservation Division Must be notified 24 hours prior to the beginning of plugging operations	
Spud Date: 01-03-03 Pig Palance Date:	
Spud Date: 01-03-03 Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Charles Chinail	
SIGNATURE SIGNATURE OJUNI TITLE Regulatory Analyst DATE 03-30-09 tracie.cherry@energen.com	
Type or print name <u>Tracie J Cherry</u> E-mail address: PHONE <u>432 684-3692</u>	
For State Use Only A	
APPROVED BY Mark Whitzhe TITLE COmp. Off. DATE 4/8/09	
Conditions of Approval (if any):	

ENERGEN RESOURCES CORPORATION

Amerada State #1

990' FSL and 330' FWL Sec 4, T-15-S, R-33-E Lea, Co. NM Saunders San Andres Field P&A well

Date: March 25, 2009

AFE No: PB031009

Cost: \$40,000

WI: 100.00% NRI: 0%

See Well Bore Diagram

Plugging Procedure

- 1. MIRU Pulling Unit
- 2. Install BOPE.

25

2600'

- 3. RIH w/tubing. Tag plug @ 4710. Spot sx cement on top of plug. PU Circulate hole w/9 #/gal plugging mud to 3100' ...
- SPOT 25 5x cm+ @ 406B' (DV Tool) 4. Perforate casing at-3140' w/4 squeeze holes.
- 5. RIH w/pkr and set at 3040'. 255X
- 6. Squeeze the cement through perfs at 3140-back up to 3040*. POOH w/pkr. @ 2550'
- 7. RIH w/tbg. Tag cement plug. Circulate 9 #/gal plugging mud to 1150'. Perf @ 1500
- Set coment plug from 1250 to 1150'. 8 SQZ w/255xcmt
- 9. Tag cement plug. Circulate 9 #/gal plugging mud to 250.
- 10. Perforate casing at 486' w/4 squeeze holes.
- 11. RIH w/pkr and set at 250'.

- 12. Squeeze the cement through perfs at 486' back up to surface. Call office & NMOCD for instructions if well will not circulate. POOH w/pkr. TAG @ 386
- > SPOT CMT PLUG FROM GO' TO SURFACE.
 - 13. Cut off wellhead 3' from surface and well on P&A marker.

14. RD pulling unit.



