Submit 3 Copies To Appropriate District State of New Mex Office District I		Form C-103
District 1	l Resources WELL API NO.	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	2	0-025-29748
District II 1301 W. Grand Ave., Artesia, NM 882 10 1625 N. French Dr., Hobbs, NM 88240  APK OIL CONSERVATION I	DIVISION 5. Indicate Type	
District III # # # DDD UR20 South St. France	is Dr. STATE	FEE 🛛
anta Fe NM X/	6. State Oil &	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	0. 5	002404
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name	or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG	BACK TO A Anderson 6	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	SUCH	/
PROPOSALS.)	8. Well No. <b>01</b>	
1. Type of Well: Oil Well Gas Well Other	9. OGRID Num	per /
2. Name of Operator	3. OOKID Nulli	012627
Kevin O Butler & Associates	10. Pool name o	
3. Address of Operator  P. O. Boy 1171 Midland TV 70702		ngton Penn, NE
P. O. Box 1171, Midland, TX 79702	Edvi	ngton i enn, ive
4. Well Location Unit Letter U: 510 feet from the South	line and 850 feet	from the <b>West</b> line
	ge 36-E NMPM	County Lea
11. Elevation (Show whether DR, R	Ç	- Table 19 19 19 19 19 19 19 19 19 19 19 19 19
11. Elevation (Snow whether Dit, 1	E-78-54 No.	
Pit or Below-grade Tank Application or Closure	and the second s	
	esh water well Distance from n	earest surface water
·		
12. Check Appropriate Box to Indicate Nat	ure of Notice, Report of Othe	r Data
NOTICE OF INTENTION TO:	SUBSEQUENT R	FPORT OF:
	REMEDIAL WORK	ALTERING CASING
	COMMENCE DRILLING OPNS.	
	CASING/CEMENT JOB	_
COMPLETION	5, 1 <b>3</b> , 13, 13, 13, 13, 13, 13, 13, 13, 13, 13	
		<u>_</u>
	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertin	ent details, and give pertinent dates	s, including estimated date of
starting any proposed work) SEF RULE 1103 For Multiple Com	dations: Attach wallhare diagram	of proposed completion or
starting any proposed work). DEE RODE 1105. 101 Manufel Com-	neliolis. Aliacii welloofe diagraffi	
recompletion.	ACE W/MLF. 9.5 BRIN	E W/12.5# gel PER F.
starting any proposed work). SEE RULE 1103. For Multiple Comprecompletion.  Penn perfs @ 11578-11607	ACE W/MLF. 9.5 BRIN	EW/12.5# gel PER E
recompletion.  Penn perfs @ 11578-11607	ACE W/MLF. 9.5 BRIN	ε ω/12.5# qel PER F.
Penn perfs @ 11578-11607	ACE W/MLF. 9.5 BRIN	ε ω/12.5# qel PER F.
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg.		
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and nump. NU BOP. POH w/ 2 3/8 tbg.		
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'.	top. POH to 8500'. — PERF & SQZ 256XS	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing	top. POH to 8500'. — PERF & SQZ 256X5	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub and content of the state of the s	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub an 7. WOC and tag.	top. POH to 8500'. — PERF & SQZ 256X5	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub an 7. WOC and tag.	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  SPOT 25345 OR 100' @ 9. Spot surface plug.	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  Spot 25 345 DE 100' @ 8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  Spot 25345 OR 100' @ -8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  Spot 25345 OR 100' @ -8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
Penn perfs @ 11578-11607  1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  Spot 25345 OR 100' @ -8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.	top. POH to 8500'.  PERF & SQZ 256X5  and shoe plug)	
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.	top. POH to 8500'.  — PERF : SQZ 25 5X 5.  Id shoe plug)  2100' T.O.S.	@ 5500' WOC ? T
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug. 100' 10. Cut off well head and weld on Dry Hole Marker.	top. POH to 8500'.  PERF ! SQZ 25 5X5  Id shoe plug)  Z100' T.O.5.	that any pit or below-grade tank
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.	top. POH to 8500'.  PERF ! SQZ 25 5X5  Id shoe plug)  Z100' T.O.5.	that any pit or below-grade tank
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug. 25'.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is trae and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g	top. POH to 8500'.  PERF ! SQZ 25 5X5  Id shoe plug)  Z100' T.O.5.	that any pit or below-grade tank
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.	top. POH to 8500'.  PERF ! SQZ 25 5X5  Id shoe plug)  Z100' T.O.5.	that any pit or below-grade tank
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug. 10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g  SIGNATURE	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank ative OCD-approved plan DATE 41459
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is tree and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank ative OCD-approved plan DATE 41409
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is trace and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g  SIGNATURE  TITLE	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank ative OCD-approved plan DATE 41409
1. Move in Rig up plugging equipment. 2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg. 3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'. 5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g  SIGNATURE  Title	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank ative OCD-approved plan DATE 41409
1. Move in Rig up plugging equipment.  2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg.  3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'.  5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE  Type or print name  SIGNATURE  TITLE	top. POH to 8500'.  PERF ! SQZ 25 5X5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit or an (attached) alternative for the common of t	that any pit or below-grade tank active OCD-approved plan  DATE 4/14/09  ephone No. 432 588761  DATE 4/14/200
1. Move in Rig up plugging equipment.  2. POH w/ rods and pump. NU BOP. POH w/ 2 3/8 tbg.  3. RIH w/ 5 1/2 CIBP and set @ 11525. Spot 25 sx class C cement on 4. Spot 25 sx cement @ 8500-8300'.  5. POH w/ tbg. RIH and cut 5 1/2 csg. @ +/- 4300'. Lay down casing 6. RIH w/ tbg to 4350. Spot 45 sx cement plug @ 4400-4200. (stub at 7. WOC and tag.  8. POH to 425'. Spot 65 sx. plug 425- 165. WOC and Tag 9. Spot surface plug.  10. Cut off well head and weld on Dry Hole Marker.  I hereby certify that the information above is true and complete to the best of my has been/will be constructed or closed according to NMOCD guidelines, a g SIGNATURE  Type or print name  SIGNATURE  TITLE	top. POH to 8500'.  PERF ! SQZ 25 5X 5  Id shoe plug)  Z100' T.O.5.  knowledge and belief. I further certify eneral permit  or an (attached) alternative.	that any pit or below-grade tank active OCD-approved plan  DATE 4/14/09  Pephone No. 432 588767  DATE 4/14/200

01,400 cc PM.

appled acad.

Towelle 11,750'

Well History

-7-86

-30-86

-1-86

-3-86

-ZO-86

-24-86

-2-86

. *B*3

'-*2-6*8

- 11-90

-10-93

13-93

HP LASERJET FAX ANDERSON, G-1 Property use ODZACA Unit "U" Section 6 TILOS 1837E 510 FSL 9 850 FWL Lea County, New Mexico API # 300252978 LOVINGTON NE (PENN) FIELD KB - 3874" Note: Penn = Straw Line (8-10-06)30-86 Specific Wellby Eston!.
Ran 1378 Ul (Spicete 375.)
Circ.Cont to Sunce
-7-86 898"32 "Cog set @ 4,249" W/18005x (Pid Not circ cmt). DST #1 (11,575-11,658') rec SON FOHLOUS, SC-5,500 FOOCE 133/8" (d#Set@ 375" (Circ. cont to Surface) 5/2" 17# N80/SOS/P10 LT/C C11,750 W/5305X, TOCE10,000 Perforated (Penn) from 11,553 San Adres @ 4A05' to 11,593, w/40 moles. Glurietri @ 6536 Acidized V/Z,500 gals 15% NE/FE Acid. Well Flower. FBHP- 2519 psig, FSIP-3,216) psig @ [1,573 from BHP test.] Heidre W/5,000gals 15% CXL 800' TOC by T.S. ■ 896° 52± Set @ 4,749' (Dd Not Che. Chit) Placed Wellow goslift. Setpler @11,363 (76LV from 11,300 to 6,500) Install too pump and pumping Repaired Coung leak w/ cmt squeeze (4.340'-6.499') TOH w/tubing for part tubing. (Split Collar). Found tight spotl IN casing @6,310 w/prestot. Dd 27647 J-55 EUE TUDING (319, 15) Not tog 'w/ open ended, tubing. Worked) Sudden Wucusing tight spots. TAC @ +/- 9,827' EOT C+1-9,889'

Resource tested cosing V/ RBP4 RP from 9,875 to 6,400', Found leaks in cosing from 6,340 to GAPA, set relainere 6,235. Rumped Contequence jobs Onled out and from 6,145 through relainer & fellower Abl. Resource tested cossing to 400 ps/held/ ÛΚ,

RCIN tubing & nots in hole. Placed 27-93 Well ON PUMP. LIZIMPHERSZIPSOF tubingRestorated Penn (11,553-11,593') w/40 holes (Stawn)

5/2" 17# N80/595/PNO LIZC @ 11,750 Cm Hd w/5305x. TOCE 10,000 per Temp Survey.

TO 11750