Office	opies To Appropriate District, RECEIPER Minerals and Natural Re	esources	· I	Form C-103 June 19, 2008
<u>District I</u> 1625 N Fre <u>District II</u>	and Ave., Artesia, NM 88240		/ELL API NO. 000500657	Julie 19, 2000
1301 W. Gr District III	and Ave., Artesia, NM 88210 NO OVECONSERVATION DIV	$\frac{1510N}{5}$	Indicate Type of Lease	- 1
1000 Rio Bi District IV	razos Rd, Aztec, NM 8#10BBSOCD220 South St. Francis I Santa Fe, NM 87505	л. 	STATE X FEE	
DISTINCT	Francis Dr., Santa Fe, NM PAGE 1 OF 2	0.	6. State Oil & Gas Lease No. E-2771	
	SUNDRY NOTICES AND REPORTS ON WELLS		Lease Name or Unit Agree	
DIFFEREN	JSE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BA T RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C401) FOR SUC	тн 📕	OUTH CAPROCK QUEEN	UNIT V
PROPOSAI	LS.) of Well: X Oil Well Gas Well Other	δ.	8. Well Number 011	
2. Name	of Operator /		9. OGRID Number	
	BUTLER & ASSOCIATES, INC.  ss of Operator		12627	
	1171, MIDLAND, TEXAS 79702		<ol> <li>Pool name or Wildcat</li> <li>S559 CAPROCK QUEEN</li> </ol>	/
4. Well I	Location			
1	Jnit LetterK1980 feet from theSOUTH		1963feet from theWE	STline
		ange 31E	NMPM CHAVES	County
	11. Elevation (Show whether DR, RKB, 4447' GR	, <i>R1, GR, etc.)</i>		
	12. Check Appropriate Box to Indicate Nature	of Notice, Re	port or Other Data	
	NOTICE OF INTENTION TO:	SUBSE	QUENT REPORT OF	<b>-</b>
		IEDIAL WORK	X ALTERING	CASING
		SING/CEMENT JC		
<u>OTHER:</u> 13. D	escribe proposed or completed operations. (Clearly state all pertine	IER: PRODUCIN	ve pertinent dates, including	estimated date
13. D of	OTH escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion.	ent details, and gi	ve pertinent dates, including	estimated date
13. D of or	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion.	ent details, and gi	ve pertinent dates, including	estimated date sed completion
13. D of or DO PI	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion.	ent details, and ginpletions: Attach	ve pertinent dates, including wellbore diagram of propos	sed completion
13. D of DO PI 10/29/08 Wed.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo	sed completion
13. D of or DO PI 10/29/08	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t	sed completion
13. D of DO PI 10/29/08 Wed.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t	sed completion
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured	ent details, and ginpletions: Attach 5 ½" x 2' sub owl. Broke out ak out of 5 ½"co Close well in. S up casing to 300	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t SDFN.	wed bint o it ead
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 <sup>1</sup> / <sub>2</sub> " x 2 7/8" swedge, unflange wellhead and pressured with 5 <sup>1</sup> / <sub>2</sub> " x 16" nipple and BOP. PU 4 <sup>3</sup> / <sub>4</sub> " rock bit, bit sul	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co Close well in. S up casing to 300 b, crossover, 6 –	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. D#. NU new Larkin wellh 3 1/8" collars and sub jo	wed bint o it ead int.
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con recompletion. <u>UG &amp; STIMULATE</u> MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25	ent details, and ginpletions: Attach 5 ½" x 2' sub owl. Broke out ak out of 5 ½"co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. )#. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joi	ved bint o it ead int.
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. <u>CUG &amp; STIMULATE</u> <u>MIRU Basic Energy Service WSU. Dug out wellhead. A</u> multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. <u>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured</u> with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in rete empted to circul	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. #. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joints a late well but 5 1/2" collar y	ved bint o it ead int. ints and was
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. <u>LUG &amp; STIMULATE</u> <u>MIRU Basic Energy Service WSU. Dug out wellhead. A</u> multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. <u>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured</u> with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug a	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. #. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joints a late well but 5 1/2" collar y	ved bint o it ead int. ints and was
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. <u>CUG &amp; STIMULATE</u> <u>MIRU Basic Energy Service WSU. Dug out wellhead. A</u> multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. <u>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured</u> with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug a	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. #. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joints a late well but 5 1/2" collar y	ved bint o it ead int. ints and was
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2	<ul> <li>escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion.</li> <li>CUG &amp; STIMULATE</li> <li>MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar.</li> <li>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¼" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75</li> <li>Tough Dog welded on bull nipple to damaged 5 ½" collar a</li> </ul>	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> "co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug at 0'). SDFN.	ve pertinent dates, including wellbore diagram of proposition joint under wellhead show wellhead, recovered one joint llar but unsuccessful due t DFN.	ved completion ved pint o it ead int. ints and was ing h 2
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75 Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> " co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug at 0'). SDFN.	ve pertinent dates, including wellbore diagram of proposi- joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. W. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joi turns. RIH with 91 joints a late well but 5 1/2" collar y nd RIH with 20 joints sett (held good). RBIH wit with bit, BHA and 91 joi	wed bint o it ead int. ints and was ing h 2 ints
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¼" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75 Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a tagging plug @ 3,041'. Circulated well clean while truck pu	ent details, and ginpletions: Attach 5 1/2" x 2' sub owl. Broke out ak out of 5 1/2"co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug at 00'). SDFN.	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN. )#. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joints a late well but 5 ½" collar y nd RIH with 20 joints sett )# (held good). RBIH with with bit, BHA and 91 joints bit. PU swivel and drilled	wed bint o it ead int. ints and was ring h 2 ints out
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea- being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75 Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints and tagging plug @ 3,041'. Circulated well clean while truck pu 18" of plug before drop out. Washed out 4 joints and circulated while truck pu	ent details, and ginpletions: Attach 5 1/2" x 2' sub owl. Broke out ak out of 5 1/2"co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in rete empted to circul ble clevis plug at 00'). SDFN.	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN.	wed bint o it ead int. ints and was ing h 2 ints out ore
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75 Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a tagging plug @ 3,041'. Circulated well clean while truck pu 18" of plug before drop out. Washed out 4 joints and circu	ent details, and ginpletions: Attach 5 1/2" x 2' sub owl. Broke out ak out of 5 1/2"co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in rete empted to circul ble clevis plug at 00'). SDFN.	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN.	wed bint o it ead int. ints and was ing h 2 ints out ore
13. D of DO PI 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri.	escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion. UG & STIMULATE MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar. NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75 Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a tagging plug @ 3,041'. Circulated well clean while truck pu 18" of plug before drop out. Washed out 4 joints and circu capacity and cleaned out fill. Lost 40 Bbls in 10 minutes whi with 12 joints (EOT @ 2,788'). Close well in. SDFN.	ent details, and ginpletions: Attach 5 1/2" x 2' sub owl. Broke out ak out of 5 1/2" co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug an 00'). SDFN.	ve pertinent dates, including wellbore diagram of propos joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t BDFN. 0#. NU new Larkin wellh 3 1/8" collars and sub jo bove oil. RIH with 47 joi turns. RIH with 91 joints a late well but 5 ½" collar y nd RIH with 20 joints sett 0# (held good). RBIH wit 1 with bit, BHA and 91 joi bit. PU swivel and drilled mation. Circulated wellb RD swivel, PU tongs and Po	ved completion ved Dint o it ead int. ints and was ing h 2 ints out ore OH
13. D of OP I 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri. Day 3	<ul> <li>escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion.</li> <li>CUG &amp; STIMULATE</li> <li>MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea being welded internally. Repaired damage threads on collar.</li> <li>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75</li> <li>Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a tagging plug @ 3,041'. Circulated well clean while truck pu 18" of plug before drop out. Washed out 4 joints and circu capacity and cleaned out fill. Lost 40 Bbls in 10 minutes whi with 12 joints (EOT @ 2,788'). Close well in. SDFN.</li> <li>POH with 84 joints, BHA and bit. RIH with 5 ½" AD-1 pace leaving 12 points of tension. Loaded casing and tested to 300</li> </ul>	ent details, and ginpletions: Attach 5 <sup>1</sup> / <sub>2</sub> " x 2' sub owl. Broke out ak out of 5 <sup>1</sup> / <sub>2</sub> " co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug at 0'). SDFN.	ve pertinent dates, including wellbore diagram of proposi- joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN.	wed completion wed pint o it ead int. ints and was ing h 2 ints out ore OH 39' uid
13. D of OP I 10/29/08 Wed. Day 1 10/30/08 Thurs. Day 2 10/31/08 Fri. Day 3	<ul> <li>escribe proposed or completed operations. (Clearly state all pertine starting any proposed work). SEE RULE 1103. For Multiple Con- recompletion.</li> <li>UG &amp; STIMULATE</li> <li>MIRU Basic Energy Service WSU. Dug out wellhead. A multiple holes but none visible bellow collar above 8 5/8" bo but couldn't break out of National flange. Attempted to brea- being welded internally. Repaired damage threads on collar.</li> <li>NU 5 ½" x 2 7/8" swedge, unflange wellhead and pressured with 5 ½" x 16" nipple and BOP. PU 4 ¾" rock bit, bit sul Displaced 100% cut to cellar. PU 2 joints and circulated 25 stopping to hand bail cellar. Circulated 45 Bbls but continue tagged CIBP @ 3,041'. Quanah truck pulled cellar and atte leaking. POH with 91 joints and 6 DC's. PU 5 ½" retrieval plug @ 815'. Stand back 2 joints and close well in (EOT @ 75</li> <li>Tough Dog welded on bull nipple to damaged 5 ½" collar a joints and Watson man released plug. POH with 20 joints a tagging plug @ 3,041'. Circulated well clean while truck pu 18" of plug before drop out. Washed out 4 joints and circu capacity and cleaned out fill. Lost 40 Bbls in 10 minutes whi with 12 joints (EOT @ 2,788'). Close well in. SDFN.</li> <li>POH with 84 joints, BHA and bit. RIH with 5 ½" AD-1 pacl</li> </ul>	ent details, and ginpletions: Attach 5 1/2" x 2' sub owl. Broke out ak out of 5 1/2" co Close well in. S up casing to 300 b, crossover, 6 – 5 Bbls but still a e to get oil in ret empted to circul ble clevis plug at 0"). SDFN. and tested to 350 and plug. RBIH lled fluid from p ulated fill of for le circulating. R ker and 97 joints (held good). In a acid job – plea	ve pertinent dates, including wellbore diagram of propose joint under wellhead show wellhead, recovered one jo llar but unsuccessful due t DFN.	wed completion wed pint o it ead int. ints and was ing h 2 ints out ore OH 39' uid

11/04/08	0# of pressure on arrival. RU	swab equipment and fluid level was @ 2,200	. Made a total of 7 swab runs
Tues.	leaving fluid level @ 1,400'.	Made 9 more runs then recovered 2% cut.	Fluid level remain @ 1,400'.

Day 5	Recovered 110 Bbls of fluid. Close well in. SDFN.
11/05/08 Wed. Day 6	0# of pressure on arrival. RU swab equipment and fluid level was @ 1,400'. Made a total of 16 swab runs recovering 85 Bbls of fluid. Bottled a few samples to get analyzed. Left fluid level @ 1,400' with 5% cut. RD swab equipment and RU tubing equipment. Couldn't LD tubing due to high winds. Close well in. SDFN.
11/06/08 Thurs. Day 7	Bled well off. Release packer and POH with tubing. LD tubing and packer. ND BOP, flange wellhead with 2 3/8" x 6' J-55 sub with collars on both ends. RDMO.

PWOP

11/25/08	MIRU Basic Energy Services WSU. Bled well off. Unflange wellhead, NU BOP and spooler. Close well in.
Tues.	SDFN.
	SDFN.
Day 1	
11/26/08	Bled well off. RU tubing equipment and RIH with tubing & BHA. ND BOP, sat TAC with 10 points o
Wed.	tension and flange wellhead. RD tubing equipment & RU rod equipment. RIH with pc pump and rods
Day 2	Hung well and spaced out pump 36" off bottom. SDFN.
	Tubing Detail
	$\overline{97 - 27/8"}$ N-80 YB joints
	1 – 2 7/8" x 4' J-55 sub joint
	1 – 3.5" x 26.5 stator joint
	1 – 2 7/8" x 1.67" bump sub joint
	1 – 2 7/8" N-80 YB joint
	1 – 5 ½" TAC 40K @ 3,108'
	1 – 2 7/8" x 4' perf'd sub joint w/ BP
	Rod Detail
	$\frac{1}{1-1}$ $\frac{1}{4}$ x 16' PR
	1 – 7/8" D rod w/ twin guides
	2 – 7/8" pony rods 6', 4'
	9 – 7/8" D rods w/ twin guides
	100 – 7/8" D rods w/ single guides
	10 – 7/8" D rods w/ twin guides
	1 – 7/8" D rod w/ single guides
	1 – 7/8" x 1' lift sub & 22.91' chrome rotor
12/01/08	Level drive head and installed motor support. RDMO.
Mon.	
Day 3	

Spud Date:		Rig Release D	ate:	
I hereby certify th	at the information above i	is true and complete to the b	est of my knowledge and beli	ef.
SIGNATURE	Co.t	TITLE Pre	esident/Owner DATE 4-3-0	9
Type or print nam	e KEVIN O BUTLER	_E-mail address: robie@ge	edmidland.com PHONE: 4	32-682-1178
For State Use Or APPROVED BY: Conditions of App	Alan	TITLE PET	POLEUM ENGUNIER	APR 2 2 2009

## SCQU #11-30 (STATE "D" #1) WELLBORE DIAGRAM

ć

## LOCATION: K-30-T15N-R31E CHAVES COUNTY, NEW MEXICO

(9-30-2005)



TD: 3,181'