
Submit 3 Copies To Appropriate District Office State of New Me	10111 0 103
District 1 Energy, Minerals and Natural Resources Revised June 10, 2003	
1625 N. French Dr., Hobbs, NM 88240 WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	DIVISION 30-025-32857
District III 1220 South St. Fran	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87410	SIAIE L FEE LA
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.)	JG BACK TO A COOPER JAL UNIT
1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
SDG Resources L. P. 022351	
3. Address of Operator P. O. Box 1390 10. Pool name or Wildcat	
Montrose, CO 81402	LANGLIE MATTIX: 7RVRS, QUEEN; JALMAT: TANSILL, YATES, 7RVRS
4. Well Location	
Unit LetterF_:_1425feet from the NORTH1	ine and1450feet from theWESTline
	36-E NMPM LEA County
11. Elevation (Show whether DR, 3324' G. L.	RKB, RT, GR, etc.)
12. Check Appropriate Box to Indicate N	ature of Notice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB
OTHER: Re-enter, Deepen, and Complete Well.	OTHER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
or recompletion.	
1. Re-entered P&A'd well and deepen.	
1. Re-entered P&A'd well and deepen. 2. RIH with 4 ¾" bit & 12 - 3 ½" drill collars on 2 7/8" work string (N-80 inspected). 3. Drill out cement plugs. Drill out CIBP at 3,000 and at 3,450'. 4. Deepen well from 3,735' to 3,940'. Collect formation (cuttings) samples at 5' intervals. 5. RU Wireline company and run Compensated Neutron Log from 3,940' to 2,600'. 6. RIH with 5 ½" packer and set at 3,700'. Swab test open hole for production rate. 7. Acidize open hole (3,786'3,940') with 2,500 gallons 15% NEFE acid. 8. RIH with submersible pump on 2 7/8" tubing to 3,775'. 9. Hook well to flowline and report potential.	
3. Drill out cement plugs. Drill out CIBP at 3,000 and at 3,450'.	
4. Deepen well from 3,735' to 3,940'. Collect formation (cuttir	gs) samples at 5' intervals.
5. RU Wireline company and run Compensated Neutron Log fi	om 3,940' to 2,600'.
6. RIH with 5 ½" packer and set at 3,700'. Swab test open hole	for production rate.
7. Acidize open hole (3,786'3,940') with 2,500 gallons 15% NEFE acid. 8. RIH with submersible pump on 2 7/8" tubing to 3,775'.	
9. Hook well to flowline and report potential.	51/10/00/957
7. 1100 ii won to now mie and report potential.	016873
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE	
Type or print name Domingo Carrizales E-mail address: dom	ingo@sdgresources.com Telephone No. 432-550-7580
(This space for State use)	
APPPROVED BY Mis Williams OF DISTRICT SUPERVISOR/GENERAL MANAGER DEC 2 3 2003	
Conditions of approval, if any:	



TRIPPLE M OIL TOOL, INC.

WELLSITE BLOWOUT PREVENTER 7-1/16 DUKE MECHANICAL REPLACEMENT PARTS

