Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
D'A LAT	Energy, Minerals and Natu	rai Resources	May 27, 2004 WELL API NO. /
1625 N French Dr., Hobbs, NM District II	OIL CONSERVATION	N DIVISION	30-025-25127
1301 W. Grand Ave., Artesia, NM 88210	711091220 South St. Fra	ancis Dr.	5. Indicate Type of Lease
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd, Aztec, NM 87410	Santa Fe, NM 8	7505	STATE FEE X
District IV 1220 S. St. Francis Dr , Santa Fe, MARS	35000		6. State Oil & Gas Lease No.
	ES AND REPORTS ON WEIDSALS TO DRILL OR TO DEEPEN (OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name:
PROPOSALS.)	(,.	South Hobbs (GSA) Unit 8. Well Number
1. Type of Well: Oil Well Gas Well	Other WIW		8. Well Number
2. Name of Operator			9. OGRID Number
Occidental Permian Limite	d Partnership		157984 10. Pool name or Wildcat
3. Address of Operator P.O. Box 4294, Houston, T	X 77210-4294		Hobbs; Grayburg - San Andres
4. Well Location			
Unit Letter M :	feet from the Sou	uth line and	710 feet from the West line
Section 3		Range 38-E	
	11. Elevation (Show whether 36)	<i>DR, RKB, RT, GR, et</i> 14' KB	c.)
Pit or Below-grade Tank Application		11 (10)	Eggs (Fr. Vet. Fryshinder vet.) wild, only the statement are advantaged in a translations.
Pit type Depth to Groundwater	Distance from nearest fres	h water well Dis	stance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Constructi	on Material
12. Check A NOTICE OF INTERPORT REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING			SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT
OTHER:		OTHER: Commence	e Injection After Workover
1 1	• •		re pertinent dates, including estimated date in wellbore diagram of proposed completion
Subject well commenced	injection on 5/22/09	- the well had	been shut-in since the RTI
procedure (11/22/08 -	1/8/09); see attached	copy of previous	usly approved $C-103 (4/13/09)$.
•			
			e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
SIGNATURE Mark Step	shem TI	TLE Regulatory Cor	mpliance Analyst DATE 5/26/09
Type or print name Mark Stephe		mail address: Mark_S	Telephone No. (713) 366-5158
For State Use Only	n.11:M	JISTRICT 1	SUPERVISOR JUN022009
APPROVED BY Conditions of Approval, if any:	TI TI	TLE	DATE



State of New Mexico RECEIVEDgy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE APR 10 2009 OIL CONSERVATION DIVISION				
DISTRICT! 1625 N French Dr., Hobbs, NM PABBSOCD 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-25 127			
DISTRICT II	5 Indicate Type of Lease			
1301 W. Grand Ave, Artesia, NM 88210	STATE FEE X			
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.			
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	Section 3			
1. Type of Well.	8 Well No			
Oil Well Gas Well Other Lyertion	9. OGRID No. 157984			
2 Name of Operator Occidental Permian Ltd.				
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)			
4008 N. Grimes PMB-269, Hobbs, NM 88240				
4. Well Location	et From The West Line			
One peticle IVI . 363				
Section 3 Township 19-S Range 38-1 11 Elevation (Show whether DF, RKB, RT GR, etc.)	E THAT I'M LEG COUNTY			
3614' KB				
Pit or Below-grade Tank Application or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	ateria!			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
NOTICE OF INTERVIOR TO.	DEGOEIAI INCI OINI OI .			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING			
	ALTERING CASING			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING NS PLUG & ABANDONMENT			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS PLUG & ABANDONMENT			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB I to injection X			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	ALTERING CASING NS PLUG & ABANDONMENT NT JOB I to injection X s, including estimated date of starting any			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB I to injection X s, including estimated date of starting any			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/ 4-1/2" ARROWSET RBP, SET RBP @ 3836	ALTERING CASING NS PLUG & ABANDONMENT It to injection X s, including estimated date of starting any			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG	ALTERING CASING NS PLUG & ABANDONMENT NT JOB I to injection X s, including estimated date of starting any			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634	ALTERING CASING NS PLUG & ABANDONMENT It to injection X s, including estimated date of starting any			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Ito injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Ito injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Ito injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Ito injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH 10. TAG FILL AT 4110' W/ 132JTS OF TBG.	ALTERING CASING NS PLUG & ABANDONMENT It to injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH	ALTERING CASING NS PLUG & ABANDONMENT It to injection X s, including estimated date of starting any completion or recompletion.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH 10. TAG FILL AT 4110' W/ 132JTS OF TBG. 11. START DRILLING AT 4102', DOWN TO 4117' MADE A CONNECTION COULDN'T CIRCA *** SEE ATTACHED ****	ALTERING CASING PLUG & ABANDONMENT It to injection X s, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY.			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH 10. TAG FILL AT 4110' W/ 132JTS OF TBG. 11. START DRILLING AT 4102', DOWN TO 4117' MADE A CONNECTION COULDN'T CIRCUlture of the control of the contr	ALTERING CASING PLUG & ABANDONMENT It to injection X S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG 9. PICK UP 3.875" 11 BIT AND RIH 10. TAG FILL AT 4110' W/ 132JTS OF TBG. 11. START DRILLING AT 4102', DOWN TO 4117' MADE A CONNECTION COULDN'T CIRCUM** SEE ATTACHED **** I hereby certify that the information above is true and complete to the best of my knowledge and belief 1 further certify	ALTERING CASING PLUG & ABANDONMENT It to injection X S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP CASING TEST AND CEMENT PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT Proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375", 9' OUT 8. POOH W/ PKR ON 123 JTS OF 2 375" TBG. 1. START DRILL AT 4110' W/ 132JTS OF TBG. 1. START DRILLING AT 4102', DOWN TO 4117' MADE A CONNECTION COULDN'T CIRCUM*** SEE ATTACHED **** Thereby certify that the information above is true and complete to the best of my knowledge and belief 1 further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative or an electronic results and complete to the best of my knowledge and belief 1 further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative or an electronic results according to NMOCD guidelines or an electronic results and complete to the dest of my knowledge and belief 1 further certify constructed or closed according to NMOCD guidelines or an electronic results according to NMOCD guidelines or an electron	ALTERING CASING PLUG & ABANDONMENT X It to injection X S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be the OCD-approved			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OTHER Return well 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RU PU 2. RIH W/ 4-1/2" ARROWSET RBP, SET RBP @ 3836 3. RIH W/4-1/2" RBP ON 20JTS 2-3/8" TBG 4. SET 3ND RBP @634 5. DUMPED 2 SX SAND DWN CSG ONTO RBP 6. TALLY AND PICK UP 20JTS OF 2.375" TBG. TAG SAND 25' OUT. NEED TO CLEAN OUT 7. TAG PKR @ 3836' WITH 123 JTS OF 2.375" TBG 9. PICK UP 3.875" 11 BIT AND RIH 10. TAG FILL AT 4110' W/ 132JTS OF TBG. 11. START DRILLING AT 4102', DOWN TO 4117' MADE A CONNECTION COULDN'T CIRCO **** SEE ATTACHED **** 1 hereby certify that the information above is true and complete to the best of my knowledge and belief 1 further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan.	ALTERING CASING PLUG & ABANDONMENT It to injection S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be the OCD-approved Associate DATE			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER. OTHER OTHER OTHER OTHER Return well	ALTERING CASING PLUG & ABANDONMENT It to injection S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE TELEPHONE NO. 575-397-8247			
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP CASING TEST AND CEMENT OTHER. OTHER OTHER OTHER OTHER Return well	ALTERING CASING NS PLUG & ABANDONMENT TO injection S, including estimated date of starting any completion or recompletion. SAND CULATE EITHER WAY. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE			

- 12. TBG WAS PLUGGED WORKED W/ IT TILL IT BROKE FREE AND STARTED GETTING COOD CIRCULATION 38 BPM AT 700 PSI
- 13. RUN BACK IN THE HOLE W/ 3.875" BIT. TAGGED @4117
- 14. START DRILLING FROM 4117' TO 4163'
- 15. DRILLED TO 4209'
- 16. RIH W/ NEW 3.875 L2 BIT. TAG HIGH @ 4199'
- 17. DRILLING FROM 4199', NEW PBTD @ 4220'
- 18. DRILLED FROM 4169' TO 4220'
- 19. RIH W/ 4.5 ARROW SET 1X PKR IN HOLE DOWN TO 4110' WITH 131 JTS
- 20. PKR WOULD NOT SET UNTIL GOT UP TO 3934' W/ 126 JTS
- 21. POOH UP TO 3905' W/ 125 JTS AND SET PKR
- 22. ACIDIZE, SALT BLOCK, 15% NEFE @ 3.5 BPM W/ 1180 MAX PSI
- 23. RELEASE PKR AND PULL W/ 125 -2 7/8 WORKSTRING
- 24. PICK UP 41/2 LOK-SET PKR W/ PUMP OUT PLUG AND RIH W/ 4' PERF SUB AND RIH W/ 124-2 3/8 WORKSTRING, SET PKR @ 3873'
- 25. PRESSURE UP 4 ½ CSG TO 600 PSI, RUN 30 MIN, MIT TEST, OCD WAS PRESENT
- 26. RD PU AND REV UNIT. CLEAN LOCATION

RU PU 11/22/08 RD PU 1/08/09

