Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised May 08, 2003 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-29980 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III FEE 😠 1000 Rio Brazos Rd., Aztec, NM 87410 STATE Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RYERS DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well No. 1. Type of Well: Oil Well Gas Well X Other 2. Name of Operator 9. OGRID Number GRUY PETROLEUM MANAGEMENT CO. ATTN: DON ALDRIDGE 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 140907, IRVING, TEXAS 75014-0907 SHIPP STRAWN 4. Well Location 1980 Unit Letter I : feet from the SOUTH line and 660 feet from the line Township 178 Section Range 37E **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,764.1' GROUND LEVEL 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING CASING TEST AND **MULTIPLE** COMPLETION CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. CRUY PETROLEUM MANAGEMENT CO. REQUESTS APPROVAL TO PLUG AND ABANDON THE SUBJECT WELL PER NMCCD SPECIFICATIONS AS PER THE ATTAHCED PLUGGING PROCEDURE. IF YOU SHOULD HAVE ANY QUESTIONS OR COMMENTS PLEASE CONTACT DAVID EYLER @ 432-687-3033 THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BECHNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE. ACENT - TITLE-12/29/03 _DATE_

Telephone No.

DATE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

TITLE_

432-687-3033

'JAN 0 2 2004

Type or print name DAVID A. EYLER

(This space for State use)

Conditions of approval, if and

APPROVED BY

Gruy Petroleum Management Company

Byers #1

A.P.I. #: 30-025-29980

Lease Serial #:

Field: Shipp Strawn

Location: 1980' FSL & 660' FEL, Unit Letter I, Sec. 03, Twp. 17S, Rge. 37E

Lea County, New Mexico

Completion Date: 1987

Total Depth: 11,685' P.B.T.D.: CIBP @ 11,340' w/ 35' cement

Casing Data: 13-3/8" 48# @ 425' w/ 420 sxs. – Cement circulated to surface.

8-5/8" 28# S-80 @ 4210' w/ 1315 sxs. – TOC = 1100' (temp. survey) 5-1/2" 17# N-80 @ 11685' w/ 1445 sxs. – TOC = +/- 7800' (CBL)

Tubing Data: None

Rod Data:
Open Perfs:

None None

Remarks:

Perfs @ 11415'-11551' - CIBP @ 11340' w/35' cmt.

Sqz. csg. leaks: 5308'-5324' w/ 215 sxs. (04/96) Sqz. csg. leaks: 5816'-6382' w/ 200 sxs. (11/02) Unable to get below 6125' w/ 4.66" OD gauge ring.

PXA PROCEDURE

1) MIRU workover rig, PXA equipment and 11300' workstring.

- 2) ND wellhead and NU BOP's; PU & RIH w/ tubing & tag top of plug; Circulate well w/ PXA mud; POOH laying down tbg. to 7730'; Mix & pump a 25 sx. class "H" cmt. plug @ 7730'- 7830'(Tubb); POOH w/ tbg. standing back 4450' & laying down the balance.
- 3) ND BOP's & NU casing equip.; Work stretch on 5-1/2" csg.; RUWL & csg. cutter & RIH & cut 5-1/2" casing (est. csg. recovery @ 4210'); POOH & RDWL; POOH laying down 5-1/2" casing; ND csg. equip. & NU BOP's.
- 4) RIH w/ tbg. OE to 50' below csg. cut; Mix & pump a 200', 80 sx. class "H" cmt. plug 50' below csg. cut and 150' above 8-5/8" csg. shoe; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug; POOH laying down tbg. to 2150'; Mix & pump a 35 sx. class "H" cmt. plug 789 @ 2050'-2150' (Salt); POOH w/ tbg. standing back 250' & laying down the balance.
- 5) RUWL & RIH & perf. sqz. holes in 8-5/8" csg. @ 475'; POOH & RDWL; PU \$5/8" pkr RIH w/ pkr. & tbg. to 250'; Mix & sqz. a 100 sx. class "H" cmt. plug @ 375'-475' (FW)
- 6) Rel. pkr. & POOH w/ tbg. & pkr.; Remove pkr. & RIH w/ tubing OE to 63' & mix & pump a 20 sx. cmt. surf. plug @ 3'-63'; FOOH w/ tubing; PU & RIH w/ 1" tbg. to 63' in 8=5/8" X 13-3/8" annulus; Mix & pump a 20 sx. class "C" cmt. plug @ 3'-63'; POOH w/ 1" string
- 7) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 9) RDMO rig and PXA equipment. Clean location.

