

State of New Mexico
Energy, Minerals and Natural Resources

RECEIVED
JUL 20 2009
HOBBSOCD

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. ✓

30-025-11676

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Hadfield

8. Well Number

1

9. OGRID Number

192143

10. Pool name or Wildcat
Jalmat, Tan-Yates-7 Rivers

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Herman L. Loeb

3. Address of Operator

P O Box 838 Lawrenceville, IL 62439

4. Well Location

Unit Letter O : 660 feet from the South line and 1,980 feet from the East line
Section 21 Township 25S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3,054 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set cast iron bridge plug @ 2,630 ft. Pressure test casing to 500#. Run tubing to 2,630 ft. Spot balanced plug of 25 sk of cement. POH w/ 5 jts tubing. Mix & pump 50 bbl of mud (25 sk gel/100 bbl water). POH w/ tubing (lay down all but 35 jts).
2. Perforate 7" @ 1,250' w/ 4 holes. RIH w/ packer & tubing, set pkr @ 900'. Pump water, check for circulation between 7" and 8 5/8". Pump 100 sk cement or more if necessary. Displace cement to 1000 ft. SI WOC.
3. Release packer, RIH w/ tubing to tag cement. POH w/ tubing. Perforate 7" casing at 330'. Pump cement as necessary for top Plug to fill 7" from 330' to surface inside and outside.
4. Top off casing as necessary, cut off well head, weld plate, backfill and level location. Install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge.

The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operations

SIGNATURE

George A. Payne

TITLE

Petr. Engr.

DATE

7/15/09

Type or print name

George A. Payne

E-mail address:

gapayne@sigecon.net

PHONE:

(812) 453-0385

For State Use Only

APPROVED BY:

Marilyn Brown

TITLE

Compliance Officer

DATE

7/20/2009

Conditions of Approval (if any):

Lease: Hadfield
Well #: 1

Permit: 30-025-11676
Location: 660 FSL 1980 FEL 21-25S-37E
County: Lea
State: New Mexico
Field: Jalmat
Operator: Herman Loeb

Diagram: 07/14/2009
Elev KB: 0
TD: 3142

Comp Date: 02/23/1947
Elev GL: 3053
PBSD: 0

