Submit 3 Copies 10 Appropriate District	State of New Mex	X1CO	Form C-103
<ul><li>Office</li><li>District I</li></ul>	Energy, Minerals and Natur	ral Resources	May/27, 2004
1625 N. French Dr. Hobbs, NM 88240	-		WELL API NO.
District II  1301 W. Grand Ave., Artesia, NM  District III  1000 Rio Brazos Rd. Aztec NM 874104	CHOLL-CONSERVATION	DIVISION	30-025-35553
District III	1220 South St. Fran	ois Dr	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 874106 District IV	O turn C 4 E NIX 07	505	STATE FEE
District IV	0 χ(0)y Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa F	SOCO		
SUMDRY NOTIC	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS		JG BACK TO A	O W STATE
DIFFERENT RESERVOIR. USE "APPLIC			O W STATE
PROPOSALS.)		✓	8. Well Number
1. Type of Well: Oil Well	Gas Well 🖄 Other	,	a. Well Number
2. Name of Operator			9. OGRID Number
	PRODUCTION COMPANY, L	p /	6137
3. Address of Operator	TRODUCTION COMPANT, L	· ·	10. Pool name or Wildcat
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615			South Wilson Penn
• • • • • • • • • • • • • • • • • • • •	anoma City, OK 75102	403-332-4013	South Wison Felli
4. Well Location			
Unit Letter_P:	_660'feet from the _SOUTH_	line and <b>_660'_</b> _	_feet from theEASTline
Section 22	Township 21S R	Range 34E	NMPM County LEA
ACTION OF THE PARTY OF THE PART	11. Elevation (Show whether DR,		
	3697' GL	,,	The Material Property of the Control
Pit or Below-grade Tank Application on			
Pit type Depth to Groundwa	ter Distance from nearest fresh wa	oter well Dista	ince from negrest surface water
		<del></del>	
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Con	nstruction Material
12. Check A	ppropriate Box to Indicate Na	ature of Notice, I	Report or Other Data
			_
NOTICE OF IN	FENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS □	COMMENCE DRIL	LING OPNS.□ P AND A 🛛
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
<del></del>			_
OTHER:		OTHER:	
13. Describe proposed or compl	eted operations. (Clearly state all p	ertinent details, and	give pertinent dates, including estimated date
of starting any proposed wo	k). SEE RULE 1103. For Multiple	e Completions: Att	ach wellbore diagram of proposed completion
or recompletion.	_	_	
1. <u>7/16/09</u> MIRU. POOH v	// 2-3/8" production tubing.		Approved for plugging of well bore only.
2. Set CIBP @ 12,734'. Dur	np 36' cement on top.		Liability under bond is retained nending receipt
3. Circulate wellbore w/10	ppg mud.		of C-103 (Subsequent Report of Well Planning)
4. Spot 25 sx @ 11079' - 1	1282'		which may be found at OCD Web Page under
5. Spot 25 sx @ 9116' - 9319'. (DV tool @ 9269')			
5. Spot 25 sx @ 9116' - 93'	9'. (DV tool @ 9269')	:	Forms, www.cmnrd.state.nm.us/ocd.
6. Spot 25 sx @ 7951' - 81	<b>54</b> .		Forms, www.cmnrd.state.nm.us.ocd.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' – 60	64. 32'.  Tagged.  ( 9-5/8" shoe @ :	5982')	
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' – 60 8. Free point 5-1/2" casing	64. 32'.  Tagged.  ( 9-5/8" shoe @ @ 4500'.  Cut 5-1/2" casing @	5982') 2 4300'. POOH w	
<ul> <li>6. Spot 25 sx @ 7951' - 815</li> <li>7. Spot 25 sx @ 5761' - 60</li> <li>8. Free point 5-1/2" casing</li> <li>9. Spot 35 sx stub plug @</li> </ul>	64. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged.	5982') ) 4300'. POOH w	
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36	i4. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576')	) 4300'. POOH w	
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145	34. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 50'. Tagged. (13-3/8" shoe @	) 4300'. POOH w	
6. Spot 25 sx @ 7951' - 81! 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 14! 12. Spot 35 sx @ 392' - 500	34. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 50'. Tagged. (13-3/8" shoe @	) 4300'. POOH w	
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108	34. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 50'. Tagged. (13-3/8" shoe @ ' to surface.	) 4300'. POOH w 1400')	/casing.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108	34. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 50'. Tagged. (13-3/8" shoe @	) 4300'. POOH w 1400')	/casing.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108	34. 32'. Tagged. ( 9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 50'. Tagged. (13-3/8" shoe @ ' to surface.	) 4300'. POOH w 1400')	/casing.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	44. 32'. Tagged. (9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 0'. Tagged. (13-3/8" shoe @ ' to surface. f. Set dry hole marker. Wellb	9 4300'. POOH w 1400') ore plugged & al	casing.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	44. 32'. Tagged. (9-5/8" shoe @	1400') ore plugged & at	casing.  candoned.  and belief. I further certify that any pit or below-
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	44. 32'. Tagged. (9-5/8" shoe @	1400') ore plugged & at	casing.
6. Spot 25 sx @ 7951' - 81! 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 14! 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	34. 32'. Tagged. (9-5/8" shoe @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @ 'to surface. 31' to surface. 32' to surface. 33' to surface. 34' to surface. 35' to surface. 36' to surface.	1400') ore plugged & at st of my knowledge	Casing.  Dandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	44. 32'. Tagged. (9-5/8" shoe @	1400') ore plugged & at	Casing.  Dandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	32'. Tagged. (9-5/8" shoe @ 4500'. Cut 5-1/2" casing @ 4229' - 4354'. Tagged. (26'. (DV tool @ 3576') (26'. Tagged. (13-3/8" shoe @ 4.5') to surface. (15.5 Set dry hole marker. Wellb bove is true and complete to the belosed according to NMOCD guidelines.	1400')  ore plugged & alest of my knowledge  a general permit   Engineering Tech	Casing.  Dandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.  InicianDATE8/6/09
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of  I hereby certify that the information a grade tank has been/will be constructed or c	34. 32'. Tagged. (9-5/8" shoe @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @ 'to surface. 31' to surface. 32' to surface. 33' to surface. 34' to surface. 35' to surface. 36' to surface.	1400')  ore plugged & alest of my knowledge  a general permit   Engineering Tech	Casing.  Dandoned.  and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan □.  InicianDATE8/6/09
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of	32'. Tagged. (9-5/8" shoe @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @  'to surface. f. Set dry hole marker. Wellb bove is true and complete to the be losed according to NMOCD guidelines   E-mail address: Ro	1400')  ore plugged & all  st of my knowledge  ], a general permit   Engineering Tech  onnie.Slack@dvn.c	oandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.  inician DATE _8/6/09  om Telephone No. 405-552-4615
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of  I hereby certify that the information a grade tank has been/will be constructed or of  SIGNATURE  Type or print name  Ronnie Slack For State Use Only	32'. Tagged. (9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' - 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @  'to surface. f. Set dry hole marker. Wellb bove is true and complete to the be losed according to NMOCD guidelines	1400')  ore plugged & alest of my knowledge  a general permit   Engineering Tech	oandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.  mician DATE 8/6/09  om Telephone No. 405-552-4615
6. Spot 25 sx @ 7951' - 815 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 145 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of  I hereby certify that the information a grade tank has been/will be constructed or c	32'. Tagged. (9-5/8" shoe @ 4500'. Cut 5-1/2" casing @ 4229' – 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @  'to surface. f. Set dry hole marker. Wellb bove is true and complete to the be losed according to NMOCD guidelines   E-mail address: Ro	1400')  ore plugged & all  st of my knowledge  ], a general permit   Engineering Tech  onnie.Slack@dvn.c	oandoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.  inician DATE _8/6/09  om Telephone No. 405-552-4615
6. Spot 25 sx @ 7951' - 81! 7. Spot 25 sx @ 5761' - 60 8. Free point 5-1/2" casing 9. Spot 35 sx stub plug @ 10. Spot 35 sx @ 3518' - 36 11. Spot 35 sx @ 1340' - 14! 12. Spot 35 sx @ 392' - 500 13. Circulate 35 sx from 108 14. 8/6/09— Cut wellhead of  I hereby certify that the information a grade tank has been/will be constructed or of  SIGNATURE  Type or print name  Ronnie Slack For State Use Only  APPROVED BY:	32'. Tagged. (9-5/8" shoe @ @ 4500'. Cut 5-1/2" casing @ 4229' - 4354'. Tagged. 26'. (DV tool @ 3576') 30'. Tagged. (13-3/8" shoe @  'to surface. f. Set dry hole marker. Wellb bove is true and complete to the be losed according to NMOCD guidelines	1400')  ore plugged & all  st of my knowledge  ], a general permit   Engineering Tech  onnie.Slack@dvn.c	casing.  candoned.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan □.  mician DATE8/6/09  om Telephone No. 405-552-4615

