Submit 3 Copies To Appropriate District State of New Mexi		
<u>District I</u> Energy, Minerals and Natural	WELL API NO.	
District II	30-025-33598	
District III	is Dr. 5. Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 882 Co. 1101 Control 1220 South St. Franci 1000 Rio Brazos Rd, Aztec, NM 8741 SEP 0, 1 2009 Santa Fe, NM 8750 District IV District IV	05 6. State Oil & Gas Lease No.	
1220 S St Francis Dr, Santa Fe, NHOBBSOCD		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR		
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 6	
2. Name of Operator	9. OGRID Number 4323	
CHEVRON USA INC	10. Dect nome on Wildert	
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705	10. Pool name or Wildcat MONUMENT ABO	
4. Well Location		
Unit Letter M: 410 feet from the SOUTH line and 330 feet from the WEST line		
Section 26 Township 19-S Range 36-E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	REMEDIAL WORK Image: Altering Casing Image: Altering Image: Altering Casing Image: A	
OTHER: INTENT TO C/O, ADD PAY & REPL PUMP OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
or recompletion.		
CHEVRON U.S.A. INC. INTENDS TO CLEAN OUT WELLBORE, ADD PERFS, & REPLACE SUB PUMP.		
THE INTENDED PROCEDURE, AND CURRENT AND PROPOSED WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL, AS WELL AS THE C-144 PIT INFO.		
Spud Date: Rig Release Date:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE MUSE WILLE FATIFLE REGULATORY SPECIALIST DATE 08-28-2009		
Type or print name DENISE PINKERTON E-mail address: leakejd@chevron.com PHONE: 432-687-7375		
For State Use Only		
APPROVED BY:		
Conditions of Approval (IFany):		

,

.

Procedure:

.

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 7/28/2009. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and **open valve** at header. Document this process in the morning report.
- 3. MI & RU workover unit. Bleed pressure from well, if any. Pump down csg with fresh water, if necessary to kill well. Remove WH. Install BOP's and test as required. <u>Note:</u> Tbg or sub pump is stuck at an unknown depth.
- 4. MI & RU pump trucks. Pump down casing with 3000 gals NEFE 15% HCl acid at 2 BPM and 2000 psi maximum surface pressure. Flush acid down casing with 100 bbls fresh water at 2 BPM and 2000 psi surface pressure. Shut well in and let acid soak for 2 hours. RD and release pump trucks. Open well. PU on tbg and determine if tbg and/or sub pump is still stuck.
- 5. MI & RU electric line unit. GIH and conduct free point of 2 3/8" tbg. Make jet cut above stuck point. POH with jet cutter. RD and release electric line unit. POH with 2 3/8" tbg string and sub pump cable.
- 6. PU & GIH with 4 ¹/₂" overshot, DC's and jars on 2 7/8" work string to top of cut tbg joint. Engage fish and jar free. POH with work string and fish. LD fish, overshot, DC's and jars.
- PU and GIH with 4 ³/₄" MT bit and scraper on 2 7/8" work string to 7500'. Reverse circulate well clean from 7500' using 8.6 PPG cut brine water. POH with work string, bit, and scraper. LD bit and scraper. Note: If well will not circulate, use air unit to clean out fill.
- MI & RU Baker Atlas electric line unit. Install lubricator and test to 2000 psi. GIH with 3 3/8" RHSC Titan EXP-3325-321T casing guns (0.42" EH & 47" penetration) and perforate from 7070-74', 7084-90', 7096-7102', 7106-12', 7136-42', 7348-56', and 7364-72' with 2 JSPF at 120 degree phasing, using 25 gram premium charges. POH. RD & release electric line unit. Note: Use casing collars from Schlumberger GR/CBL/CCL Log dated 11/18/96 for depth correction.

- 9. PU and GIH w/ 5 ¹/₂" treating pkr on 2 7/8" work string to approximately 6900'. Test tbg to 6000 psi while GIH.
- 10. Acidize perfs 7070-7420' with 5,000 gals regular antisludge 20% HCl acid ** at a maximum rate of 5 BPM and a maximum surface pressure of 5500 psi. Spot acid to bottom of 2 7/8" tbg. Displace acid with 8.6 PPG cut brine water -- do not overdisplace. Drop 350 1.3 sp.gr. ball sealers evenly dispersed throughout acid. Record ISIP, 5, 10, & 15 minute SIP's. RD & release DS Services.

** Acid system is to contain:	1 GPT A264	Corrosion Inhibitor
	8 GPT L63	Iron Control Agent
	2 PPT A179	Iron Control Aid
	20 GPT U66	Mutual Solvent
	2 GPT W53	Non-Emulsifier

- 11. Bleed off pressure. Release pkr. LD to 7420' with pkr to wipe balls off perfs. PUH and reset pkr at 6900'.
- **12.** GIH and swab back all intervals together. Recover 100% of treatment and load volumes before shutting well in for night, if possible. Report recovered fluid volumes, pressures, and/or swabbing fluid levels.
- 13. Open well. MI & RU pump trucks. Pump down tbg with:

.

ι.

30 bbls fresh water containing 20 gals Baker XCIDE-302 at **5 BPM** 120 bbls fresh water containing 275 gals Baker XC-120 at **5 BPM**.

Displace solutions down 2 7/8" work string with 300 bbls 8.6 PPG cut brine water at **5 BPM** and **2500 psi maximum pressure**. RD and release pump trucks. <u>Shut well in overnight for treatment to soak.</u>

- 14. Open well. Release pkr. POH with 2 7/8" work string. LD 2 7/8" work string and packer.
- 15. PU and GIH w/ Centrilift sub pump assembly (with 5/8" OD Inplex capillary string), drain sub, 2 3/8" x 6' IPC/EPC tbg sub, SN, 67 jts 2 3/8" EUE 8R J-55 IPC/EPC tbg and 150 jts 2 3/8" EUE 8R J-55 IPC tbg, testing to 5500 psi. Suspend tbg with bottom of sub pump assembly at approximately 7000'. Note: Sub pump and bottom of tbg string will be in extremely corrosive environment. Entire sub pump assembly and bottom 1500' of cable must be monel coated. Also, bottom 67 jts of 2 3/8" tbg string will be externally coated with Ryt-Wrap and entire tbg string will be IPC. Additionally, 7000' of 5/8" OD Inplex capillary injection tubing will be run and banded to the outside of the 2 3/8" OD production tubing string.

- 16. Remove BOP's and install WH. MI & RU pump truck. Pump down tbg with 30 bbls fresh water containing 20 gals WCW-2827 surfactant. RD and release pump truck. RD & release pulling unit.
- 17. Turn well over to production. Connect continous injection chemical to capillary injection tbg. Contact Dexter Nichols and initiate chemical treating program on well.

.

AMH 8/21/2009

•

,

WELL DATA SHEET CURRENT

.



FORMATION: Abo

WELL DATA SHEET PROPOSED

