State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE QIL CONSERVATION DIVISION	
DISTRICT I 1625 N French Dr., Hobbs, NM 88240 DISTRICT I Santa Fe, NM 87505	WELL API NO. 30-025-35541
DISTRICT II SEP 2:5 2009	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210 DISTRICT III	STATE X FEE
	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 29
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 533
2. Name of Operator	9. OGRID No 157984
Occidental Permian Ltd.	10. Pool name or Wildcat Hobbs (G/SA)
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323	1000s (G/SA)
4 Well Location	
Journal Journa	et From The East Line
Section 29 Township 18-S Range 38-F	E NMPM Lea County
3646' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C NOTICE OF INTENTION TO: SUBS	Other Data SEQUENT REPORT OF:
	SEGUENT REFURT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING .
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	ALTERING CASING NS PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS PLUG & ABANDONMENT NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Casing Leak	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X I, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X I, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X I, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In the plug and
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In the plug and
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In the plug & ABANDONMENT X In the plug & ABANDONMENT X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8'' casing. Sting out of retainer. POOH with setting tool.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In 10# brine. See a packer.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8" casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In 10# brine. See a packer.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8'' casing. Sting out of retainer. POOH with setting tool.	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X Including estimated date of starting any completion or recompletion. In 10# brine. See a packer.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8" casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1	ALTERING CASING PLUG & ABANDONMENT Repair Repair Repair Repair Repair X. 1. 1. 2. 3. Including estimated date of starting any completion or recompletion. 2. 3. 3. 4. 5. Including estimated date of starting any completion or recompletion. 3. 4. 5. 6. 7. 8. 8. 9. 8. 9. 9. 1. 1. 1. 1. 1. 1. 1. 1
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP CASING TEST AND CEMENOTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8'' casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1 **** see additional data on attached sheet*** 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or	ALTERING CASING PLUG & ABANDONMENT Repair R
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug. 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8" casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1 *** see additional data on attached sheet***	ALTERING CASING PLUG & ABANDONMENT Repair R
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8'' casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1 **** see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative or an (attached) alternative or an (attached) alternative or an extrached sheet***	ALTERING CASING NS PLUG & ABANDONMENT NT JOB Repair X. Including estimated date of starting any completion or recompletion. In 10# brine. See a packer. See a packe
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8" casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1 **** see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT Repair R
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. RU wireline & tag tubing @2500'. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bb. 3. RU wireline & perforate tubing @4025'. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850'. Test casing. Lost 150 PSI. POOH w/plug 7. RIH w/CIBP set @4000'. RU wireline & perforate squeeze holes @1300'. RD wireline. 8. RIH w/Halliburton CR @1186'. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8" casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186'. RU power swivel. Drill on CR and cement from 1186-1 **** see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TTILE Administrative or an mendy johnson@oxy.com	ALTERING CASING NS PLUG & ABANDONMENT AT JOB Repair S, including estimated date of starting any completion or recompletion. DI 10# brine. See Packer. See
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Casing Leak 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed R. RUPU & RU. RU wireline & tag tubing @2500°. 2. Pump 500 gal of Xylene down casing. Flush w/70 bbl 10# brine. Circ chem out of well w/140 bt RU wireline & perforate tubing @4025°. 4. NU BOP. 5. POOH w/ESP equipment. 6. RIH w/RBP & Arrowset packer. Packer set @3850°. Test casing. Lost 150 PSI. POOH w/plug RIH w/CIBP set @4000°. RU wireline & perforate squeeze holes @1300°. RD wireline. 8. RIH w/Halliburton CR @1186°. Circulate 275 sks of Class C cement w/2% cal chloride around 8 & 8-5/8° casing. Sting out of retainer. POOH with setting tool. 9. RIH w/bit & drill collars. Tag @1186°. RU power swivel. Drill on CR and cement from 1186-1 **** see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TITLE Administrative TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	ALTERING CASING NS PLUG & ABANDONMENT A Repair A Including estimated date of starting any completion or recompletion. DI 10# brine. A spacker. -5/8" surface casing and 187 sks between 5-1/2" 311' Circ clean. Test casing. OK. That any pit or below-grade tank has been/will be the OCD-approved Associate DATE 09/22/2009 TELEPHONE NO. 806-592-6280

NHU 29-533

- 10. Continue in hole w/bit & drill collars to 4000'. RU power swivel & drill out CIBP. Push plug to 4221'. Clean out asphaltenes & barium scale to 4312'. Circ Clean. RD power swivel. POOH w/bit & drill collars.
- 11. RIH w/ESP equipment on 2-7/8" tubing. Intake set @4041'.
- 12. ND BOP/NU wellhead.
- 13. RDPU & RU. Clean location.

RUPU 06/22/09 RDPU 07/01/09