State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

DISTRICT I	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 RECEIVED 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-05499
DISTRICT II	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210 SEP 2 9 2009	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 HOBBSOCD	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 25
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 441
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd. 3. Address of Operator	10. Pool name or Wildcat (Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	110000 (0/5:1)
4. Well Location	,
South 1 770 South South	eet From The East Line
Section 25 Township 18-S Range 37	-E NMPM Lea County
3667' DF	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	
	/Deepen/Acid Treat X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dat proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	
proposed work) SEE RULE 1103. For Multiple Completions. Attach wendore diagram of proposed	Loomplotion or recompletion
	l completion or recompletion.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. 	l completion or recompletion.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. 	I completion or recompletion.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. 	
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 	
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 	'. Tag CIBP. Circ clean. Cleanout well from
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 	'. Tag CIBP. Circ clean. Cleanout well from k & bad casing @4151-4166'. RD power swivel.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr 	'. Tag CIBP. Circ clean. Cleanout well from k & bad casing @4151-4166'. RD power swivel.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 	'. Tag CIBP. Circ clean. Cleanout well from k & bad casing @4151-4166'. RD power swivel.
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr swivel & striper head. POOH w/bit & drill collars. ****see attached sheet for additional data***	'. Tag CIBP. Circ clean. Cleanout well from k & bad casing @4151-4166'. RD power swivel. ill new formation from 4193-4260'. RD power
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr swivel & striper head. POOH w/bit & drill collars. ****see attached sheet for additional data***	'. Tag CIBP. Circ clean. Cleanout well from ik & bad casing @4151-4166'. RD power swivel. ill new formation from 4193-4260'. RD power by that any pit or below-grade tank has been/will be
1. RUPU & RU. RU wireline and set plug in packer @3990'. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4120'. 5. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. 6. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 8. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr swivel & stripper head. POOH w/bit & drill collars. ***see attached sheet for additional data*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation	'. Tag CIBP. Circ clean. Cleanout well from the well shad casing @4151-4166'. RD power swivel. The switch shad casing with the well shad case with the well shad cas
 RUPU & RU. RU wireline and set plug in packer @3990'. ND wellhead/NU BOP. POOH w/tubing and packer. RIH w/bit. Tag @4120'. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr swivel & striper head. POOH w/bit & drill collars. ****see attached sheet for additional data***	2. Tag CIBP. Circ clean. Cleanout well from alk & bad casing @4151-4166'. RD power swivel. ill new formation from 4193-4260'. RD power by that any pit or below-grade tank has been/will be ve OCD-approved
1. RUPU & RU. RU wireline and set plug in packer @3990'. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4120'. 5. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. 6. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 8. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Do swivel & striper head. POOH w/bit & drill collars. ***see attached sheet for additional data*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation plan	2. Tag CIBP. Circ clean. Cleanout well from alk & bad casing @4151-4166'. RD power swivel. ill new formation from 4193-4260'. RD power by that any pit or below-grade tank has been/will be ve OCD-approved Be Associate DATE 09/24/2009
1. RUPU & RU. RU wireline and set plug in packer @3990'. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4120'. 5. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. 6. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 8. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr. swivel & striper head. POOH w/bit & drill collars. ***see attached sheet for additional data*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.co	2. Tag CIBP. Circ clean. Cleanout well from alk & bad casing @4151-4166'. RD power swivel. Fill new formation from 4193-4260'. RD power by that any pit or below-grade tank has been/will be to ocd-approved Be Associate DATE 09/24/2009 TELEPHONE NO 806-592-6280
1. RUPU & RU. RU wireline and set plug in packer @3990'. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4120'. 5. RU power swivel. Clean out iron sulfide & pump out plug to 4130'. Drill cement at 4130-4149 4149-4151'. Found cement and casing in returns. RD power swivel & POOH w/bit. 6. RIH w/Kutrite shoe and drill collars to 4050'. RU power swivel & stripper head. Wash over jur 7. RU wireline & perforate tubing @3600'. POOH w/Kutrite shoe & drill collars. 8. RIH w/bit. Tag @4162'. RU stripper head & power swivel. Drill cement from 4162-4193'. Dr swivel & striper head. POOH w/bit & drill collars. ***see attached sheet for additional data*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy johnson@oxy.co	2. Tag CIBP. Circ clean. Cleanout well from sk & bad casing @4151-4166'. RD power swivel. ill new formation from 4193-4260'. RD power by that any pit or below-grade tank has been/will be ve OCD-approved Be Associate DATE09/24/2009

NHU 25-441

- 9. RIH w/treating packer set @4250. RU HES & pump 1084 gal of 15% NEFE acid in 2 stages of gelled brine. Flush w/25 bbl of 10# brine. RD HES. POOH w/treating packer.
- 10. RIH w/Arrow Set 1-X Dbl Grip packer on 125 jt of 2-7/8" Duoline tubing. Packer set @3964'.
- 11. ND BOP/NU wellhead.
- 12. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. Robet Harrison w/NMOCD on site for test.
- 13. RDPU & RU. Clean location.

RUPU 07/21/09 RDPU 07/30/09

