State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		/
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr.		WELL API NO. 30-025-07077	
DISTRICT II SED 2 O 2000		5 Indicate Type of Lease		
		STATE 6. State Oil & Gas Lease No.	FEE X	
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	HOBBSOCD		6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit		
	APPLICATION FOR PERMIT" (Form C-10	01) for such proposals.)	Section 30 8. Well No 111	
1. Type of Well [.] Oil Well	Gas Well Other Inj	ector	***	/
Name of Operator Occidental Permian Ltd.	_		9. OGRID No. 157984	/
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, T.	X 79323			
4. Well Location Unit Letter D : 330	Feet From The North	_330 Fee	t From The West	Line
Section 30	Township 18-S	Range 38-E	NMPM	Lea County
	11. Elevation (Show whether DF, RK 3650' GR	B, RT GR, etc.)		
Pit or Below-grade Tank Application	or Closure	,		
Pit Type Depth of Grou	1 1 1	earest fresh water well	Distance from nearest su	rface water
Pit Liner Thickness mil	Below-Grade Tank: Volume			
12. Che NOTICE OF IN	ck Appropriate Box to Indicate Nat FENTION TO:		other Data SEQUENT REPORT OF	F:
DEDECOM DEMEDIAL WORK	PLUG AND ABANDON			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI		BANDONMENT
			NS. PLUG & A	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPI	NS. PLUG & A	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates	NS. PLUG & A IT JOB Perf/Acid Treat , including estimated date of s	BANDONMENT X.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103	CHANGE PLANS Multiple Completion	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates	NS. PLUG & A IT JOB Perf/Acid Treat , including estimated date of s	BANDONMENT X.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates	NS. PLUG & A IT JOB Perf/Acid Treat , including estimated date of s	BANDONMENT X.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates ellbore diagram of proposed of	NS. PLUG & A IT JOB Perf/Acid Treat , including estimated date of s	BANDONMENT X.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates ellbore diagram of proposed of	PLUG & A OPET / Acid Treat Including estimated date of secompletion or recompletion.	tarting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Futails, and give pertinent dates ellbore diagram of proposed of	PLUG & A OPET / Acid Treat Including estimated date of secompletion or recompletion.	tarting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oproposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitails, and give pertinent dates ellbore diagram of proposed converse of the conv	PLUG & A T JOB Perf/Acid Treat including estimated date of sempletion or recompletion. D power swivel & stripper h	tarting any
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitails, and give pertinent dates ellbore diagram of proposed contact of the cont	PLUG & A T JOB Perf/Acid Treat Perf/Acid Treat Including estimated date of secompletion or recompletion. Proposed Stripper has been been been been been been been bee	tarting any nead. o CR. Pump 11 bbl
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Oproposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitails, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Region of CR. Spot 20 bbl of Clean out pea gravel to 427	Perf/Acid Treat	tarting any nead.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitails, and give pertinent dates ellbore diagram of proposed contact of the cont	Perf/Acid Treat	tarting any nead.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. **	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Regiout of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additional comments.	Perf/Acid Treat Perf/Acid Treat In Job Perf/Acid Treat In including estimated date of stompletion or recompletion. In power swivel & stripper have been down the strip	tarting any nead. o CR. Pump 11 bbl el & stripper head.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowledge.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Region of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additional codes and belief. I further certify	Perf/Acid Treat Perf/A	tarting any nead. o CR. Pump 11 bbl el & stripper head.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowledge.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Regiout of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additional comments.	Perf/Acid Treat Perf/A	tarting any nead. o CR. Pump 11 bbl el & stripper head.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed Or proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowledge.	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of the company of t	Perf/Acid Treat Perf/A	tarting any nead. o CR. Pump 11 bbl el & stripper head.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine I hereby certify that the information above is constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowless , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalis, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Reg out of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additional edge and belief. I further certify or an (attached) alternative plan	Perf/Acid Treat Perf/Acid Treat In Job Perf/Acid Treat In including estimated date of state of stat	tarting any nead. o CR. Pump 11 bbl el & stripper head. as been/will be
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine I hereby certify that the information above is constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A. For State Use Only	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowled to the best of my knowle	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Region of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additedge and belief. I further certify or an (attached) alternative plan TITLE Administrative mendy johnson@oxy.com	Perf/Acid Treat Perf/A	tarting any Tarti
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe Proposed or Completed O proposed work) SEE RULE 1103 1. RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. Dump 13 buckets of gravel down 5. RU power swivel & stripper head 6. POOH w/noch collar. 7. RIH w/CR. RU HES & pump 25 cmet. Reverse out 24 bbl of cement. 8. RU swivel & stripper head. Drill Circ clean w/45 bbl of brine I hereby certify that the information above is constructed or closed according to NMOCD guideline SIGNATURE TYPE OR PRINT NAME Mendy A.	CHANGE PLANS Multiple Completion perations (Clearly state all pertinent de For Multiple Completions: Attach w csg. RIH w/noch collar, tag @4151' Break circulation and clean out gr bbl of fresh water to clean tbg. Sting RD HES & pullout of hole. out cement & CR from 3994-4185'. ** strue and complete to the best of my knowled to the best of my knowle	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Plug back/Fitalls, and give pertinent dates ellbore diagram of proposed of avel from 5151 to 4177'. Region of CR. Spot 20 bbl of Clean out pea gravel to 427 *see attached sheet for additedge and belief. I further certify or an (attached) alternative plan TITLE Administrative mendy johnson@oxy.com	Perf/Acid Treat Perf/Acid Treat In Job Perf/Acid Treat In including estimated date of state of stat	tarting any tarting any nead. o CR. Pump 11 bbl el & stripper head. as been/will be 09/23/2009 806-592-6280

NHU 30-111

- 9. RU wireline and perforate hole @4170-80-87-92; 4220-30 at 1 JSPF. RD wireline.
- 10. RU HES & spot 15 bbl of 15% acid & 8 bbl of 10# brine. Pump acid to break perfs. Flush w/30 bbl of 10# brine. RD HES.
- 11. RIH w/dual packers on 126 jts of 2-7/8" Duoline 20 tubing. Packers set @3990 (Arrowset 1-X Dbl Grip) and 4125' (KTC Hydraulice).
- 12. ND BOP/NU wellhead & injection tree.
- 13. Test casing to 600 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD on site for test.
- 14. RDPU & RU. Clean location.

RUPU 07/15/09 RDPU 07/23/09

