State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-025-37101
DISTRICT II SEP 2 9 2009	5 Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 24
1. Type of Well: Oil Well Gas Well Other Injector	8. Well No. 637
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd. 3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR I Box 90 Denver City, TX 79323	
4 Well Location	, and the second se
Unit Letter B 1268 Feet From The South 1455 Feet	et From The <u>East</u> Line
Section 24 Township 18-S Range 37-E NMPM Lea County	
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3671' GR	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or	
NOTICE OF INTENTION TO:	SEQUENT REPORT OF:
	[]
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	PNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	PNS. PLUG & ABANDONMENT NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Ac	PNS. PLUG & ABANDONMENT NT JOB X
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: OTHER: Perforate/Acc 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates	PNS. PLUG & ABANDONMENT NT JOB cid treat x, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Ac	PNS. PLUG & ABANDONMENT NT JOB cid treat x, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP.	PNS. PLUG & ABANDONMENT NT JOB cid treat x, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Perforate/Act 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer.	PNS. PLUG & ABANDONMENT NT JOB cid treat x, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP.	PNS. PLUG & ABANDONMENT NT JOB cid treat x, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Act OTHER: Perforate/	PNS. PLUG & ABANDONMENT NT JOB Cid treat S, including estimated date of starting any completion or recompletion. POOH w/SPA packer.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Additional Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. 5. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. 7. RIH w/dual packers set on 125 jts of 2-7/8'' Duoline 20 tubing. Packers set @4103' (Arrow-set)	PNS. PLUG & ABANDONMENT NT JOB Cid treat S, including estimated date of starting any completion or recompletion. POOH w/SPA packer.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Additional Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. 5. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. 7. RIH w/dual packers set on 125 jts of 2-7/8" Duoline 20 tubing. Packers set @4103' (Arrow-set 8. ND BOP/NU wellhead. 9. Test casing to 510 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD of the completion of	PNS. PLUG & ABANDONMENT NT JOB Cid treat S, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic).
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Additional Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. 5. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. RIH w/dual packers set on 125 jts of 2-7/8'' Duoline 20 tubing. Packers set @4103' (Arrow-set 8. ND BOP/NU wellhead. 9. Test casing to 510 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD on 10. RDPU & RU. Clean location.	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. //bit. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). n site for test.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. S. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. RIH w/dual packers set on 125 jts of 2-7/8'' Duoline 20 tubing. Packers set @4103' (Arrow-set 8. ND BOP/NU wellhead. 9. Test casing to 510 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD on 10. RDPU & RU. Clean location.	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. //bit. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). n site for test.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH with the set of my set of the set of my set of the set of my knowledge and belief. I further certify I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. //bit. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). n site for test.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action Differs: OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH well be set of more proposed in the set of more proposed. RUPU as a setting of the set of more proposed in the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed in the set of more proposed. RUPU as a setting of the set of more proposed. RUPU as a setting of the set of more proposed in the set of more proposed. RUPU as a setting of the set of more proposed in the set of more proposed. RUPU as a setting of the set of more proposed in the set of more proposed. RUPU as a set of more proposed in the set of more proposed. RUPU as a set of more proposed in the set of more prop	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). In site for test. 08/10/09 that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action of the Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. S. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. RIH w/dual packers set on 125 jts of 2-7/8" Duoline 20 tubing. Packers set @4103' (Arrow-set 8. ND BOP/NU wellhead. 9. Test casing to 510 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD on 10. RDPU & RU. Clean location. RUPU 08/03/09 RDPU Constructed or closed according to NMOCD guidelines and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines are general permit or an (attached) alternative plan.	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). In site for test. 08/10/09 that any pit or below-grade tank has been/will be e OCD-approved
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: OTHER: Perforate/Action Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH w. S. RU wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. R.	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). In site for test. 08/10/09 that any pit or below-grade tank has been/will be e OCD-approved Associate DATE PLUG & ABANDONMENT X ABANDONMENT ABAND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Perforate/Action of the Pull of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of the Perforate of CASING TEST AND CEMENT OTHER: Perforate/Action of CASING TEST AND CEMENT OTHER: Perfora	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). In site for test. 08/10/09 that any pit or below-grade tank has been/will be e OCD-approved Associate DATE TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: OTHER: Perforate/Action of Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. RUPU & RU. Kill well. RU wireline and set blanking plug. 2. ND wellhead/NU BOP. 3. POOH w/tubing and packer. 4. RIH w/bit. Tag @4377'. Pump 12 bbl 12.5# mud down casing and 4 bbl down tubing. POOH wireline & perforate hole @4234-45, 56-60, 76-85' @2 JSPF. RD wireline. 6. RIH w/SPA packer set @4303'. RU HES. Pump 45 bbl of 15% NEFE in 3 settings. RD HES. F. RIH w/dual packers set on 125 jts of 2-7/8" Duoline 20 tubing. Packers set @4103' (Arrow-set ND BOP/NU wellhead. 9. Test casing to 510 PSI for 30 minutes and chart for the NMOCD. Robert Harrison w/NMOCD on 10. RDPU & RU. Clean location. RUPU 08/03/09 RDPU of 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines are general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.com	PLUG & ABANDONMENT NT JOB cid treat x s, including estimated date of starting any completion or recompletion. POOH w/SPA packer. 1-X Dbl grip) and 4172' (KTC Hydraulic). In site for test. 08/10/09 that any pit or below-grade tank has been/will be e OCD-approved Associate DATE TELEPHONE NO. 806-592-6280

