Submit 3 Copies To Appropriate District State of New Mexico	Form C-103 May 27, 2004
Office Energy, Minerals and Natural Resources	S WELL API NO.
1625 N. French Dr., Hobbs, NM 88240	30-025-03011
District II 1301 W. Grand Ave., Artesia, NM 88210 District III OIL CONSERVATION DIVISION OCT 0912200 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	8. Well number 5
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number
ConocoPhillips Company ATTN: Donna Williams	217817
3. Address of Operator P.O. Box 51810 Midland, TX 79710-1810	10. Pool name or Wildcat Vacuum Abo Reef
4. Well Location	
Unit Letter M_: 330_ feet from the South line and 3	
Section 34 Township 17-S Range 35-E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GI	R, etc.)
Pit or Below-grade Tank Application 🖾 or Closure	
	Distance from nearest surface water
	bis; Construction MaterialSTEEL
Pit Liner Thickness: STEEL mil Below-Grade Tank: Volume 180 bi 12. Check Appropriate Box to Indicate Nature of No	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CE	WORK ALTERING CASING ALTERING ALTERI
TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. OTHER: (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of the second sec	E DRILLING OPNS. PANDA
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: COMPLETE Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of a (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. 	E DRILLING OPNS. PANDA
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: COMPLETE Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of a 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not p of a and at a 3 220'. Spot 25sx cmt w/ 2% CaCL. Calc TOC @ 2,973'. Tag (6) 	E DRILLING OPNS. PANDA EMENT JOB
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: COMPLETE Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not provide the start of t	E DRILLING OPNS. PANDA EMENT JOB
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: COMPLETE Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of 0 (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not provide to 1,659'. Spot 25sx cmt. Calc TOC @ 1,412'. Tag @ 1,417'. 	E DRILLING OPNS. PANDA EMENT JOB PANDA Similar and give pertinent dates, including estimated da ns: Attach wellbore diagram of proposed completion existing CIBP @ 8,595'. Calc TOC @ 8,342'. get inj rate. OK'd w/ Robert-OCD to RIH w/ the 2,970'. get inj rate. OK'd w/ Robert-OCD to RIH w/ The 2,970'.
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: COMPLETE Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not provide the start of t	E DRILLING OPNS. PANDA EMENT JOB PANDA Similar and give pertinent dates, including estimated da ns: Attach wellbore diagram of proposed completion existing CIBP @ 8,595'. Calc TOC @ 8,342'. get inj rate. OK'd w/ Robert-OCD to RIH w/ the 2,970'. get inj rate. OK'd w/ Robert-OCD to RIH w/ The 2,970'.
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of a 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. The sure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. The sure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out and perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out and performance. 	E DRILLING OPNS. PANDA EMENT JOB PANDA Similar and give pertinent dates, including estimated da ns: Attach wellbore diagram of proposed completion existing CIBP @ 8,595'. Calc TOC @ 8,342'. get inj rate. OK'd w/ Robert-OCD to RIH w/ the 2,970'. get inj rate. OK'd w/ Robert-OCD to RIH w/ The 2,970'.
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of a 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. The sure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. The sure to 1000 psi, could not perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out and perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out and performance. 	E DRILLING OPNS. P AND A EMENT JOB
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not f (5) ended to 3,220'. Spot 25sx cmt. Calc TOC @ 1,407'. 7/13/09 Perf @ 1,609'. PKR @ 1,215'. Pressure to 1000 psi, could not f (6) ended to 1,659', spot 25sx cmt. Calc TOC @ 1,412', Tag @ 1,417'. 7/14/09 Perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out (7) RDMO. 	E DRILLING OPNS. P AND A EMENT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of 0 (3) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not f (5) ended to 3,220'. Spot 25sx cmt. Calc TOC @ 1,412', Tag @ 1,417'. 7/14/09 Perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out of 0 (6) ended to 1,659', spot 25sx cmt. Calc TOC @ 1,412', Tag @ 1,417'. 7/14/09 Perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out of 0 (7) RDMO. I hereby certify that the information above is true and complete to the best of my knograde tank has been/will be constructed or closed according to NMOCD guidelines 🖾, a general performance on the formation above is true and complete to the best of my knograde tank has been/will be constructed or closed according to NMOCD guidelines 🖾, a general performance on the formation above is true and complete to the best of my knograde tank has be	E DRILLING OPNS. P AND A EMENT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPL CASING/CE OTHER: Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. (1) (1) 7/9/09 Notify Robert w/ OCD of MIRU (2) 7/10/09 Tbg @ 8,595'. Circ hole w/ 10# MLF. Spot 25sx cmt on top of (3) (2) 7/10/09 Tbg @ 6,270'. Spot 25sx cmt. Calc TOC @ 6,017'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. (4) 7/10/09 Tbg @ 4,513'. Spot 50sx cmt. Calc TOC @ 4,007'. 7/13/09 Perf @ 3,170'. PKR @ 1,600'. Pressure to 1000 psi, could not pt (5) (5) ended to 3,220'. Spot 25sx cmt. Calc TOC @ 1,412', Tag @ 1,417'. 7/14/09 Perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out of (7) (6) ended to 1,659', spot 25sx cmt. Calc TOC @ 1,412', Tag @ 1,417'. 7/14/09 Perf @ 347'. NU WH. Pump 115sx cmt @ 347' to surface out of (7) I hereby certify that the information above is true and complete to the best of my knograde tank has been/will be constructed or closed according to MtOCD guidelines 🖾, a general pe SIGNATURE Muthered or closed according to MtOCD guidelines 🖾, a general pe SIGNATURE	E DRILLING OPNS. P AND A EMENT JOB