and the second	
Submit 3 Copies To Appropriate District State of New Mexico Office District I RECEIVED Minerals and Natural Resources	Form C-103
1625 N. Eronah Dr. Habba NM 97240	May 27, 2004
District II DOT 16 2000 CONSERVATION DIVISION	<u>30-025-27196</u>
1301 W. Grand Ave, Artesia, NM 88201 TO Earle Conversion of the formation	5. Indicate Type of Lease STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	7. Lease Name or Unit Agreement Name: SHIPLEY "A" WN
1. Type of Well: Oil Well Gas Well X Other	8. Well Number
2. Name of Operator	9. OGRID Number
BP America Production Company	00778 🗸
3. Address of Operator P.O. Box 1089 Eunice, NM 88231	10. Pool name or Wildcat JALMAT TANSIL YATES 7R GAS
4. Well Location	
Unit LetterE : 1650 feet from theN line and660 feet from theW line	
Section 27 Township 22S Range 36E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, et	
3499.1' GR	
Pit or Below-grade Tank Application or Closure Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON I REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB	ING OPNS. D PLUG AND ABANDONMENT
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give	e pertinent dates including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
 MIRU PU. Check tubing, casing and surface pipe for pressure - bleed off into containment. Monitor well and assure it's stable. Kill well as necessary. ND WH & install BOP. TOH with 2 3/8" production tubing. TIH with 4 3/4" bit and 5 1/2" casing scraper on tubing to 3200'. TOH. TIH with CIBP on 2 3/8" tubing and set at 3170'. Load hole with fresh water. Test casing to 500 psi. Spot 300' cement plug from 3170' to 2870' using 30 sx Class C (producing zone plug, Base of Salt = 3000'). PU to 2750'. Circulate hole with mud-laden fluid (9.0 ppg, 1250# gel/100 bbl). Continued on page 2. 	
I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or plased according to NMOCD guidelines, a general permit	e and belief. I further certify that any pit or below-
	ons Team Lead DATE 10/14/09
Type or print name Barry C. Price E-mail address: barry.price@bp.com Telephone No. 575-394-1648	
For State Use Only Mark of Whitelen TITLE Courd ince Officer DATE 10/19/2009	
APPROVED BY 1 Carl With The TITLE Whip I loude UTLEN DATE 10/19/2009 Conditions of Approval, if any:	
The Oil Conservation Division Must be notified 24 hours prior to the beginning of plugging operations	

Form C-103 Shipley A WN #6 30-025-27196 Continued from Page 1

•

- 5. TOH LD tubing to 1600'. Spot 500' cement plug from 1600' to 1100' using 50 sx Class C neat (Top of Salt = 1430', surface casing shoe = 1190'). LD tubing.
- 6. RU wireline. Tag surface casing shoe plug top must be at 1140' or shallower. Perforate 5 ½" casing at 400'. Establish circulation down 5 ½" and out 5 ½" x 8 5/8" annulus. RD WL.
- ND BOP. Install adapter flange. Fill 5 ½" casing from surface to 400' and 5 ½" x 8 5/8" annulus from 400' to surface with 100 sx Class C neat (estimated – pump until good cement returns).
- 8. RD PU and clean location.
- 9. Dig out WH and cut-off casingheads to 3' below GL.
- 10. Install regulation dry-hole marker. Clean location and prepare location for NMOCD inspections.



.

· - -

- ---- -

- -- ----

