Office	State of New Mexico	Form C-103
District J • 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Ave., Artesia, NM 87410 District III 1000 Rio Brazos Rd , Aztec, NM 87410 1000 Rio Brazos Rd , Aztec, NM		June 19, 2008
		30-025-33236 5. Indicate Type of Lease
		STATE FEE 6. State Oil & Gas Lease No.
District IV NUVU3 2009 Santa Pe, NUV 87505 1220 S St Francis Dr., Santa Fe, NM 87505 HOBBSOCD		0. State on & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		THEODORE ANDERSON
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other		8. Well Number 10
2. Name of Operator / CHEVRON U.S.A. INC.		9. OGRID 4323
3. Address of Operator 15 SMITH ROAD, MIDLAND, TEXAS 79705		10. Pool name or Wildcat Monoment WEIR; BLINEBRY
4. Well Location		
Unit Letter P: 990 feet from the SOUTH line and 515 feet from the EAST line Section 8 Township 20-S Range 37-E NMPM County LEA		
Section 8 Township 20-S Range 37-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: INTENT TO TEMPORARILY ABANDON OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
CHEVRON U.S.A. INC. INTENDS TO TEMPORARILY ABANDON THE SUBJECT WELL. THIS WELL WILL BE PLUGGED & ABANDONED WHEN RIG IS AVAILABLE.		
THE INTENDED PROCEDURE AND WELLBORE DIAGRAMS ARE ATTACHED FOR YOUR APPROVAL.		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and	d complete to the best of my knowledg	e and belief.
Auto)	
SIGNATURE VENUSEDTIC YE TO C	TITLE REGULATORY SPECIA	ALIST DÀTE 11-02-2009
Type or print nameDENISE PINKERTONFor State Use OnlyImage: Control of the state of	E-mail address: leakejd@chevron	.com PHONE: 432-687-7375
APPROVED BY: Camp W. A if TITLE DISTRICT 1 SUPERVISOR DATE DATE DATE		
· · · · · · · · · · · · · · · · · · ·	Condition of Approval: Notify office 24 hours prior to runni	
	< .	

Theodore Anderson #10 30-025-33236 Weir, Blinebry T 208 R 37E, Sec. 8 990' FSL & 515' FEL Charge To: UCL270900

Job: <u>TA Blinebry</u>

Procedure:

- 1. This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 9/4/2009. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.
- 2. Displace flowline with fresh water. Have field specialist close valve at header. Pressure line according to the type of line. Buried fiberglass lines will be tested with 300 psi. All polypipe (SDR7 and SDR11) will be tested w/100 psi. All steel lines will be tested w/500 psi. If a leak is found, contact Donnie Ives for repair/replacement. If test is good, bleed off pressure and open valve at header. Document this process in the morning report.
- 3. MI & RU pulling unit. Bleed pressure from well, if any. Pump down casing with 8.6 PPG cut brine water, if necessary to kill well. POH LD rods and pump. Remove WH. Install BOP's and test as required. POH with production tubing string.
- MI & RU Baker Atlas WL electric line unit. Install lubricator and test to 1000 psi. GIH with gauge ring and junk basket (for 5- 1/2" 15.5# csg) to 5500'. POH. GIH and set CIBP in 5-1/2" csg at 5490'. POH. GIH and dump 35' cement on top of CIBP. POH. RD & release electric line unit. Note: Use Schlumberger litho-density log dated 2/9/1996 for correlation.
- 5. GIH with 2-7/8" tbg string to 5455'. Reverse circulate well clean from 5455' using fresh water. Pressure test csg and CIBP to 500 psi. POH LD 2-7/8" tbg string.
- 6. Remove BOP's and install flanged-type WH. Install tapped bullplug, ¹/₂" ball valve and pressure gauge in top of 5- 1/2" csg string.
- Notify NMOCD of MIT Test. Pressure test 5-1/2" csg to 500 psi and record chart for NMOCD. Change status of well in Catalyst to "AD". Send report and charts to Denise Pinkerton for filing with the NMOCD.

Adam English 9/4/2009

Syate Diz

WELL DATA SHEET



Modified by: akxl Date: 9/4/2009



WELL DATA SHEET

د ا