State of New Mexico Energy, Minerals and Natural Resources Department


Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE RECEIVED CONSERVATION DIVISION	
DICTRICT I	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 FEB 2 2 2010 Santa Fe, NM 87505	30-025-29074
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 8821 HOBBSUCD	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS	/
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	North Hobbs (G/SA) Unit Section 32
1. Type of Well:	8. Well No. 422
Oil Well Gas Well Other Injector	/
2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	/
3. Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR I Box 90 Denver City, TX 79323 4. Well Location	
	A. P. A. B. A.
Unit Letter H : 1385 Feet From The North 110 Fee	t From The East Line
Section 32 Township 18-S Range 38-E	NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.)	
3644' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
Pit Liner Thickness niii	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C	Other Data
01/04	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF: ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	ALTERING CASING NS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat X
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed or proposed or complete the second states.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat x including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'.	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat , including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120	ALTERING CASING NS. PLUG & ABANDONMENT IT JOB forate/acid treat , including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES.	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. D sacks of prem plus w/2.0% Cal Chloride and 10#
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars.	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. D sacks of prem plus w/2.0% Cal Chloride and 10#
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. D sacks of prem plus w/2.0% Cal Chloride and 10#
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet***	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. D sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars.	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. D sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet***	ALTERING CASING PLUG & ABANDONMENT To JOB forate/acid treat including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel.
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPPULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENOTHER: OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet***	ALTERING CASING PLUG & ABANDONMENT To JOB forate/acid treat including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet*** Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT T JOB forate/acid treat , including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel. that any pit or below-grade tank has been/will be e OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet*** Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative	ALTERING CASING PLUG & ABANDONMENT To JOB forate/acid treat including estimated date of starting any completion or recompletion. Disacks of premiplus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 02/18/2010
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Adminson E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT To Job forate/acid treat including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 02/18/2010 TELEPHONE NO 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Adminism E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT To Job forate/acid treat , including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 02/18/2010 TELEPHONE NO 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: OTHER: Squeeze/per: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of RUPU & RU. Kill well. 2. ND wellhead/NU BOP. 3. POOH w/packer and tubing. 4. RIH w/bit. Tag @4266'. POOH w/bit. 5. Run TD check. Tagged @4225'. Dump bail gravel & sand from 4225-4215'. 6. RIH w/CICR set @4017'. 7. RU HES and squeeze perfs from 4051-4205 w/ 200 sacks of 50/50 POZ with .2% Super CBL, 120 of Microbond cement. Reverse out 23 bbl of cement. RD HES. 8. RIH w/bit & drill collars. NU stripper head and power swivel. Drill on cement & CICR from 401 POOH w/bit & drill collars. ***see additional data on attached sheet*** I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Adminson E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT To Job forate/acid treat including estimated date of starting any completion or recompletion. Sacks of prem plus w/2.0% Cal Chloride and 10# 5-4208'. ND stripperhead and power swivel. that any pit or below-grade tank has been/will be e OCD-approved Associate DATE 02/18/2010 TELEPHONE NO 806-592-6280

NHU 32-422

- 9. RU wireline and perforate hole at 4050-60, 4063-65, 4115, 4122, 4135-60, 4169-76, 4183-93 at 2 JSPF. RD wireline
- 10. RH w/ PPI packer set @3940'. RU HES & acid treat new perfs w/straddle packer on 34' spacing w/135 gal of 15% PAD acid in 4 stages. Broke down perfs from 416-93, 4135-60, 4115-22 & 4050-65'. RD HES.
- 11. POOH w/PPI pakcers.
- 12. RIH w/Arrowset 1X injection packer set on 126 jts of2-7/8" Duoline 20 tubing. Packer set @4024'
- 13. ND BOP/NU wellhead.
- 14. Test casing to 600 PSI for 30 minutes and chart for the NMOCD.
- 15. RDPU & RU. Clean location and return well to injection,

RUPU 12/05/2009 RDPU 12/16/2009



B. Steplean

Jim /// 2