## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVAT	TION DIVISION
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 CEIVED 1220 South St. Santa Fe, NI	20.025.07527
DISTRICT II	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 FEB 1 9 2010	STATE FEE X
DISTRICT III	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 8741 0 OBBSOCD	
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101)	for such proposals.) Section 32
Type of Well: Onl Well Gas Well Other Inject	
2 Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4. Well Location  Unit Letter L: 2310 Feet From The South	330 Feet From The West Line
Section 32 Township 18-S	Range 38-E NMPM Lea County
11. Elevation (Show whether DF, RKB, 13634' GL	
Pit or Below-grade Tank Application or Closure	Valuation
Pit Type Depth of Ground Water Distance from near	est fresh water well Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume	bbls; Construction Material
12. Check Appropriate Box to Indicate Nature	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
1101102 01 111121111011	
	EMEDIAL WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON R	F
PERFORM REMEDIAL WORK PLUG AND ABANDON R TEMPORARILY ABANDON CHANGE PLANS C	EMEDIAL WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COPULL OR ALTER CASING Multiple Completion CO	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK CHANGE PLANS COPULL OR ALTER CASING Multiple Completion CO	EMEDIAL WORK ALTERING CASING OMMENCE DRILLING OPNS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well a proposed work) SEE RULE 1103. For Multiple Completions: Attach well 1. RUPU & RU. Kill well.	EMEDIAL WORK  ALTERING CASING  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well proposed work) SEE RULE 1103. For Multiple Completions: Attach well RUPU & RU. Kill well.  2. NU BOP/ND wellhead.	EMEDIAL WORK  ALTERING CASING  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COUNTER: COUNT	EMEDIAL WORK  ALTERING CASING  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach wellto 1. Describe Proposed or Completed Operations (Clearly state all pertinent detain proposed work) SEE RULE 1103. For Multiple Completions: Attach wellto 1. RUPU & RU. Kill well. 2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'.	EMEDIAL WORK  ALTERING CASING  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach wellto 1. Describe Proposed or Completed Operations (Clearly state all pertinent detain proposed work) SEE RULE 1103. For Multiple Completions: Attach wellto 1. RUPU & RU. Kill well. 2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.	EMEDIAL WORK  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach wellto 1. Describe Proposed or Completed Operations (Clearly state all pertinent detain proposed work) SEE RULE 1103. For Multiple Completions: Attach wellto 1. RUPU & RU. Kill well. 2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel. 7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 22.	EMEDIAL WORK  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach wellto 1. Describe Proposed or Completed Operations (Clearly state all pertinent detain proposed work) SEE RULE 1103. For Multiple Completions: Attach wellto 1. RUPU & RU. Kill well. 2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead.  3. POOH w/tubing and injection packer.  4. Dump gravel from 4235-4158'. Tag @4158'  5. RIH w/tubing. Tag @4154'.  6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.  7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of the Reverse rest of cement out.  8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Co. 9. Clean out pea gravel from 4168-4242'.	EMEDIAL WORK  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead.  3. POOH w/tubing and injection packer.  4. Dump gravel from 4235-4158'. Tag @4158'  5. RIH w/tubing. Tag @4154'.  6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.  7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of Reverse rest of cement out.  8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Co	EMEDIAL WORK  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach wellto 1. Describe Proposed or Completed Operations (Clearly state all pertinent detail proposed work) SEE RULE 1103. For Multiple Completions: Attach wellto 1. RUPU & RU. Kill well. 2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel. 7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 22 Reverse rest of cement out. 8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Co 9. Clean out pea gravel from 4168-4242'.  ***see additional data on attach	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  Ited sheet***
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel. 7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 2000 Reverse rest of cement out. 8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Coep. Clean out pea gravel from 4168-4242'.  ***see additional data on attach I hereby certify that the information above is true and complete to the best of my knowledge constructed or	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  Ited sheet***  The early belief I further certify that any pit or below-grade tank has been/will be
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COPULL OR ALTER CASING Multiple Completion COPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel. 7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 2000 Reverse rest of cement out. 8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Coep. Clean out pea gravel from 4168-4242'.  ***see additional data on attach I hereby certify that the information above is true and complete to the best of my knowledge constructed or closed according to NMOCD guidelines , a general permit	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  Ited sheet***
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPULL OR ALTER CASING Multiple Completion COMPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead. 3. POOH w/tubing and injection packer. 4. Dump gravel from 4235-4158'. Tag @4158' 5. RIH w/tubing. Tag @4154'. 6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel. 7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of a Reverse rest of cement out. 8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Co. 9. Clean out pea gravel from 4168-4242'.  ***see additional data on attach.  I hereby certify that the information above is true and complete to the best of my knowledge constructed or closed according to NMOCD guidelines a general permit.  SIGNATURE	EMEDIAL WORK ALTERING CASING  OMMENCE DRILLING OPNS. PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  Ited sheet***  The and belief I further certify that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved plan  FITLE Administrative Associate  DATE 02/17/2010
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPULL OR ALTER CASING Multiple Completion COMPULL OR ALTER CASING Multiple Completions: Attach well of the proposed work) SEE RULE 1103. For Multiple Completions: Attach well of the RUPU & RU. Kill well.  2. NU BOP/ND wellhead.  3. POOH w/tubing and injection packer.  4. Dump gravel from 4235-4158'. Tag @4158'  5. RIH w/tubing. Tag @4154'.  6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.  7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 2 Reverse rest of cement out.  8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Co.  9. Clean out pea gravel from 4168-4242'.  ****see additional data on attach.  I hereby certify that the information above is true and complete to the best of my knowledge constructed or closed according to NMOCD guidelines accordin	EMEDIAL WORK  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER:  Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  It is and belief I further certify that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPULL OR ALTER CASING Multiple Completion COMPULL OR ALTER CASING Multiple Completions: Attach wellto 1. RUPU & RU. Kill well.  2. NU BOP/ND wellhead.  3. POOH w/tubing and injection packer.  4. Dump gravel from 4235-4158'. Tag @4158'  5. RIH w/tubing. Tag @4154'.  6. NU tubing swivel. Clean out from 4154-4164'. ND tubing swivel.  7. RIH w/cement retainer set @4066'. Spot 6 bbl of acid. Pump 32 bbl of 2000 Reverse rest of cement out.  8. RIH w/drill collars. Drill on CICR and cement to 4076'. Circ clean. Complete to 9. Clean out pea gravel from 4168-4242'.  ***see additional data on attach I hereby certify that the information above is true and complete to the best of my knowledge constructed or closed according to NMOCD guidelines according to NMOCD	ALTERING CASING  OMMENCE DRILLING OPNS.  PLUG & ABANDONMENT  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertinent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  It is and belief I further certify that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved plan  FITLE Administrative Associate  DATE 02/17/2010  Menendy johnson@oxy.com  TELEPHONE NO. 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON REMPORARILY ABANDON CHANGE PLANS COMPULL OR ALTER CASING Multiple Completion COTHER: CO	ALTERING CASING OMMENCE DRILLING OPNS.  ASING TEST AND CEMENT JOB  THER: Plug back/Perforate/Acid Treat  Is, and give pertunent dates, including estimated date of starting any bore diagram of proposed completion or recompletion.  2% Cal Chloride and Microbo prem plus cement. 8 bbl under retainer.  Intinue to drill on cement from 4076-4168'. Circ clean.  It is an early that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved plan  TITLE Administrative Associate  DATE 02/17/2010  TELEPHONE NO. 806-592-6280

## NHU 32-131

- 10. POOH w/drill collars.
- 11. RU wireline and perforate hole @4140-4145'. RD wireline.
- 12. RU HES and perform SPA acid job in 4 settings w/14 bbl of 15% HCL acid. POOH w/straddle packer.
- 13. RIH w/Arrowset 1X Double grip packer set on 118 jts of 2-7/8" Duoline tubing. Packer set @4101'.
- 14. ND BOP/NU wellhead.
- 15. Test casing to 570 PSI for 30 minutes and chart for the NMOCD.
- 16. RDPU & RU. Clean location and return well to injection.

RUPU 11/21/09 RDPU 12/05/09

