## State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICT I

## OIL CONSERVATION DIVISION

| Santa Fe, New Mexico 87503  | 30-025-27140  5. Indicate Type of Lease  |
|---|--|
|   | FED STATE FEE X  |
|   | 6. State Oil & Gas Lease No.   |
| SUNDRY NOTICES AND REPORTS ON WELLS   |  |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A   | 7. Lease Name or Unit Agreement Name   |
| DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101 FOR SUCH PROPOSALS.)   | NORTH HOBBS (G/SA) UNIT  |
| 1. Type of Well: Oil Well Gas Well Other INJECTOR   | SECTION 32   |
| 2. Name of Operator OCCIDENTAL PERMIAM, LTD.  | 8. Well No. 222  |
| 3. Address of Operator 1017 W STANOLIND RD.   | 9. Pool name or Wildcat  |
| 3. Addiess of Operator  | HOBBS (G/SA)   |
| 4. Well Location  |  |
| Unit Letter F : 1720 Feet From The NORTH Line and 1370 Fe   | et From The WEST Line  |
| Section 32 Township 18-S Range 38-  | E NMPM LEA County  |
| 10. Elevation (Show whether DF, RKB, RT GR, etc.)<br>3634' GL   |  |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report,   | or Other Data  |
|   | SSEQUENT REPORT OF:  |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  | X ALTERING CASING  |
| TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O  | PNS. PLUG & ABANDONMENT  |
| PULL OR ALTER CASING CASING TEST AND CEME   | ENT JOB  |
|   |  |
| OTHER: OTHER:   |  |
| OTHER:  OTHER:  OTHER:  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  | cluding estimated date of starting any proposed  |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc   | cluding estimated date of starting any proposed  |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  | cluding estimated date of starting any proposed  |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.   |  |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing   | 3.   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.  Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid.  RIH w/4.5" Guiberson G-6 pc pkr. XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg  | 3.<br>252627 1929303   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and characteristics.   | 3.   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.  Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid.  RIH w/4.5" Guiberson G-6 pc pkr. XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg  | 3.   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and characteristics.   | 3. 25 27 19 29 30 33   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and cha RDPU. Clean Location.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004   | 3.   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incowork) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and characteristics.  Well returned to injection 01/21/2004.   | 3. 25 27 19 29 30 33   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incowork) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and cha RDPU. Clean Location.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004 RIG DOWN DATE: 01/20/2004   | ert for the NMOCD.   |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomork) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.  Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid.  RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and characteristic contents.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004  RIG DOWN DATE: 01/20/2004  Thereby certify that the information above is true and complete to the best of my knowledge and belief.   | art for the NMOCD.  AND STATE OF STATE  |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.  Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid.  RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and cha RDPU. Clean Location.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004  RIG DOWN DATE: 01/20/2004  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE TITLE SR. ENGRETA                                    | art for the NMOCD.  TO THE NMOCD.  TO THE STATE OF THE ST |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.  RUPU. POH with injection equipment. Sqz all perfs below 4050' w 250 sx cmt. Drill out and re-perforate Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun. Perforate the following intervals 4200-02, 4208-14, and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 15% NEFE HCL acid. RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and cha RDPU. Clean Location.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004 RIG DOWN DATE: 01/13/2004 RIG DOWN DATE: 01/20/2004  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE                                  | ert for the NMOCD.  To the NMOCD.  T |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.  RUPU. POH with injection equipment.  Sqz all perfs below 4050' w 250 sx cmt.  Drill out and re-perforate  Perforate the following intervals 4156-60, 4164-68, 4180-90, using 2-1/8" EJ Strip gun.  Perforate the following intervals 4200-02, 4208-14,and 4228-32 using 2 JSPF and 45 degree phasing Stimulate perfs w/2400 g 1536 NEFE HCL acid.  RIH w/4.5" Guiberson G-6 pc pkr, XL on/off tool w/1.875 ss "F" nipple, 129 jts 2-7/8" Duoline tbg Pkr set @4048'. Bottom of tbg @4048'. Circ csg w/pkr fluid. Test csg to 700 psi for 30 min and cha RDPU. Clean Location.  Well returned to injection 01/21/2004.  RIG UP DATE: 01/13/2004  RIG DOWN DATE: 01/20/2004  Thereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE TITLE SR. ENGRIPH  TYPE OR PRINT NAME Robert Gilbert | ert for the NMOCD.  To the NMOCD.  T |

